sumner regional medical center

Based on VSDA2

Provider Number	Nursing Home Name	City
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA

sumner regional medical center

Based on VSDA2

State	Survey Date	Date of Correction	Deficiency Type
KS	06/04/2008	07/03/2008	Fire Safety
KS	06/04/2008	06/13/2008	Fire Safety
KS	06/04/2008	07/03/2008	Fire Safety
KS	06/04/2008	06/13/2008	Fire Safety
KS	06/04/2008	06/13/2008	Fire Safety
KS	06/04/2008	07/03/2008	Fire Safety
KS	06/04/2008	07/03/2008	Fire Safety
KS	06/04/2008	06/13/2008	Fire Safety
KS	06/04/2008	07/03/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Deficiency Category	Deficiency	Scope
Building Construction Deficiencies	approved construction type or materials.	Widespread
Interior Finish Deficiencies	fire-resistant interior walls.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in	Isolated

sumner regional medical center

Based on VSDA2

Level of Harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA

sumner regional medical center

Based on VSDA2

KS	06/04/2008	06/13/2008	Fire Safety
KS	06/04/2008	06/13/2008	Fire Safety
KS	06/04/2008	06/13/2008	Fire Safety
KS	06/04/2008	07/03/2008	Fire Safety
KS	06/04/2008	06/13/2008	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Widespread
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA
175008	MEDICALODGES WICHITA	WICHITA

sumner regional medical center

Based on VSDA2

KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety

	would resist fire for at least one hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175008	MEDICALODGES WICHITA	WICHITA
175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	09/13/2010	09/16/2010	Fire Safety
KS	10/10/2008	10/14/2008	Fire Safety
KS	10/10/2008	10/14/2008	Fire Safety
KS	10/10/2008	10/14/2008	Fire Safety
KS	10/10/2008	10/10/2008	Fire Safety
KS	12/03/2009	12/03/2009	Fire Safety
KS	12/03/2009	12/03/2009	Fire Safety
KS	12/03/2009	12/03/2009	Fire Safety
KS	12/03/2009	12/08/2009	Fire Safety

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA
175044	BREWSTER HEALTH CENTER	TOPEKA
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG

sumner regional medical center

Based on VSDA2

KS	12/03/2009	12/03/2009	Fire Safety
KS	12/03/2009	12/03/2009	Fire Safety
KS	12/03/2009	12/03/2009	Fire Safety
KS	04/24/2008	04/24/2008	Fire Safety
KS	04/24/2008	05/13/2008	Fire Safety
KS	04/24/2008	04/30/2008	Fire Safety
KS	04/24/2008	05/23/2008	Fire Safety
KS	04/24/2008	04/25/2008	Fire Safety
KS	04/24/2008	04/24/2008	Fire Safety

	minutes.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Interior Finish Deficiencies	fire-resistant interior walls.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG
175070	MEDICALODGES PITTSBURG	PITTSBURG

sumner regional medical center

Based on VSDA2

KS	04/24/2008	04/24/2008	Fire Safety
KS	04/24/2008	05/13/2008	Fire Safety
KS	04/24/2008	05/13/2008	Fire Safety
KS	05/13/2009	06/11/2009	Fire Safety
KS	06/10/2010	06/22/2010	Fire Safety
KS	06/10/2010	06/11/2010	Fire Safety
KS	06/10/2010	06/10/2010	Fire Safety
KS	06/10/2010	06/22/2010	Fire Safety
KS	06/10/2010	06/10/2010	Fire Safety

	that have been properly installed according to the manufacturer's instructions.	
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Isolated
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175070	MEDICALODGES PITTSBURG	PITTSBURG
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE

sumner regional medical center

Based on VSDA2

KS	06/10/2010	06/22/2010	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety

	according to the manufacturer's instructions.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be	Widespread

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE

sumner regional medical center

Based on VSDA2

KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	09/17/2008	09/19/2008	Fire Safety
KS	09/17/2008	10/17/2008	Fire Safety
KS	09/17/2008	10/17/2008	Fire Safety
KS	09/17/2008	10/17/2008	Fire Safety
KS	09/17/2008	10/17/2008	Fire Safety
KS	09/17/2008	10/17/2008	Fire Safety
KS	09/17/2008	10/17/2008	Fire Safety
KS	09/17/2008	10/08/2008	Fire Safety

	heard throughout the facility.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175077	LIFE CARE CENTER OF OSAWATOMIE	OSAWATOMIE
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	09/17/2008	10/08/2008	Fire Safety
KS	10/15/2009	11/13/2009	Fire Safety
KS	10/15/2009	11/13/2009	Fire Safety
KS	10/15/2009	11/13/2009	Fire Safety
KS	08/28/2007	09/27/2007	Fire Safety
KS	08/28/2007	09/27/2007	Fire Safety
KS	08/28/2007	09/27/2007	Fire Safety
KS	08/28/2007	10/30/2007	Fire Safety
KS	08/28/2007	09/27/2007	Fire Safety
KS	08/28/2007	09/27/2007	Fire Safety
KS	09/09/2008	10/08/2008	Fire Safety
KS	09/09/2008	10/08/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	09/09/2008	09/11/2008	Fire Safety
KS	09/09/2008	10/08/2008	Fire Safety
KS	09/09/2008	09/09/2008	Fire Safety
KS	09/09/2008	10/08/2008	Fire Safety
KS	09/09/2008	10/08/2008	Fire Safety
KS	09/09/2008	09/10/2008	Fire Safety
KS	09/09/2008	10/08/2008	Fire Safety
KS	09/09/2008	10/08/2008	Fire Safety
KS	09/09/2008	10/08/2008	Fire Safety

	for one hour or an approved fire extinguishing system.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Widespread
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175078	COLLEGE HILL NURSING & REHAB CENTER	WICHITA
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN

sumner regional medical center

Based on VSDA2

KS	09/09/2008	10/08/2008	Fire Safety
KS	10/06/2009	10/07/2009	Fire Safety
KS	10/06/2009	10/28/2009	Fire Safety
KS	10/06/2009	10/16/2009	Fire Safety
KS	10/06/2009	10/28/2009	Fire Safety
KS	10/06/2009	10/09/2009	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN

sumner regional medical center

Based on VSDA2

KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	11/06/2008	11/06/2008	Fire Safety
KS	11/06/2008	11/07/2008	Fire Safety
KS	11/06/2008	11/06/2008	Fire Safety
KS	11/06/2008	11/07/2008	Fire Safety
KS	11/06/2008	11/07/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN

sumner regional medical center

Based on VSDA2

KS	11/06/2008	11/20/2008	Fire Safety
KS	11/06/2008	11/07/2008	Fire Safety
KS	11/06/2008	11/06/2008	Fire Safety
KS	11/06/2008	12/02/2008	Fire Safety
KS	11/06/2008	11/13/2008	Fire Safety
KS	11/06/2008	11/06/2008	Fire Safety
KS	11/06/2008	12/04/2008	Fire Safety
KS	11/06/2008	12/01/2008	Fire Safety
KS	11/06/2008	11/07/2008	Fire Safety
KS	11/06/2008	12/02/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175100	VIA CHRISTI VILLAGE MANHATTAN INC	MANHATTAN
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	11/06/2008	11/10/2008	Fire Safety
KS	11/24/2009	11/24/2009	Fire Safety
KS	11/24/2009	12/24/2009	Fire Safety
KS	11/24/2009	12/09/2009	Fire Safety
KS	11/24/2009	12/04/2009	Fire Safety
KS	11/24/2009	12/24/2009	Fire Safety
KS	06/02/2008	06/12/2008	Fire Safety
KS	06/02/2008	06/12/2008	Fire Safety
KS	06/02/2008	06/12/2008	Fire Safety
KS	06/02/2008	06/27/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	06/02/2008	06/13/2008	Fire Safety
KS	06/02/2008	06/12/2008	Fire Safety
KS	06/02/2008	06/13/2008	Fire Safety
KS	06/02/2008	06/13/2008	Fire Safety
KS	06/02/2008	06/12/2008	Fire Safety
KS	06/02/2008	06/12/2008	Fire Safety
KS	07/28/2009	08/10/2009	Fire Safety
KS	07/28/2009	08/27/2009	Fire Safety
KS	07/28/2009	08/03/2009	Fire Safety

	at least 1 1/2 hours.	
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA

KS	07/28/2009	08/27/2009	Fire Safety
KS	07/28/2009	08/04/2009	Fire Safety
KS	07/28/2009	08/06/2009	Fire Safety
KS	07/28/2009	08/03/2009	Fire Safety
KS	07/28/2009	08/27/2009	Fire Safety
KS	07/28/2009	08/27/2009	Fire Safety
KS	07/28/2009	08/04/2009	Fire Safety
KS	07/28/2009	08/06/2009	Fire Safety
KS	07/28/2009	08/04/2009	Fire Safety

	alarm or smoke detectors.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	an externally vented heating system.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	07/28/2009	08/06/2009	Fire Safety
KS	07/28/2009	08/05/2009	Fire Safety
KS	07/28/2009	07/28/2009	Fire Safety
KS	07/28/2009	08/27/2009	Fire Safety
KS	12/03/2010	12/31/2010	Fire Safety
KS	12/03/2010	12/31/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/31/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety

	system.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175113	EVENTIDE CONVALESCENT CENTER	TOPEKA
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON

sumner regional medical center

Based on VSDA2

KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	12/03/2010	12/10/2010	Fire Safety
KS	10/31/2007	10/31/2007	Fire Safety

	each shift under varying conditions.	
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON

KS	10/31/2007	10/31/2007	Fire Safety
KS	10/31/2007	11/08/2007	Fire Safety
KS	10/31/2007	10/31/2007	Fire Safety
KS	10/31/2007	11/01/2007	Fire Safety
KS	10/31/2007	11/29/2007	Fire Safety
KS	10/31/2007	11/29/2007	Fire Safety
KS	10/31/2007	10/31/2007	Fire Safety
KS	01/21/2009	01/21/2009	Fire Safety
KS	01/21/2009	01/21/2009	Fire Safety

	resist smoke for at least 20 minutes.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175114	GOLDEN PLAINS HEALTH CARE CENTER	HUTCHINSON
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE

sumner regional medical center
Based on VSDA2

KS	01/21/2009	01/26/2009	Fire Safety
KS	01/21/2009	01/26/2009	Fire Safety
KS	01/21/2009	01/21/2009	Fire Safety
KS	10/30/2007	11/29/2007	Fire Safety
KS	10/30/2007	10/31/2007	Fire Safety
KS	10/30/2007	11/29/2007	Fire Safety
KS	10/30/2007	11/29/2007	Fire Safety
KS	10/30/2007	11/29/2007	Fire Safety
KS	10/30/2007	10/31/2007	Fire Safety
KS	10/30/2007	11/10/2007	Fire Safety

	ashtrays where smoking was allowed.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit"	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE

sumner regional medical center

Based on VSDA2

KS	10/30/2007	11/30/2007	Fire Safety
KS	10/30/2007	10/31/2007	Fire Safety
KS	10/30/2007	11/15/2007	Fire Safety
KS	10/30/2007	10/31/2007	Fire Safety
KS	10/30/2007	10/31/2007	Fire Safety
KS	10/30/2007	11/01/2007	Fire Safety
KS	10/30/2007	11/29/2007	Fire Safety
KS	10/30/2007	11/09/2007	Fire Safety

	signs.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE

sumner regional medical center

Based on VSDA2

KS	10/30/2007	11/30/2007	Fire Safety
KS	10/30/2007	11/30/2007	Fire Safety
KS	01/13/2009	01/13/2009	Fire Safety
KS	01/13/2009	02/12/2009	Fire Safety
KS	01/13/2009	02/12/2009	Fire Safety
KS	01/13/2009	01/13/2009	Fire Safety
KS	01/13/2009	01/31/2009	Fire Safety
KS	01/13/2009	02/12/2009	Fire Safety
KS	01/13/2009	01/13/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Isolated
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE
175115	VILLA ST FRANCIS	OLATHE

sumner regional medical center

Based on VSDA2

KS	01/13/2009	01/13/2009	Fire Safety
KS	01/13/2009	02/12/2009	Fire Safety
KS	01/13/2009	01/31/2009	Fire Safety
KS	01/13/2009	01/13/2009	Fire Safety
KS	01/13/2009	01/31/2009	Fire Safety
KS	01/13/2009	01/13/2009	Fire Safety
KS	03/12/2010	03/12/2010	Fire Safety
KS	03/12/2010	03/12/2010	Fire Safety
KS	03/12/2010	04/09/2010	Fire Safety
KS	03/12/2010	03/15/2010	Fire Safety

Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper fire barriers, ventilation and signs for the transport of oxygen.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175115	VILLA ST FRANCIS	OLATHE
175116	SUMNER REGIONAL MEDICAL CENTER SNF	WELLINGTON
175116	SUMNER REGIONAL MEDICAL CENTER SNF	WELLINGTON
175116	SUMNER REGIONAL MEDICAL CENTER SNF	WELLINGTON
175116	SUMNER REGIONAL MEDICAL CENTER SNF	WELLINGTON
175116	SUMNER REGIONAL MEDICAL CENTER SNF	WELLINGTON
175116	SUMNER REGIONAL MEDICAL CENTER SNF	WELLINGTON
175116	SUMNER REGIONAL MEDICAL CENTER SNF	WELLINGTON
175116	SUMNER REGIONAL MEDICAL CENTER SNF	WELLINGTON
175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA

sumner regional medical center

Based on VSDA2

KS	03/12/2010	04/09/2010	Fire Safety
KS	04/02/2008	04/30/2008	Fire Safety
KS	04/02/2008	04/02/2008	Fire Safety
KS	04/02/2008	04/30/2008	Fire Safety
KS	04/02/2008	04/30/2008	Fire Safety
KS	04/02/2008	04/30/2008	Fire Safety
KS	04/02/2008	04/30/2008	Fire Safety
KS	04/02/2008	04/30/2008	Fire Safety
KS	07/02/2009	07/08/2009	Fire Safety
KS	03/25/2008	04/22/2008	Fire Safety
KS	03/25/2008	04/22/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Vertical Openings Deficiencies	proper stairway enclosures and	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA

sumner regional medical center

Based on VSDA2

KS	03/25/2008	04/22/2008	Fire Safety
KS	03/25/2008	04/01/2008	Fire Safety
KS	03/25/2008	04/25/2008	Fire Safety
KS	03/25/2008	04/25/2008	Fire Safety
KS	03/25/2008	03/31/2008	Fire Safety
KS	06/10/2009	06/19/2009	Fire Safety
KS	06/10/2009	06/19/2009	Fire Safety
KS	06/10/2009	06/19/2009	Fire Safety
KS	06/10/2009	06/19/2009	Fire Safety

	vertical shafts.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175118	KANSAS MASONIC HOME	WICHITA
175118	KANSAS MASONIC HOME	WICHITA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA

sumner regional medical center

Based on VSDA2

KS	06/10/2009	06/19/2009	Fire Safety
KS	09/08/2010	09/15/2010	Fire Safety
KS	11/21/2007	12/11/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	12/14/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	12/06/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	12/14/2007	Fire Safety

	each shift under varying conditions.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA

sumner regional medical center

Based on VSDA2

KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	11/21/2007	Fire Safety
KS	11/21/2007	12/14/2007	Fire Safety
KS	11/21/2007	12/06/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	12/06/2007	Fire Safety
KS	11/21/2007	12/06/2007	Fire Safety
KS	11/21/2007	12/06/2007	Fire Safety
KS	02/05/2009	02/12/2009	Fire Safety
KS	02/05/2009	03/01/2009	Fire Safety

	maintenance and testing program for fire alarm systems.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly constructed linen or trash chutes.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Isolated
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA
175122	DELMAR GARDENS OF LENEXA	LENEXA

sumner regional medical center

Based on VSDA2

KS	02/05/2009	03/01/2009	Fire Safety
KS	02/05/2009	03/01/2009	Fire Safety
KS	02/05/2009	02/28/2009	Fire Safety
KS	02/05/2009	03/01/2009	Fire Safety
KS	02/05/2009	03/01/2009	Fire Safety
KS	02/05/2009	03/01/2009	Fire Safety
KS	02/05/2009	03/01/2009	Fire Safety
KS	03/15/2010	03/22/2010	Fire Safety
KS	03/15/2010	03/22/2010	Fire Safety

	resist smoke for at least 20 minutes.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175122	DELMAR GARDENS OF LENEXA	LENEXA
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM

sumner regional medical center

Based on VSDA2

KS	03/15/2010	03/22/2010	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION	MERRIAM

KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	02/29/2008	03/30/2008	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Widespread
Miscellaneous Deficiencies	fire safety features required by	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	CENTER INC	
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175123	TRINITY NURSING & REHABILITATION CENTER INC	MERRIAM
175124	LAKEPOINT NURSING & REHAB CENTER OF EL DORADO	EL DORADO
175124	LAKEPOINT NURSING & REHAB CENTER OF EL DORADO	EL DORADO

sumner regional medical center

Based on VSDA2

KS	05/14/2009	06/13/2009	Fire Safety
KS	05/14/2009	06/13/2009	Fire Safety
KS	07/27/2010	08/04/2010	Fire Safety
KS	07/27/2010	08/04/2010	Fire Safety
KS	07/27/2010	08/04/2010	Fire Safety
KS	07/27/2010	08/04/2010	Fire Safety
KS	07/27/2010	08/04/2010	Fire Safety
KS	07/27/2010	08/10/2010	Fire Safety
KS	07/27/2010	08/05/2010	Fire Safety
KS	02/03/2009	02/27/2009	Fire Safety
KS	02/03/2009	02/27/2009	Fire Safety

	current fire safety codes.	
Medical Gases and Anesthetizing Areas Deficiencies	proper fire barriers, ventilation and signs for the transport of oxygen.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY

sumner regional medical center

Based on VSDA2

KS	07/31/2008	08/29/2008	Fire Safety
KS	07/31/2008	08/29/2008	Fire Safety
KS	07/31/2008	08/29/2008	Fire Safety
KS	07/31/2008	08/29/2008	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY

sumner regional medical center

Based on VSDA2

KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/18/2009	09/16/2009	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety

	conditions.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY

sumner regional medical center

Based on VSDA2

KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety
KS	08/24/2010	09/20/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Exits and Egress Deficiencies	rooms that can be unlocked from inside without a key.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Electrical Deficiencies	properly installed electrical wiring	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175126	VALLEY VIEW SENIOR LIFE	JUNCTION CITY
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA

sumner regional medical center

Based on VSDA2

KS	08/24/2010	09/20/2010	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety

	and equipment.	
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA

sumner regional medical center

Based on VSDA2

KS	06/10/2008	06/19/2008	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety
KS	06/10/2008	06/19/2008	Fire Safety
KS	07/15/2009	07/22/2009	Fire Safety
KS	07/15/2009	07/22/2009	Fire Safety
KS	07/15/2009	07/22/2009	Fire Safety
KS	11/18/2010	11/18/2010	Fire Safety
KS	11/18/2010	11/18/2010	Fire Safety
KS	11/18/2010	11/18/2010	Fire Safety
KS	11/18/2010	11/18/2010	Fire Safety

	allowed.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175127	WINDSOR ESTATES NURSING HOME	SALINA
175127	WINDSOR ESTATES NURSING HOME	SALINA
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER

sumner regional medical center

Based on VSDA2

KS	11/18/2010	11/18/2010	Fire Safety
KS	11/18/2010	11/18/2010	Fire Safety
KS	01/08/2009	01/23/2009	Fire Safety
KS	01/08/2009	01/12/2009	Fire Safety
KS	01/08/2009	01/15/2009	Fire Safety
KS	01/08/2009	01/13/2009	Fire Safety
KS	01/08/2009	01/08/2009	Fire Safety
KS	01/08/2009	01/08/2009	Fire Safety
KS	04/28/2010	05/25/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER

sumner regional medical center

Based on VSDA2

KS	04/28/2010	05/03/2010	Fire Safety
KS	03/01/2011	03/10/2011	Fire Safety
KS	03/01/2011	03/01/2011	Fire Safety
KS	03/01/2011	03/31/2011	Fire Safety
KS	03/01/2011	03/23/2011	Fire Safety
KS	03/01/2011	03/23/2011	Fire Safety
KS	03/01/2011	03/23/2011	Fire Safety
KS	03/01/2011	04/01/2011	Fire Safety
KS	03/01/2011	03/04/2011	Fire Safety

	would resist fire for at least one hour.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175130	MEADOWBROOK REHABILITATION HOSPITAL LTCU	GARDNER
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE

sumner regional medical center

Based on VSDA2

KS	03/01/2011	03/03/2011	Fire Safety
KS	03/01/2011	03/01/2011	Fire Safety
KS	03/01/2011	03/15/2011	Fire Safety
KS	03/01/2011	03/23/2011	Fire Safety
KS	03/01/2011	03/01/2011	Fire Safety
KS	09/27/2007	09/27/2007	Fire Safety
KS	09/27/2007	09/27/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE

sumner regional medical center

Based on VSDA2

KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	10/26/2007	Fire Safety
KS	09/27/2007	09/27/2007	Fire Safety
KS	12/11/2008	01/10/2009	Fire Safety
KS	12/11/2008	01/10/2009	Fire Safety
KS	12/11/2008	01/10/2009	Fire Safety
KS	12/11/2008	01/10/2009	Fire Safety

	have been maintained in working order.	
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	weekly inspections and monthly	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175133	HAYSVILLE HEALTHCARE CENTER	HAYSVILLE
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	03/09/2010	03/19/2010	Fire Safety
KS	03/09/2010	03/31/2010	Fire Safety
KS	03/09/2010	03/31/2010	Fire Safety
KS	03/09/2010	03/16/2010	Fire Safety
KS	03/09/2010	03/19/2010	Fire Safety
KS	11/20/2007	12/20/2007	Fire Safety
KS	11/20/2007	12/20/2007	Fire Safety
KS	11/20/2007	11/20/2007	Fire Safety
KS	11/20/2007	11/26/2007	Fire Safety
KS	11/20/2007	12/20/2007	Fire Safety

	testing of generators.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

	CENTER	
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	11/20/2007	12/01/2007	Fire Safety
KS	11/20/2007	11/20/2007	Fire Safety
KS	11/20/2007	11/26/2007	Fire Safety
KS	11/20/2007	11/26/2007	Fire Safety
KS	03/11/2009	04/10/2009	Fire Safety
KS	03/11/2009	04/10/2009	Fire Safety
KS	03/11/2009	04/10/2009	Fire Safety
KS	03/11/2009	04/10/2009	Fire Safety
KS	03/11/2009	04/10/2009	Fire Safety
KS	03/11/2009	04/10/2009	Fire Safety

	flammable curtains.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Widespread
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175135	MEDICALODGES POST ACUTE CARE CENTER	KANSAS CITY
175141	MEDICALODGES ATCHISON	ATCHISON
175141	MEDICALODGES ATCHISON	ATCHISON

sumner regional medical center

Based on VSDA2

KS	03/11/2009	04/10/2009	Fire Safety
KS	03/11/2009	04/10/2009	Fire Safety
KS	05/20/2010	05/20/2010	Fire Safety
KS	05/20/2010	05/20/2010	Fire Safety
KS	05/20/2010	05/20/2010	Fire Safety
KS	05/20/2010	06/18/2010	Fire Safety
KS	05/20/2010	05/21/2010	Fire Safety
KS	08/16/2007	09/14/2007	Fire Safety
KS	08/16/2007	09/14/2007	Fire Safety

	ashtrays where smoking was allowed.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Laboratories Deficiencies	emergency showers.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175141	MEDICALODGES ATCHISON	ATCHISON
175141	MEDICALODGES ATCHISON	ATCHISON
175141	MEDICALODGES ATCHISON	ATCHISON
175141	MEDICALODGES ATCHISON	ATCHISON
175141	MEDICALODGES ATCHISON	ATCHISON
175141	MEDICALODGES ATCHISON	ATCHISON
175141	MEDICALODGES ATCHISON	ATCHISON
175141	MEDICALODGES ATCHISON	ATCHISON
175141	MEDICALODGES ATCHISON	ATCHISON

sumner regional medical center

Based on VSDA2

KS	08/16/2007	08/22/2007	Fire Safety
KS	08/16/2007	09/14/2007	Fire Safety
KS	11/12/2008	12/10/2008	Fire Safety
KS	11/12/2008	12/10/2008	Fire Safety
KS	11/12/2008	12/10/2008	Fire Safety
KS	11/12/2008	11/21/2008	Fire Safety
KS	01/12/2010	02/10/2010	Fire Safety
KS	01/12/2010	02/10/2010	Fire Safety
KS	01/12/2010	02/10/2010	Fire Safety

Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK

sumner regional medical center

Based on VSDA2

KS	03/11/2008	03/15/2008	Fire Safety
KS	03/11/2008	03/15/2008	Fire Safety
KS	03/11/2008	04/01/2008	Fire Safety
KS	03/11/2008	04/01/2008	Fire Safety
KS	03/11/2008	03/15/2008	Fire Safety
KS	03/11/2008	04/01/2008	Fire Safety
KS	03/11/2008	04/01/2008	Fire Safety
KS	03/11/2008	03/20/2008	Fire Safety
KS	03/11/2008	03/15/2008	Fire Safety
KS	06/09/2009	07/01/2009	Fire Safety

	alarm system.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175145	BROOKSIDE RETIREMENT COMMUNITY	OVERBROOK
175146	PROMISE REGIONAL MEDICAL CENTER-HUTCHINSON INC SNU	HUTCHINSON
175146	PROMISE REGIONAL MEDICAL CENTER-HUTCHINSON INC SNU	HUTCHINSON
175146	PROMISE REGIONAL MEDICAL CENTER-HUTCHINSON INC SNU	HUTCHINSON
175146	PROMISE REGIONAL MEDICAL CENTER-HUTCHINSON INC SNU	HUTCHINSON
175146	PROMISE REGIONAL MEDICAL CENTER-HUTCHINSON INC SNU	HUTCHINSON
175146	PROMISE REGIONAL MEDICAL CENTER-HUTCHINSON INC SNU	HUTCHINSON

KS	07/29/2010	08/25/2010	Fire Safety
KS	07/29/2010	08/25/2010	Fire Safety
KS	07/29/2010	08/25/2010	Fire Safety
KS	04/07/2008	05/06/2008	Fire Safety
KS	04/07/2008	05/07/2008	Fire Safety
KS	04/07/2008	04/17/2008	Fire Safety
KS	04/07/2008	04/14/2008	Fire Safety
KS	04/07/2008	05/07/2008	Fire Safety
KS	06/23/2009	07/07/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Vertical Openings Deficiencies	protected exits that allow the resident to escape the building.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

	HUTCHINSON INC SNU	
175146	PROMISE REGIONAL MEDICAL CENTER-HUTCHINSON INC SNU	HUTCHINSON
175151	LAWRENCE MEMORIAL HOSPITAL SNF	LAWRENCE
175151	LAWRENCE MEMORIAL HOSPITAL SNF	LAWRENCE
175151	LAWRENCE MEMORIAL HOSPITAL SNF	LAWRENCE
175151	LAWRENCE MEMORIAL HOSPITAL SNF	LAWRENCE
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	06/23/2009	07/07/2009	Fire Safety
KS	08/01/2008	08/06/2008	Fire Safety
KS	08/01/2008	08/04/2008	Fire Safety
KS	08/01/2008	08/04/2008	Fire Safety
KS	03/31/2009	04/02/2009	Fire Safety
KS	05/19/2008	06/19/2008	Fire Safety
KS	05/19/2008	06/19/2008	Fire Safety
KS	05/19/2008	06/19/2008	Fire Safety

	each shift under varying conditions.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	05/19/2008	06/19/2008	Fire Safety
KS	05/19/2008	06/19/2008	Fire Safety
KS	05/19/2008	06/19/2008	Fire Safety
KS	05/19/2008	06/19/2008	Fire Safety
KS	05/19/2008	06/19/2008	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	07/09/2009	08/09/2009	Fire Safety
KS	07/09/2009	08/09/2009	Fire Safety
KS	08/17/2010	09/16/2010	Fire Safety
KS	08/17/2010	09/16/2010	Fire Safety
KS	08/17/2010	09/16/2010	Fire Safety
KS	08/17/2010	09/16/2010	Fire Safety
KS	08/17/2010	09/16/2010	Fire Safety
KS	08/17/2010	09/16/2010	Fire Safety
KS	08/17/2010	09/16/2010	Fire Safety
KS	08/17/2010	09/16/2010	Fire Safety
KS	08/17/2010	09/16/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	CENTER	
175154	LEXINGTON PARK NURSING & POST ACUTE CENTER	TOPEKA
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER

sumner regional medical center

Based on VSDA2

KS	08/17/2010	09/16/2010	Fire Safety
KS	12/06/2007	01/06/2008	Fire Safety
KS	12/06/2007	01/06/2008	Fire Safety
KS	12/06/2007	01/06/2008	Fire Safety
KS	12/06/2007	01/06/2008	Fire Safety
KS	12/06/2007	01/06/2008	Fire Safety
KS	12/06/2007	01/06/2008	Fire Safety
KS	12/06/2007	01/06/2008	Fire Safety
KS	12/08/2008	12/17/2008	Fire Safety
KS	12/08/2008	12/17/2008	Fire Safety
KS	12/08/2008	12/17/2008	Fire Safety

	testing of generators.	
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Interior Finish Deficiencies	fire-resistant interior walls.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175157	LIFE CARE CENTER OF ANDOVER	ANDOVER
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	12/08/2008	12/17/2008	Fire Safety
KS	01/28/2010	01/28/2010	Fire Safety
KS	01/28/2010	01/28/2010	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/20/2008	Fire Safety

	obstructions and can be used at all times.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	05/06/2008	05/09/2008	Fire Safety
KS	05/06/2008	05/16/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/19/2008	Fire Safety
KS	05/06/2008	05/09/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/14/2008	Fire Safety
KS	05/06/2008	05/07/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK

KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/09/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Widespread
Laboratories Deficiencies	emergency showers.	Pattern
Laboratories Deficiencies	proper facilities for the use and storage of combustible liquids.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread
Fire Alarm Systems Deficiencies	an approved back-up procedure	Widespread

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175158	GARDEN TERRACE AT OVERLAND PARK	OVERLAND PARK
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	05/06/2008	05/06/2008	Fire Safety
KS	08/19/2010	08/19/2010	Fire Safety
KS	08/19/2010	08/19/2010	Fire Safety
KS	08/07/2007	08/10/2007	Fire Safety
KS	08/07/2007	08/14/2007	Fire Safety
KS	08/07/2007	08/09/2007	Fire Safety
KS	08/07/2007	08/09/2007	Fire Safety
KS	08/07/2007	08/24/2007	Fire Safety
KS	08/07/2007	08/24/2007	Fire Safety
KS	08/07/2007	09/07/2007	Fire Safety
KS	08/07/2007	08/08/2007	Fire Safety

	for a faulty fire alarm system.	
Building Service Equipment Deficiencies	an elevator that firefighters can control in the event of a fire.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Widespread
Interior Finish Deficiencies	fire-resistant interior walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler	Widespread

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	08/07/2007	08/31/2007	Fire Safety
KS	08/07/2007	08/08/2007	Fire Safety
KS	05/09/2008	05/19/2008	Fire Safety
KS	05/09/2008	06/09/2008	Fire Safety
KS	05/09/2008	06/09/2008	Fire Safety
KS	05/09/2008	06/09/2008	Fire Safety
KS	05/09/2008	06/09/2008	Fire Safety
KS	05/09/2008	06/09/2008	Fire Safety
KS	05/09/2008	06/09/2008	Fire Safety
KS	05/09/2008	06/09/2008	Fire Safety

	system connected to the fire alarm system.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175159	PROVIDENCE PLACE	KANSAS CITY
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING &	OLATHE

sumner regional medical center

Based on VSDA2

KS	05/09/2008	06/09/2008	Fire Safety
KS	05/09/2008	05/10/2008	Fire Safety
KS	07/29/2009	07/30/2009	Fire Safety
KS	07/29/2009	07/30/2009	Fire Safety
KS	07/29/2009	08/25/2009	Fire Safety
KS	07/29/2009	08/25/2009	Fire Safety
KS	07/29/2009	08/25/2009	Fire Safety
KS	07/29/2009	08/25/2009	Fire Safety
KS	07/29/2009	07/29/2009	Fire Safety
KS	03/27/2008	04/25/2008	Fire Safety
KS	03/27/2008	04/25/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	REHABILITATION CENTER	
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING &	OLATHE

sumner regional medical center

Based on VSDA2

KS	03/27/2008	04/25/2008	Fire Safety
KS	03/27/2008	03/28/2008	Fire Safety
KS	03/27/2008	04/25/2008	Fire Safety
KS	03/27/2008	04/25/2008	Fire Safety
KS	03/27/2008	04/25/2008	Fire Safety
KS	03/27/2008	03/28/2008	Fire Safety
KS	03/27/2008	04/25/2008	Fire Safety
KS	03/27/2008	04/25/2008	Fire Safety
KS	05/07/2009	06/05/2009	Fire Safety
KS	05/07/2009	06/05/2009	Fire Safety

sumner regional medical center

Based on VSDA2

	times.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	REHABILITATION CENTER	
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE

sumner regional medical center

Based on VSDA2

KS	05/07/2009	06/05/2009	Fire Safety
KS	05/07/2009	06/05/2009	Fire Safety
KS	05/07/2009	06/05/2009	Fire Safety
KS	05/07/2009	06/05/2009	Fire Safety
KS	05/07/2009	06/05/2009	Fire Safety
KS	05/07/2009	06/05/2009	Fire Safety
KS	05/07/2009	06/05/2009	Fire Safety
KS	07/15/2010	08/13/2010	Fire Safety
KS	07/15/2010	08/13/2010	Fire Safety
KS	07/15/2010	08/13/2010	Fire Safety

	at least 1 1/2 hours.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper fire barriers, ventilation and signs for the transport of oxygen.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Service Equipment Deficiencies	an elevator that firefighters can control in the event of a fire.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175160	ROYAL TERRACE NURSING & REHABILITATION CENTER	OLATHE
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH

sumner regional medical center

Based on VSDA2

KS	07/15/2010	08/13/2010	Fire Safety
KS	07/15/2010	08/13/2010	Fire Safety
KS	07/15/2010	08/13/2010	Fire Safety
KS	07/15/2010	08/13/2010	Fire Safety
KS	07/15/2010	08/13/2010	Fire Safety
KS	07/15/2010	08/13/2010	Fire Safety
KS	07/15/2010	08/13/2010	Fire Safety
KS	11/19/2008	11/19/2008	Fire Safety
KS	11/19/2008	11/20/2008	Fire Safety

	hour.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH

KS	11/19/2008	12/01/2008	Fire Safety
KS	11/19/2008	12/01/2008	Fire Safety
KS	11/19/2008	12/01/2008	Fire Safety
KS	11/19/2008	12/01/2008	Fire Safety
KS	04/21/2009	05/21/2009	Fire Safety
KS	04/21/2009	04/27/2009	Fire Safety
KS	04/21/2009	05/21/2009	Fire Safety
KS	04/21/2009	04/27/2009	Fire Safety
KS	04/21/2009	05/21/2009	Fire Safety
KS	04/21/2009	05/21/2009	Fire Safety

	extinguishing system.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175162	MEDICALODGES LEAVENWORTH	LEAVENWORTH
175163	SOUTHWEST MEDICAL CENTER SNF	LIBERAL
175163	SOUTHWEST MEDICAL CENTER SNF	LIBERAL
175163	SOUTHWEST MEDICAL CENTER SNF	LIBERAL

sumner regional medical center

Based on VSDA2

KS	04/21/2009	04/27/2009	Fire Safety
KS	04/21/2009	05/21/2009	Fire Safety
KS	06/04/2010	06/11/2010	Fire Safety
KS	06/04/2010	06/25/2010	Fire Safety
KS	06/04/2010	06/11/2010	Fire Safety
KS	06/04/2010	06/04/2010	Fire Safety
KS	06/04/2010	06/04/2010	Fire Safety
KS	06/04/2008	06/12/2008	Fire Safety
KS	06/04/2008	06/05/2008	Fire Safety
KS	08/11/2009	08/12/2009	Fire Safety

	have been maintained in working order.	
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175163	SOUTHWEST MEDICAL CENTER SNF	LIBERAL
175163	SOUTHWEST MEDICAL CENTER SNF	LIBERAL
175163	SOUTHWEST MEDICAL CENTER SNF	LIBERAL
175163	SOUTHWEST MEDICAL CENTER SNF	LIBERAL
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	07/21/2010	07/21/2010	Fire Safety
KS	07/21/2010	07/21/2010	Fire Safety
KS	07/21/2010	07/23/2010	Fire Safety
KS	07/21/2010	07/21/2010	Fire Safety
KS	01/22/2009	02/20/2009	Fire Safety
KS	01/22/2009	02/20/2009	Fire Safety
KS	01/22/2009	02/20/2009	Fire Safety
KS	01/22/2009	02/20/2009	Fire Safety
KS	01/22/2009	02/20/2009	Fire Safety
KS	01/22/2009	02/20/2009	Fire Safety

	conditions.	
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit"	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	01/22/2009	02/20/2009	Fire Safety
KS	01/22/2009	02/20/2009	Fire Safety
KS	01/22/2009	02/20/2009	Fire Safety
KS	01/22/2009	02/20/2009	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety

	signs.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA

KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175165	ROLLING HILLS HEALTH CENTER	TOPEKA
175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA
175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA
175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA
175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA
175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA
175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA
175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA

KS	03/15/2010	04/16/2010	Fire Safety
KS	03/15/2010	04/16/2010	Fire Safety
KS	02/12/2008	03/13/2008	Fire Safety
KS	02/12/2008	03/13/2008	Fire Safety
KS	02/12/2008	03/13/2008	Fire Safety
KS	02/12/2008	03/13/2008	Fire Safety
KS	02/12/2008	03/13/2008	Fire Safety
KS	02/12/2008	03/13/2008	Fire Safety
KS	02/12/2008	03/13/2008	Fire Safety

	administration areas.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA
175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA
175168	MANORCARE HEALTH SERVICES - WICHITA	WICHITA
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175169	COFFEYVILLE REGIONAL MEDICAL CENTER	COFFEYVILLE

sumner regional medical center

Based on VSDA2

KS	02/12/2008	03/13/2008	Fire Safety
KS	02/27/2009	02/27/2009	Fire Safety
KS	04/21/2010	04/21/2010	Fire Safety
KS	08/15/2008	10/14/2008	Fire Safety
KS	08/15/2008	10/14/2008	Fire Safety
KS	08/11/2009	08/11/2009	Fire Safety
KS	08/11/2009	08/12/2009	Fire Safety
KS	08/11/2009	08/12/2009	Fire Safety
KS	08/11/2009	08/12/2009	Fire Safety
KS	08/11/2009	08/11/2009	Fire Safety

	ashtrays where smoking was allowed.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

	SNF	
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175169	COFFEYVILLE REGIONAL MEDICAL CENTER SNF	COFFEYVILLE
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	08/11/2009	08/11/2009	Fire Safety
KS	08/11/2009	08/17/2009	Fire Safety
KS	11/10/2010	11/15/2010	Fire Safety
KS	11/10/2010	11/22/2010	Fire Safety
KS	04/22/2008	05/02/2008	Fire Safety
KS	04/22/2008	05/02/2008	Fire Safety
KS	04/22/2008	05/02/2008	Fire Safety
KS	04/22/2008	05/23/2008	Fire Safety
KS	04/22/2008	05/23/2008	Fire Safety
KS	04/22/2008	05/02/2008	Fire Safety

	at least 1 1/2 hours.	
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	04/22/2008	05/02/2008	Fire Safety
KS	04/22/2008	05/02/2008	Fire Safety
KS	04/22/2008	05/02/2008	Fire Safety
KS	04/22/2008	05/02/2008	Fire Safety
KS	04/22/2008	05/23/2008	Fire Safety
KS	04/22/2008	05/23/2008	Fire Safety
KS	04/22/2008	05/02/2008	Fire Safety
KS	04/22/2008	05/23/2008	Fire Safety
KS	04/22/2008	05/23/2008	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	04/22/2008	05/09/2008	Fire Safety
KS	04/22/2008	05/23/2008	Fire Safety
KS	04/22/2008	05/23/2008	Fire Safety
KS	04/22/2008	05/23/2008	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	01/01/1900	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	06/03/2009	07/01/2009	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety

	order.	
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175171	MCCRITE PLAZA HEALTH CENTER	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA

sumner regional medical center

Based on VSDA2

KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	07/15/2010	08/14/2010	Fire Safety
KS	11/06/2008	12/06/2008	Fire Safety
KS	11/06/2008	12/06/2008	Fire Safety

	extinguishing system.	
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA

KS	11/06/2008	12/06/2008	Fire Safety
KS	11/06/2008	12/06/2008	Fire Safety
KS	11/06/2008	12/06/2008	Fire Safety
KS	11/06/2008	12/06/2008	Fire Safety
KS	02/18/2010	03/05/2010	Fire Safety
KS	02/18/2010	03/02/2010	Fire Safety
KS	02/18/2010	03/02/2010	Fire Safety
KS	02/18/2010	02/18/2010	Fire Safety
KS	02/18/2010	02/18/2010	Fire Safety
KS	02/18/2010	03/02/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA

sumner regional medical center

Based on VSDA2

KS	02/18/2010	03/05/2010	Fire Safety
KS	02/18/2010	02/18/2010	Fire Safety
KS	02/10/2011	02/21/2011	Fire Safety
KS	02/10/2011	02/18/2011	Fire Safety
KS	02/10/2011	02/10/2011	Fire Safety
KS	02/10/2011	02/18/2011	Fire Safety
KS	02/10/2011	02/10/2011	Fire Safety
KS	02/10/2011	02/18/2011	Fire Safety
KS	02/10/2011	02/10/2011	Fire Safety

	administration areas.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175172	MANORCARE HEALTH SERVICES - TOPEKA	TOPEKA
175173	HOLIDAY RESORT	EMPORIA
175173	HOLIDAY RESORT	EMPORIA
175173	HOLIDAY RESORT	EMPORIA
175173	HOLIDAY RESORT	EMPORIA
175173	HOLIDAY RESORT	EMPORIA
175173	HOLIDAY RESORT	EMPORIA
175173	HOLIDAY RESORT	EMPORIA
175173	HOLIDAY RESORT	EMPORIA
175174	MEADOWLARK HILLS	MANHATTAN

sumner regional medical center

Based on VSDA2

KS	02/10/2011	02/18/2011	Fire Safety
KS	08/14/2008	08/18/2008	Fire Safety
KS	08/14/2008	08/14/2008	Fire Safety
KS	08/14/2008	08/14/2008	Fire Safety
KS	09/17/2009	10/17/2009	Fire Safety
KS	09/17/2009	10/17/2009	Fire Safety
KS	10/22/2010	11/01/2010	Fire Safety
KS	10/22/2010	11/01/2010	Fire Safety
KS	12/04/2007	12/31/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN

sumner regional medical center

Based on VSDA2

KS	12/04/2007	12/31/2007	Fire Safety
KS	12/04/2007	12/21/2007	Fire Safety
KS	12/04/2007	12/21/2007	Fire Safety
KS	12/04/2007	12/28/2007	Fire Safety
KS	12/04/2007	12/07/2007	Fire Safety
KS	12/04/2007	01/03/2008	Fire Safety
KS	12/04/2007	12/28/2007	Fire Safety
KS	12/04/2007	12/27/2007	Fire Safety
KS	12/04/2007	12/04/2007	Fire Safety

Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN

KS	12/04/2007	12/07/2007	Fire Safety
KS	12/04/2007	12/04/2007	Fire Safety
KS	12/04/2007	12/05/2007	Fire Safety
KS	12/04/2007	12/28/2007	Fire Safety
KS	12/04/2007	01/02/2008	Fire Safety
KS	12/04/2007	12/14/2007	Fire Safety
KS	12/04/2007	12/19/2007	Fire Safety
KS	01/09/2009	02/07/2009	Fire Safety
KS	01/09/2009	01/09/2009	Fire Safety
KS	01/09/2009	01/09/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175174	MEADOWLARK HILLS	MANHATTAN
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY

sumner regional medical center

Based on VSDA2

KS	01/09/2009	01/23/2009	Fire Safety
KS	01/09/2009	01/09/2009	Fire Safety
KS	01/09/2009	01/09/2009	Fire Safety
KS	01/09/2009	02/07/2009	Fire Safety
KS	01/09/2009	01/09/2009	Fire Safety
KS	02/23/2010	03/24/2010	Fire Safety
KS	02/23/2010	03/24/2010	Fire Safety
KS	02/23/2010	02/26/2010	Fire Safety
KS	02/23/2010	02/23/2010	Fire Safety
KS	01/23/2008	01/24/2008	Fire Safety

	would resist fire for at least one hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY

sumner regional medical center

Based on VSDA2

KS	01/23/2008	02/23/2008	Fire Safety
KS	01/23/2008	01/25/2008	Fire Safety
KS	01/23/2008	01/28/2008	Fire Safety
KS	01/23/2008	01/26/2008	Fire Safety
KS	01/23/2008	01/28/2008	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	01/11/2010	02/08/2010	Fire Safety
KS	01/11/2010	02/08/2010	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175175	GARDEN VALLEY RETIREMENT VILLAGE	GARDEN CITY
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	01/11/2010	02/08/2010	Fire Safety
KS	01/11/2010	02/08/2010	Fire Safety
KS	01/11/2010	02/08/2010	Fire Safety
KS	01/11/2010	02/08/2010	Fire Safety
KS	08/28/2007	08/30/2007	Fire Safety
KS	08/28/2007	08/30/2007	Fire Safety
KS	08/28/2007	08/30/2007	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	08/28/2007	08/30/2007	Fire Safety
KS	08/28/2007	08/30/2007	Fire Safety
KS	08/28/2007	09/27/2007	Fire Safety
KS	08/28/2007	08/28/2007	Fire Safety
KS	12/03/2008	12/04/2008	Fire Safety
KS	12/03/2008	12/04/2008	Fire Safety
KS	12/03/2008	12/16/2008	Fire Safety
KS	12/03/2008	12/04/2008	Fire Safety
KS	12/03/2008	12/16/2008	Fire Safety
KS	12/03/2008	12/16/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175176	INDIAN CREEK HEALTHCARE CENTER	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	12/03/2008	12/24/2008	Fire Safety
KS	12/03/2008	12/05/2008	Fire Safety
KS	12/03/2008	12/05/2008	Fire Safety
KS	12/03/2008	12/24/2008	Fire Safety
KS	12/03/2008	12/24/2008	Fire Safety
KS	02/12/2010	02/12/2010	Fire Safety
KS	02/12/2010	03/12/2010	Fire Safety
KS	02/12/2010	02/12/2010	Fire Safety
KS	02/12/2010	02/12/2010	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	OVERLAND PARK	
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK

KS	04/11/2007	05/11/2007	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety
KS	04/11/2007	05/11/2007	Fire Safety

	block smoke.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

	OVERLAND PARK	
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175180	MANORCARE HEALTH SERVICES -	OVERLAND PARK

KS	06/05/2008	06/15/2008	Fire Safety
KS	06/05/2008	06/15/2008	Fire Safety
KS	06/05/2008	06/15/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	06/16/2008	Fire Safety
KS	06/05/2008	06/09/2008	Fire Safety
KS	06/05/2008	06/10/2008	Fire Safety

	and equipment.	
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

	OVERLAND PARK	
175180	MANORCARE HEALTH SERVICES - OVERLAND PARK	OVERLAND PARK
175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA

sumner regional medical center

Based on VSDA2

KS	06/05/2008	06/05/2008	Fire Safety
KS	09/23/2008	10/23/2008	Fire Safety
KS	09/23/2008	10/23/2008	Fire Safety
KS	09/23/2008	10/23/2008	Fire Safety
KS	09/23/2008	10/23/2008	Fire Safety
KS	09/23/2008	10/23/2008	Fire Safety
KS	09/23/2008	10/23/2008	Fire Safety
KS	09/23/2008	10/23/2008	Fire Safety
KS	09/23/2008	10/23/2008	Fire Safety
KS	09/23/2008	10/23/2008	Fire Safety

	administration areas.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA
175181	LARKSFIELD PLACE	WICHITA
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK

KS	09/23/2008	10/23/2008	Fire Safety
KS	11/03/2009	11/03/2009	Fire Safety
KS	12/16/2010	12/16/2010	Fire Safety
KS	08/07/2007	08/21/2007	Fire Safety
KS	08/07/2007	08/07/2007	Fire Safety
KS	08/07/2007	08/21/2007	Fire Safety
KS	08/07/2007	08/07/2007	Fire Safety
KS	08/07/2007	08/07/2007	Fire Safety
KS	08/07/2007	08/07/2007	Fire Safety

	have been maintained in working order.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	08/07/2007	08/21/2007	Fire Safety
KS	08/07/2007	08/13/2007	Fire Safety
KS	08/07/2007	08/07/2007	Fire Safety
KS	08/07/2007	08/07/2007	Fire Safety
KS	08/07/2007	08/07/2007	Fire Safety
KS	10/01/2008	10/10/2008	Fire Safety
KS	10/01/2008	10/10/2008	Fire Safety
KS	10/01/2008	10/20/2008	Fire Safety
KS	10/01/2008	10/10/2008	Fire Safety

	times.	
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175182	DELMAR GARDENS OF OVERLAND PARK	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	10/01/2008	10/10/2008	Fire Safety
KS	10/01/2008	10/31/2008	Fire Safety
KS	10/01/2008	10/31/2008	Fire Safety
KS	11/03/2009	11/09/2009	Fire Safety
KS	11/03/2009	11/10/2009	Fire Safety
KS	01/16/2008	01/30/2008	Fire Safety
KS	01/16/2008	01/24/2008	Fire Safety
KS	01/16/2008	02/01/2008	Fire Safety
KS	01/16/2008	02/08/2008	Fire Safety
KS	01/16/2008	02/08/2008	Fire Safety
KS	01/16/2008	01/31/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK
175183	VILLA ST JOSEPH	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	01/16/2008	01/31/2008	Fire Safety
KS	04/02/2009	04/23/2009	Fire Safety
KS	04/02/2009	04/23/2009	Fire Safety
KS	04/02/2009	04/10/2009	Fire Safety
KS	04/02/2009	04/10/2009	Fire Safety
KS	07/19/2010	07/30/2010	Fire Safety
KS	07/19/2010	08/12/2010	Fire Safety
KS	07/19/2010	07/19/2010	Fire Safety
KS	07/19/2010	07/19/2010	Fire Safety
KS	07/19/2010	07/26/2010	Fire Safety
KS	07/19/2010	07/26/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175183	VILLA ST JOSEPH	OVERLAND PARK
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA

sumner regional medical center

Based on VSDA2

KS	07/19/2010	07/30/2010	Fire Safety
KS	07/15/2008	08/10/2008	Fire Safety
KS	07/15/2008	08/10/2008	Fire Safety
KS	07/15/2008	08/10/2008	Fire Safety
KS	07/15/2008	08/10/2008	Fire Safety
KS	08/25/2009	08/28/2009	Fire Safety
KS	08/25/2009	08/28/2009	Fire Safety
KS	08/25/2009	08/31/2009	Fire Safety
KS	08/25/2009	08/31/2009	Fire Safety

	at least 1 1/2 hours.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA

sumner regional medical center

Based on VSDA2

KS	08/25/2009	08/31/2009	Fire Safety
KS	08/25/2009	08/26/2009	Fire Safety
KS	08/25/2009	09/22/2009	Fire Safety
KS	08/25/2009	08/26/2009	Fire Safety
KS	08/25/2009	09/22/2009	Fire Safety
KS	08/25/2009	09/22/2009	Fire Safety
KS	08/25/2009	08/28/2009	Fire Safety
KS	08/25/2009	08/26/2009	Fire Safety
KS	08/25/2009	08/26/2009	Fire Safety
KS	08/25/2009	08/26/2009	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA

sumner regional medical center

Based on VSDA2

KS	09/21/2010	09/21/2010	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety
KS	09/21/2010	09/29/2010	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring	Isolated

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175184	PINNACLE PARK NURSING & REHAB CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA

sumner regional medical center

Based on VSDA2

KS			Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation,	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA

sumner regional medical center

Based on VSDA2

KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	08/20/2008	09/19/2008	Fire Safety
KS	10/14/2009	10/21/2009	Fire Safety
KS	10/14/2009	10/30/2009	Fire Safety

sumner regional medical center

Based on VSDA2

	maintenance and testing program for fire alarm systems.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Vertical Openings Deficiencies	protected exits that allow the resident to escape the building.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA

KS	10/14/2009	10/30/2009	Fire Safety
KS	10/14/2009	10/16/2009	Fire Safety
KS	10/14/2009	10/30/2009	Fire Safety
KS	10/14/2009	10/15/2009	Fire Safety
KS	10/14/2009	10/15/2009	Fire Safety
KS	10/14/2009	10/19/2009	Fire Safety
KS	11/23/2010	12/23/2010	Fire Safety
KS	11/23/2010	12/23/2010	Fire Safety
KS	11/23/2010	12/23/2010	Fire Safety
KS	11/23/2010	12/23/2010	Fire Safety
KS	11/23/2010	12/23/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175185	SMOKY HILL REHABILITATION CENTER	SALINA
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	11/23/2010	12/23/2010	Fire Safety
KS	11/23/2010	12/23/2010	Fire Safety
KS	11/23/2010	12/23/2010	Fire Safety
KS	01/30/2008	02/29/2008	Fire Safety
KS	01/30/2008	01/31/2008	Fire Safety
KS	01/30/2008	02/28/2008	Fire Safety
KS	01/30/2008	02/29/2008	Fire Safety
KS	01/30/2008	01/30/2008	Fire Safety
KS	01/30/2008	01/30/2008	Fire Safety
KS	01/30/2008	02/29/2008	Fire Safety

	order.	
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175187	OVERLAND PARK NURSING & REHAB CENTER INC	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	01/30/2008	02/29/2008	Fire Safety
KS	01/30/2008	02/29/2008	Fire Safety
KS	05/05/2009	06/04/2009	Fire Safety
KS	05/05/2009	06/04/2009	Fire Safety
KS	05/05/2009	06/04/2009	Fire Safety
KS	08/18/2010	09/01/2010	Fire Safety
KS	08/18/2010	08/31/2010	Fire Safety
KS	08/18/2010	09/16/2010	Fire Safety
KS	08/18/2010	08/31/2010	Fire Safety
KS	04/14/2008	05/12/2008	Fire Safety

	smoke passage.	
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Isolated
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper fire barriers, ventilation and signs for the transport of oxygen.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK

KS	04/14/2008	05/12/2008	Fire Safety
KS	04/14/2008	04/22/2008	Fire Safety
KS	04/14/2008	04/22/2008	Fire Safety
KS	04/14/2008	05/12/2008	Fire Safety
KS	04/14/2008	04/30/2008	Fire Safety
KS	04/14/2008	04/18/2008	Fire Safety
KS	04/14/2008	05/12/2008	Fire Safety
KS	04/14/2008	04/14/2008	Fire Safety
KS	04/14/2008	04/14/2008	Fire Safety
KS	04/14/2008	05/12/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK
175189	THE FORUM AT OVERLAND PARK	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	06/04/2009	06/30/2009	Fire Safety
KS	06/04/2009	07/03/2009	Fire Safety
KS	06/04/2009	07/03/2009	Fire Safety
KS	06/04/2009	06/11/2009	Fire Safety
KS	06/04/2009	06/15/2009	Fire Safety
KS	06/04/2009	07/03/2009	Fire Safety
KS	06/04/2009	07/03/2009	Fire Safety
KS	08/23/2010	09/01/2010	Fire Safety
KS	08/23/2010	09/22/2010	Fire Safety
KS	08/23/2010	09/06/2010	Fire Safety
KS	08/23/2010	09/22/2010	Fire Safety

	testing of generators.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN

KS	09/20/2007	09/30/2007	Fire Safety
KS	09/20/2007	09/30/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	09/30/2007	Fire Safety
KS	09/20/2007	09/30/2007	Fire Safety
KS	09/20/2007	09/30/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	09/30/2007	Fire Safety
KS	09/20/2007	09/30/2007	Fire Safety

	permitted or did not provide ashtrays where smoking was allowed.	
Building Construction Deficiencies	approved construction type or materials.	Pattern
Interior Finish Deficiencies	fire-resistant interior walls.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN

KS	09/20/2007	09/30/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	09/30/2007	Fire Safety
KS	09/22/2008	10/21/2008	Fire Safety
KS	09/22/2008	10/21/2008	Fire Safety
KS	09/22/2008	10/21/2008	Fire Safety
KS	09/22/2008	10/21/2008	Fire Safety
KS	09/22/2008	10/21/2008	Fire Safety
KS	09/22/2008	10/21/2008	Fire Safety
KS	09/22/2008	10/21/2008	Fire Safety
KS	09/22/2008	10/21/2008	Fire Safety

	heard throughout the facility.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Building Service Equipment Deficiencies	properly protected cooking	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175191	STONEYBROOK RETIREMENT COMMUNITY	MANHATTAN
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	09/22/2008	10/21/2008	Fire Safety
KS	11/10/2009	11/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	02/02/2009	02/13/2009	Fire Safety
KS	02/02/2009	02/13/2009	Fire Safety
KS	02/02/2009	02/26/2009	Fire Safety
KS	02/02/2009	03/02/2009	Fire Safety
KS	02/02/2009	02/13/2009	Fire Safety
KS	02/02/2009	03/02/2009	Fire Safety

	facilities.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation,	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	02/02/2009	02/13/2009	Fire Safety
KS	02/02/2009	03/02/2009	Fire Safety
KS	02/02/2009	03/02/2009	Fire Safety
KS	02/08/2010	03/01/2010	Fire Safety
KS	02/08/2010	03/01/2010	Fire Safety
KS	02/08/2010	03/01/2010	Fire Safety
KS	02/08/2010	03/01/2010	Fire Safety
KS	02/08/2010	03/01/2010	Fire Safety
KS	02/08/2010	03/01/2010	Fire Safety

	maintenance and testing program for fire alarm systems.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175193	TOPEKA COMMUNITY HEALTHCARE CENTER	TOPEKA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA

sumner regional medical center

Based on VSDA2

KS	02/14/2011	03/11/2011	Fire Safety
KS	02/14/2011	03/11/2011	Fire Safety
KS	02/14/2011	03/11/2011	Fire Safety
KS	02/14/2011	03/11/2011	Fire Safety
KS	02/14/2011	03/11/2011	Fire Safety
KS	02/14/2011	03/11/2011	Fire Safety
KS	02/14/2011	03/11/2011	Fire Safety
KS	02/14/2011	03/11/2011	Fire Safety
KS	02/14/2011	03/11/2011	Fire Safety
KS	06/24/2008	06/25/2008	Fire Safety
KS	06/24/2008	06/27/2008	Fire Safety

	testing of generators.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA

KS	06/24/2008	07/01/2008	Fire Safety
KS	06/24/2008	07/01/2008	Fire Safety
KS	06/24/2008	07/03/2008	Fire Safety
KS	06/24/2008	06/25/2008	Fire Safety
KS	07/14/2009	07/14/2009	Fire Safety
KS	07/14/2009	07/17/2009	Fire Safety
KS	07/14/2009	07/14/2009	Fire Safety
KS	07/14/2009	07/17/2009	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA
175200	KENWOOD VIEW NURSING HOME	SALINA

sumner regional medical center

Based on VSDA2

KS	07/14/2009	07/21/2009	Fire Safety
KS	10/19/2010	10/19/2010	Fire Safety
KS	10/19/2010	10/19/2010	Fire Safety
KS	10/19/2010	10/19/2010	Fire Safety
KS	10/19/2010	10/19/2010	Fire Safety
KS	10/19/2010	10/21/2010	Fire Safety
KS	10/19/2010	10/19/2010	Fire Safety
KS	10/19/2010	10/19/2010	Fire Safety
KS	10/19/2010	10/19/2010	Fire Safety
KS	10/19/2010	10/19/2010	Fire Safety

	for fire alarm systems.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS

sumner regional medical center

Based on VSDA2

KS	09/03/2008	10/17/2008	Fire Safety
KS	09/03/2008	10/17/2008	Fire Safety
KS	09/03/2008	10/17/2008	Fire Safety
KS	09/03/2008	10/17/2008	Fire Safety
KS	09/03/2008	10/17/2008	Fire Safety
KS	09/03/2008	10/17/2008	Fire Safety
KS	09/03/2008	10/17/2008	Fire Safety
KS	09/03/2008	10/17/2008	Fire Safety
KS	09/03/2008	10/17/2008	Fire Safety

	administration areas.	
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175201	GOLDEN LIVINGCENTER - DOWNS	DOWNS
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY

sumner regional medical center

Based on VSDA2

KS	09/03/2008	10/17/2008	Fire Safety
KS	09/14/2009	09/22/2009	Fire Safety
KS	09/14/2009	09/22/2009	Fire Safety
KS	09/14/2009	09/22/2009	Fire Safety
KS	10/19/2010	11/18/2010	Fire Safety
KS	10/19/2010	11/16/2010	Fire Safety
KS	01/27/2010	01/27/2010	Fire Safety
KS	01/27/2010	02/25/2010	Fire Safety
KS	01/27/2010	02/25/2010	Fire Safety
KS	01/27/2010	02/25/2010	Fire Safety

	flammable curtains.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY
175202	DESERET NURSING & REHABILITATION AT COLBY	COLBY

sumner regional medical center

Based on VSDA2

KS	01/27/2010	02/25/2010	Fire Safety
KS	01/27/2010	02/25/2010	Fire Safety
KS	07/14/2010	08/12/2010	Fire Safety
KS	07/14/2010	08/12/2010	Fire Safety
KS	02/04/2011	03/04/2011	Fire Safety
KS	02/04/2011	03/04/2011	Fire Safety
KS	02/04/2011	03/04/2011	Fire Safety
KS	02/04/2011	03/04/2011	Fire Safety
KS	02/04/2011	03/04/2011	Fire Safety
KS	02/04/2011	03/04/2011	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

	COLBY	
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175205	GOLDEN LIVINGCENTER - WILSON	WILSON
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY

sumner regional medical center

Based on VSDA2

KS	03/26/2008	04/25/2008	Fire Safety
KS	03/26/2008	04/25/2008	Fire Safety
KS	06/03/2009	06/30/2009	Fire Safety
KS	06/03/2009	06/30/2009	Fire Safety
KS	06/03/2009	06/30/2009	Fire Safety
KS	06/03/2009	06/30/2009	Fire Safety
KS	07/21/2010	07/21/2010	Fire Safety
KS	07/21/2010	07/21/2010	Fire Safety
KS	07/21/2010	08/05/2010	Fire Safety
KS	02/19/2008	02/29/2008	Fire Safety

	and equipment.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY

KS	02/19/2008	02/28/2008	Fire Safety
KS	02/19/2008	02/28/2008	Fire Safety
KS	02/19/2008	02/24/2008	Fire Safety
KS	02/19/2008	02/24/2008	Fire Safety
KS	02/19/2008	02/28/2008	Fire Safety
KS	11/05/2008	11/06/2008	Fire Safety
KS	11/05/2008	11/30/2008	Fire Safety
KS	11/05/2008	11/28/2008	Fire Safety
KS	11/05/2008	11/30/2008	Fire Safety
KS	11/05/2008	11/05/2008	Fire Safety
KS	11/05/2008	11/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175207	GOOD SAMARITAN SOCIETY - DODGE CITY	DODGE CITY
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG

sumner regional medical center

Based on VSDA2

KS	11/05/2008	11/06/2008	Fire Safety
KS	10/27/2009	11/17/2009	Fire Safety
KS	10/27/2009	11/27/2009	Fire Safety
KS	10/27/2009	11/26/2009	Fire Safety
KS	10/27/2009	11/26/2009	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety

	testing of generators.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG

KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/21/2008	Fire Safety
KS	02/18/2009	03/19/2009	Fire Safety
KS	02/18/2009	03/19/2009	Fire Safety
KS	02/18/2009	03/19/2009	Fire Safety
KS	02/18/2009	03/19/2009	Fire Safety
KS	02/18/2009	03/19/2009	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175208	GOLDEN LIVINGCENTER - PITTSBURG	PITTSBURG
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS

sumner regional medical center

Based on VSDA2

KS	02/18/2009	03/19/2009	Fire Safety
KS	02/18/2009	03/19/2009	Fire Safety
KS	02/18/2009	03/19/2009	Fire Safety
KS	02/18/2009	03/19/2009	Fire Safety
KS	02/23/2010	02/23/2010	Fire Safety
KS	09/20/2007	09/28/2007	Fire Safety
KS	09/20/2007	10/20/2007	Fire Safety
KS	09/20/2007	09/28/2007	Fire Safety
KS	09/20/2007	10/05/2007	Fire Safety
KS	09/20/2007	10/12/2007	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Electrical Deficiencies	weekly inspections and monthly	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS

sumner regional medical center

Based on VSDA2

KS	10/09/2008	10/16/2008	Fire Safety
KS	10/09/2008	10/14/2008	Fire Safety
KS	10/09/2008	10/16/2008	Fire Safety
KS	10/09/2008	10/27/2008	Fire Safety
KS	10/09/2008	10/17/2008	Fire Safety
KS	10/14/2009	10/16/2009	Fire Safety
KS	10/14/2009	10/16/2009	Fire Safety
KS	10/14/2009	10/16/2009	Fire Safety

	testing of generators.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175210	GOOD SAMARITAN SOCIETY - PARSONS	PARSONS
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE

sumner regional medical center

Based on VSDA2

KS	10/14/2009	10/20/2009	Fire Safety
KS	07/12/2007	07/27/2007	Fire Safety
KS	07/12/2007	07/27/2007	Fire Safety
KS	07/12/2007	07/27/2007	Fire Safety
KS	07/12/2007	07/27/2007	Fire Safety
KS	07/12/2007	07/27/2007	Fire Safety
KS	07/12/2007	07/27/2007	Fire Safety
KS	07/12/2007	07/27/2007	Fire Safety
KS	07/12/2007	07/20/2007	Fire Safety

	conditions.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	CENTER	
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE

KS	07/12/2007	07/16/2007	Fire Safety
KS	07/12/2007	07/13/2007	Fire Safety
KS	07/12/2007	07/20/2007	Fire Safety
KS	07/12/2007	07/19/2007	Fire Safety
KS	07/12/2007	07/19/2007	Fire Safety
KS	07/12/2007	07/13/2007	Fire Safety
KS	09/30/2008	10/09/2008	Fire Safety
KS	09/30/2008	10/09/2008	Fire Safety
KS	09/30/2008	10/09/2008	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175213	PINNACLE RIDGE NURSING & REHAB CENTER	OLATHE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE

sumner regional medical center

Based on VSDA2

KS	09/30/2008	10/09/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE

sumner regional medical center

Based on VSDA2

KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	01/18/2008	02/16/2008	Fire Safety
KS	12/17/2008	01/16/2009	Fire Safety
KS	12/17/2008	01/16/2009	Fire Safety
KS	12/17/2008	01/16/2009	Fire Safety
KS	12/17/2008	01/16/2009	Fire Safety

	order.	
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175214	CHANUTE HEALTHCARE CENTER	CHANUTE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE

sumner regional medical center

Based on VSDA2

KS	12/17/2008	01/16/2009	Fire Safety
KS	12/17/2008	01/16/2009	Fire Safety
KS	12/17/2008	01/16/2009	Fire Safety
KS	11/03/2009	12/03/2009	Fire Safety
KS	11/03/2009	12/03/2009	Fire Safety
KS	11/03/2009	12/03/2009	Fire Safety
KS	11/03/2009	12/03/2009	Fire Safety
KS	11/03/2009	12/03/2009	Fire Safety
KS	06/26/2008	07/25/2008	Fire Safety
KS	06/26/2008	07/25/2008	Fire Safety

Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE

KS	06/26/2008	07/25/2008	Fire Safety
KS	06/26/2008	07/25/2008	Fire Safety
KS	06/26/2008	07/25/2008	Fire Safety
KS	06/26/2008	07/25/2008	Fire Safety
KS	06/26/2008	07/25/2008	Fire Safety
KS	08/31/2009	09/09/2009	Fire Safety
KS	08/31/2009	09/09/2009	Fire Safety
KS	08/31/2009	09/10/2009	Fire Safety
KS	08/31/2009	09/09/2009	Fire Safety
KS	08/31/2009	09/03/2009	Fire Safety

	minutes.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE

sumner regional medical center

Based on VSDA2

KS	08/31/2009	09/30/2009	Fire Safety
KS	08/31/2009	09/03/2009	Fire Safety
KS	08/31/2009	09/09/2009	Fire Safety
KS	08/31/2009	09/30/2009	Fire Safety
KS	08/31/2009	09/15/2009	Fire Safety
KS	11/17/2010	12/09/2010	Fire Safety
KS	11/17/2010	12/09/2010	Fire Safety
KS	11/17/2010	12/09/2010	Fire Safety
KS	11/17/2010	12/09/2010	Fire Safety
KS	11/17/2010	12/09/2010	Fire Safety
KS	11/17/2010	12/09/2010	Fire Safety

	detectors.	
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Widespread

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175215	TONGANOXIE NURSING CENTER	TONGANOXIE
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA

sumner regional medical center

Based on VSDA2

KS	11/17/2010	11/18/2010	Fire Safety
KS	11/17/2010	11/29/2010	Fire Safety
KS	11/17/2010	12/09/2010	Fire Safety
KS	11/17/2010	12/09/2010	Fire Safety
KS	11/17/2010	12/09/2010	Fire Safety
KS	11/17/2010	11/17/2010	Fire Safety
KS	01/09/2008	02/06/2008	Fire Safety
KS	01/09/2008	02/06/2008	Fire Safety
KS	01/09/2008	02/06/2008	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Electrical Deficiencies	a separate and independent backup electrical power source.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION	WATHENA

sumner regional medical center

Based on VSDA2

KS	01/09/2008	01/29/2008	Fire Safety
KS	01/09/2008	01/17/2008	Fire Safety
KS	01/09/2008	01/24/2008	Fire Safety
KS	01/09/2008	02/06/2008	Fire Safety
KS	01/09/2008	02/06/2008	Fire Safety
KS	01/09/2008	02/06/2008	Fire Safety
KS	01/09/2008	01/17/2008	Fire Safety
KS	01/09/2008	01/09/2008	Fire Safety
KS	01/09/2008	01/17/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION	WATHENA

sumner regional medical center

Based on VSDA2

KS			Fire Safety
KS	01/09/2008	01/17/2008	Fire Safety
KS	01/09/2008	01/17/2008	Fire Safety
KS	01/09/2008	01/17/2008	Fire Safety
KS	01/09/2008	01/17/2008	Fire Safety
KS	01/22/2009	02/21/2009	Fire Safety
KS	01/22/2009	02/21/2009	Fire Safety
KS	01/22/2009	02/21/2009	Fire Safety
KS	01/22/2009	02/21/2009	Fire Safety
KS	01/22/2009	02/21/2009	Fire Safety
KS	01/22/2009	02/21/2009	Fire Safety
KS	01/22/2009	02/21/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Isolated
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	CENTER	
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA

sumner regional medical center

Based on VSDA2

KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	03/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	03/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety

	and equipment.	
Interior Finish Deficiencies	fire-resistant interior walls.	Widespread
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175216	WATHENA HEALTHCARE & REHABILITATION CENTER	WATHENA
175218	WESTVIEW OF DERBY	DERBY
175218	WESTVIEW OF DERBY	DERBY

KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	03/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	03/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	03/11/2010	04/11/2010	Fire Safety
KS	02/04/2010	03/05/2010	Fire Safety
KS	02/04/2010	03/05/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	a separate and independent backup electrical power source.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175218	WESTVIEW OF DERBY	DERBY
175218	WESTVIEW OF DERBY	DERBY
175218	WESTVIEW OF DERBY	DERBY
175218	WESTVIEW OF DERBY	DERBY
175218	WESTVIEW OF DERBY	DERBY
175218	WESTVIEW OF DERBY	DERBY
175218	WESTVIEW OF DERBY	DERBY
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE

sumner regional medical center

Based on VSDA2

KS	02/04/2010	03/05/2010	Fire Safety
KS	06/03/2010	06/03/2010	Fire Safety
KS	06/03/2010	06/03/2010	Fire Safety
KS	06/03/2010	06/18/2010	Fire Safety
KS	11/10/2010	12/08/2010	Fire Safety
KS	11/10/2010	12/08/2010	Fire Safety
KS	11/10/2010	12/08/2010	Fire Safety
KS	05/08/2007	06/07/2007	Fire Safety

	order.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE

sumner regional medical center

Based on VSDA2

KS	05/08/2007	06/07/2007	Fire Safety
KS	05/08/2007	06/07/2007	Fire Safety
KS	05/08/2007	06/07/2007	Fire Safety
KS	05/08/2007	06/07/2007	Fire Safety
KS	05/08/2007	06/07/2007	Fire Safety
KS	05/08/2007	06/07/2007	Fire Safety
KS	08/05/2008	08/31/2008	Fire Safety
KS	08/05/2008	08/31/2008	Fire Safety
KS	08/05/2008	08/31/2008	Fire Safety
KS	08/05/2008	08/31/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE

sumner regional medical center

Based on VSDA2

KS	08/05/2008	08/31/2008	Fire Safety
KS	08/05/2008	08/31/2008	Fire Safety
KS	08/05/2008	08/31/2008	Fire Safety
KS	08/05/2008	08/31/2008	Fire Safety
KS	10/05/2009	11/01/2009	Fire Safety
KS	10/05/2009	11/01/2009	Fire Safety
KS	10/05/2009	11/01/2009	Fire Safety
KS	10/05/2009	11/01/2009	Fire Safety
KS	10/05/2009	11/01/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175219	GOLDEN LIVINGCENTER - KAW RIVER	EDWARDSVILLE
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA

sumner regional medical center

Based on VSDA2

KS	10/05/2009	11/01/2009	Fire Safety
KS	10/05/2009	11/01/2009	Fire Safety
KS	10/05/2009	11/01/2009	Fire Safety
KS	10/05/2009	10/05/2009	Fire Safety
KS	10/05/2009	11/01/2009	Fire Safety
KS	10/05/2009	11/01/2009	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	no-smoking signs where oxygen is used.	Widespread
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA

sumner regional medical center

Based on VSDA2

KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175220	DESERET NURSING & REHABILITATION AT	ONAGA

KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	06/01/2009	06/10/2009	Fire Safety
KS	06/01/2009	06/08/2009	Fire Safety
KS	06/01/2009	07/01/2009	Fire Safety
KS	06/01/2009	07/01/2009	Fire Safety
KS	06/01/2009	07/01/2009	Fire Safety
KS	06/01/2009	07/01/2009	Fire Safety
KS	06/01/2009	07/01/2009	Fire Safety
KS	06/01/2009	07/01/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

	ONAGA	
175220	DESERET NURSING & REHABILITATION AT ONAGA	ONAGA
175221	LAKEPOINT NURSING & REHAB CENTER OF ROSE HILL	ROSE HILL
175221	LAKEPOINT NURSING & REHAB CENTER OF ROSE HILL	ROSE HILL
175221	LAKEPOINT NURSING & REHAB CENTER OF ROSE HILL	ROSE HILL
175221	LAKEPOINT NURSING & REHAB CENTER OF ROSE HILL	ROSE HILL
175221	LAKEPOINT NURSING & REHAB CENTER OF ROSE HILL	ROSE HILL
175221	LAKEPOINT NURSING & REHAB CENTER OF ROSE HILL	ROSE HILL
175221	LAKEPOINT NURSING & REHAB CENTER OF ROSE HILL	ROSE HILL
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS

sumner regional medical center

Based on VSDA2

KS	06/01/2009	06/09/2009	Fire Safety
KS	06/12/2008	07/10/2008	Fire Safety
KS	07/07/2009	07/20/2009	Fire Safety
KS	07/07/2009	07/20/2009	Fire Safety
KS	07/07/2009	07/20/2009	Fire Safety
KS	07/07/2009	07/20/2009	Fire Safety
KS	08/12/2010	09/11/2010	Fire Safety
KS	08/12/2010	09/10/2010	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS

KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	11/07/2007	Fire Safety
KS	11/01/2007	11/06/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	12/11/2008	12/19/2008	Fire Safety
KS	12/11/2008	12/16/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175223	GOLDEN LIVINGCENTER - CHASE COUNTY	COTTONWOOD FALLS
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN

sumner regional medical center

Based on VSDA2

KS	12/11/2008	12/16/2008	Fire Safety
KS	12/11/2008	12/16/2008	Fire Safety
KS	12/11/2008	12/16/2008	Fire Safety
KS	12/11/2008	12/16/2008	Fire Safety
KS	12/11/2008	12/19/2008	Fire Safety
KS	12/11/2008	12/19/2008	Fire Safety
KS	01/28/2010	01/31/2010	Fire Safety
KS	04/14/2008	05/13/2008	Fire Safety
KS	04/14/2008	05/13/2008	Fire Safety

	would resist fire for at least one hour.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Interior Finish Deficiencies	fire-resistant interior walls.	Widespread
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN

sumner regional medical center

Based on VSDA2

KS	04/14/2008	05/13/2008	Fire Safety
KS	04/14/2008	05/13/2008	Fire Safety
KS	04/14/2008	05/13/2008	Fire Safety
KS	04/14/2008	05/13/2008	Fire Safety
KS	04/14/2008	05/13/2008	Fire Safety
KS	04/14/2009	05/13/2009	Fire Safety
KS	04/14/2009	05/13/2009	Fire Safety
KS	04/14/2009	05/13/2009	Fire Safety
KS	04/14/2009	05/13/2009	Fire Safety
KS	04/14/2009	05/13/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175224	MORAN MANOR	MORAN
175226	WINDSOR PLACE AT IOLA LLC	IOLA
175226	WINDSOR PLACE AT IOLA LLC	IOLA
175226	WINDSOR PLACE AT IOLA LLC	IOLA
175226	WINDSOR PLACE AT IOLA LLC	IOLA

KS	04/14/2009	05/13/2009	Fire Safety
KS	04/14/2009	05/13/2009	Fire Safety
KS	04/14/2009	05/13/2009	Fire Safety
KS	04/14/2009	05/13/2009	Fire Safety
KS	06/10/2008	06/11/2008	Fire Safety
KS	06/10/2008	06/10/2008	Fire Safety
KS	06/10/2008	06/20/2008	Fire Safety
KS	06/10/2008	06/13/2008	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

175226	WINDSOR PLACE AT IOLA LLC	IOLA
175226	WINDSOR PLACE AT IOLA LLC	IOLA
175226	WINDSOR PLACE AT IOLA LLC	IOLA
175226	WINDSOR PLACE AT IOLA LLC	IOLA
175226	WINDSOR PLACE AT IOLA LLC	IOLA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA

sumner regional medical center

Based on VSDA2

KS			Fire Safety
KS	07/21/2009	08/01/2009	Fire Safety
KS	07/21/2009	08/01/2009	Fire Safety
KS	07/21/2009	08/05/2009	Fire Safety
KS	07/21/2009	07/23/2009	Fire Safety
KS	10/23/2007	11/22/2007	Fire Safety
KS	10/23/2007	10/29/2007	Fire Safety
KS	10/23/2007	11/23/2007	Fire Safety
KS	10/23/2007	11/23/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA

sumner regional medical center

Based on VSDA2

KS	10/23/2007	11/23/2007	Fire Safety
KS	10/23/2007	11/23/2007	Fire Safety
KS	10/23/2007	10/31/2007	Fire Safety
KS	09/12/2008	09/30/2008	Fire Safety
KS	09/12/2008	09/30/2008	Fire Safety
KS	09/12/2008	09/30/2008	Fire Safety
KS	09/12/2008	09/30/2008	Fire Safety
KS	09/12/2008	09/30/2008	Fire Safety
KS	11/05/2009	11/05/2009	Fire Safety

	have been maintained in working order.	
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175227	GOLDEN LIVINGCENTER - FREDONIA	FREDONIA
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING

sumner regional medical center

Based on VSDA2

KS	11/05/2009	11/10/2009	Fire Safety
KS	04/17/2008	04/21/2008	Fire Safety
KS	04/17/2008	05/16/2008	Fire Safety
KS	04/17/2008	04/21/2008	Fire Safety
KS	04/17/2008	04/28/2008	Fire Safety
KS	04/17/2008	05/01/2008	Fire Safety
KS	04/17/2008	04/24/2008	Fire Safety
KS	04/17/2008	04/25/2008	Fire Safety
KS	06/08/2009	07/01/2009	Fire Safety
KS	06/08/2009	07/01/2009	Fire Safety

	ashtrays where smoking was allowed.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that	Widespread

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING

sumner regional medical center

Based on VSDA2

KS	06/08/2009	07/01/2009	Fire Safety
KS	06/08/2009	06/08/2009	Fire Safety
KS	06/08/2009	07/01/2009	Fire Safety
KS	06/08/2009	06/08/2009	Fire Safety
KS	06/08/2009	07/01/2009	Fire Safety
KS	06/08/2009	07/01/2009	Fire Safety
KS	06/08/2009	06/08/2009	Fire Safety
KS	06/08/2009	06/08/2009	Fire Safety
KS	06/08/2009	07/01/2009	Fire Safety
KS	06/08/2009	07/01/2009	Fire Safety
KS	11/15/2010	11/15/2010	Fire Safety

	block smoke.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175228	GOLDEN LIVINGCENTER - LANSING	LANSING
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE

sumner regional medical center

Based on VSDA2

KS	11/15/2010	11/19/2010	Fire Safety
KS	11/15/2010	11/19/2010	Fire Safety
KS	11/15/2010	11/15/2010	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE

sumner regional medical center

Based on VSDA2

KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	09/11/2007	10/11/2007	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	12/12/2008	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	12/16/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175229	GOLDEN LIVINGCENTER - PARKWAY	EDWARDSVILLE
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH

sumner regional medical center

Based on VSDA2

KS	01/20/2010	02/19/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	10/09/2007	10/17/2007	Fire Safety

	testing of generators.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH	ELLSWORTH

sumner regional medical center

Based on VSDA2

KS	10/09/2007	10/17/2007	Fire Safety
KS	10/09/2007	10/16/2007	Fire Safety
KS	10/09/2007	10/17/2007	Fire Safety
KS	10/09/2007	10/17/2007	Fire Safety
KS	10/09/2007	10/17/2007	Fire Safety
KS	10/09/2007	10/17/2007	Fire Safety
KS	10/09/2007	10/17/2007	Fire Safety
KS	10/09/2007	10/17/2007	Fire Safety
KS	10/09/2007	10/17/2007	Fire Safety
KS	10/09/2007	10/17/2007	Fire Safety

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175231	GOOD SAMARITAN SOCIETY - ELLSWORTH VILLAGE	ELLSWORTH
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN

sumner regional medical center

Based on VSDA2

KS			Fire Safety
KS	10/09/2007	12/28/2007	Fire Safety
KS	10/14/2008	10/14/2008	Fire Safety
KS	10/14/2008	10/24/2008	Fire Safety
KS	10/26/2009	11/20/2009	Fire Safety
KS	10/26/2009	11/20/2009	Fire Safety
KS	07/07/2008	07/08/2008	Fire Safety
KS	07/07/2008	07/09/2008	Fire Safety
KS	07/07/2008	07/07/2008	Fire Safety
KS	07/07/2008	07/11/2008	Fire Safety
KS	07/07/2008	07/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Potential for minimal harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN

sumner regional medical center

Based on VSDA2

KS	07/07/2008	07/10/2008	Fire Safety
KS	07/07/2008	07/30/2008	Fire Safety
KS	07/07/2008	07/30/2008	Fire Safety
KS	07/07/2008	07/30/2008	Fire Safety
KS	07/10/2009	07/15/2009	Fire Safety
KS	07/10/2009	07/30/2009	Fire Safety
KS	07/10/2009	07/17/2009	Fire Safety
KS	07/10/2009	07/14/2009	Fire Safety
KS	07/10/2009	07/10/2009	Fire Safety
KS	07/10/2009	07/24/2009	Fire Safety

	each shift under varying conditions.	
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175232	PLEASANT VALLEY MANOR	SEDAN
175232	PLEASANT VALLEY MANOR	SEDAN
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA

sumner regional medical center

Based on VSDA2

KS	09/13/2010	09/13/2010	Fire Safety
KS	09/13/2010	09/13/2010	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA

KS	10/08/2007	11/06/2007	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety
KS	10/08/2007	11/06/2007	Fire Safety
KS	09/18/2008	10/18/2008	Fire Safety
KS	09/18/2008	10/18/2008	Fire Safety
KS	09/18/2008	10/18/2008	Fire Safety
KS	09/18/2008	10/18/2008	Fire Safety
KS	09/18/2008	10/18/2008	Fire Safety

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA

sumner regional medical center

Based on VSDA2

KS	09/15/2009	10/14/2009	Fire Safety
KS	09/15/2009	09/22/2009	Fire Safety
KS	09/15/2009	09/25/2009	Fire Safety
KS	09/15/2009	09/30/2009	Fire Safety
KS	09/15/2009	09/23/2009	Fire Safety
KS	09/15/2009	09/22/2009	Fire Safety
KS	09/15/2009	09/22/2009	Fire Safety
KS	09/15/2009	10/14/2009	Fire Safety
KS	09/15/2009	09/22/2009	Fire Safety

	ashtrays where smoking was allowed.	
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175233	GALENA NURSING & REHAB CENTER	GALENA
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED

sumner regional medical center

Based on VSDA2

KS	09/15/2009	10/14/2009	Fire Safety
KS	09/15/2009	09/16/2009	Fire Safety
KS	09/15/2009	09/25/2009	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED

sumner regional medical center

Based on VSDA2

KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	03/19/2008	04/18/2008	Fire Safety
KS	04/06/2009	05/05/2009	Fire Safety
KS	04/06/2009	05/05/2009	Fire Safety
KS	04/06/2009	05/05/2009	Fire Safety
KS	04/06/2009	05/05/2009	Fire Safety
KS	04/06/2009	05/05/2009	Fire Safety
KS	04/06/2009	05/05/2009	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175235	LARNED HEALTHCARE CENTER	LARNED
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON

sumner regional medical center

Based on VSDA2

KS	04/06/2009	05/05/2009	Fire Safety
KS	04/06/2009	05/05/2009	Fire Safety
KS	04/06/2009	05/05/2009	Fire Safety
KS	05/05/2010	05/05/2010	Fire Safety
KS	05/05/2010	05/06/2010	Fire Safety
KS	05/05/2010	05/12/2010	Fire Safety
KS	05/05/2010	05/11/2010	Fire Safety
KS	09/12/2007	10/12/2007	Fire Safety
KS	09/12/2007	10/12/2007	Fire Safety
KS	09/12/2007	10/12/2007	Fire Safety

	detectors.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON

sumner regional medical center

Based on VSDA2

KS	09/12/2007	10/12/2007	Fire Safety
KS	09/12/2007	10/12/2007	Fire Safety
KS	09/12/2007	10/12/2007	Fire Safety
KS	09/12/2007	10/12/2007	Fire Safety
KS	09/12/2007	10/12/2007	Fire Safety
KS	09/12/2007	10/12/2007	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON

KS	07/03/2008	08/03/2008	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety
KS	07/03/2008	08/03/2008	Fire Safety
KS	09/24/2009	10/24/2009	Fire Safety
KS	09/24/2009	10/24/2009	Fire Safety
KS	09/24/2009	10/24/2009	Fire Safety
KS	09/24/2009	10/24/2009	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175236	HUTCHINSON CARE CENTER LLC	HUTCHINSON
175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE
175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE
175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE
175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE
175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE
175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE

KS	09/24/2009	10/24/2009	Fire Safety
KS	09/24/2009	10/24/2009	Fire Safety
KS	09/24/2009	10/24/2009	Fire Safety
KS	09/24/2009	10/24/2009	Fire Safety
KS	04/30/2008	05/15/2008	Fire Safety
KS	04/30/2008	05/15/2008	Fire Safety
KS	04/30/2008	05/15/2008	Fire Safety
KS	04/30/2008	05/15/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	06/25/2009	06/26/2009	Fire Safety

	at least 1 1/2 hours.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE
175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE
175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE
175237	MEDICALODGES COFFEYVILLE	COFFEYVILLE
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG

sumner regional medical center

Based on VSDA2

KS	06/25/2009	07/01/2009	Fire Safety
KS	07/27/2010	08/25/2010	Fire Safety
KS	07/27/2010	07/30/2010	Fire Safety
KS	07/27/2010	07/27/2010	Fire Safety
KS	08/24/2007	09/14/2007	Fire Safety
KS	08/24/2007	09/29/2007	Fire Safety
KS	08/24/2007	08/31/2007	Fire Safety
KS	08/24/2007	09/14/2007	Fire Safety
KS	08/24/2007	09/21/2007	Fire Safety
KS	08/24/2007	08/29/2007	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG

KS	08/24/2007	08/30/2007	Fire Safety
KS	08/24/2007	08/30/2007	Fire Safety
KS	08/24/2007	09/07/2007	Fire Safety
KS	08/24/2007	09/14/2007	Fire Safety
KS	08/24/2007	08/29/2007	Fire Safety
KS	08/24/2007	08/31/2007	Fire Safety
KS	08/07/2008	08/20/2008	Fire Safety
KS	08/07/2008	08/15/2008	Fire Safety
KS	08/07/2008	08/08/2008	Fire Safety
KS	08/07/2008	08/14/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG

sumner regional medical center

Based on VSDA2

KS	08/07/2008	08/20/2008	Fire Safety
KS	08/07/2008	08/07/2008	Fire Safety
KS	08/07/2008	08/15/2008	Fire Safety
KS	08/07/2008	08/15/2008	Fire Safety
KS	08/07/2008	08/13/2008	Fire Safety
KS	08/07/2008	08/12/2008	Fire Safety
KS	09/28/2009	10/12/2009	Fire Safety
KS	09/28/2009	10/16/2009	Fire Safety
KS	09/28/2009	10/16/2009	Fire Safety
KS	09/28/2009	09/28/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Immediate jeopardy to resident health or safety
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175238	LOUISBURG HEALTHCARE & REHAB CTR	LOUISBURG
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE

sumner regional medical center

Based on VSDA2

KS	09/28/2009	09/28/2009	Fire Safety
KS	09/28/2009	10/01/2009	Fire Safety
KS	05/23/2008	05/23/2008	Fire Safety
KS	05/23/2008	05/27/2008	Fire Safety
KS	05/23/2008	05/27/2008	Fire Safety
KS	05/23/2008	05/23/2008	Fire Safety
KS	05/23/2008	05/30/2008	Fire Safety
KS	05/23/2008	06/06/2008	Fire Safety
KS	05/23/2008	06/13/2008	Fire Safety

	obstructions and can be used at all times.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE

sumner regional medical center

Based on VSDA2

KS	05/23/2008	05/28/2008	Fire Safety
KS	06/05/2009	06/10/2009	Fire Safety
KS	06/05/2009	06/10/2009	Fire Safety
KS	06/05/2009	06/11/2009	Fire Safety
KS	06/05/2009	06/12/2009	Fire Safety
KS	06/05/2009	06/12/2009	Fire Safety
KS	06/05/2009	06/11/2009	Fire Safety
KS	06/11/2010	06/15/2010	Fire Safety
KS	06/11/2010	06/25/2010	Fire Safety
KS	06/11/2010	06/17/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175239	COUNCIL GROVE HEALTHCARE CENTER	COUNCIL GROVE
175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK
175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK
175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK
175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	06/11/2010	07/09/2010	Fire Safety
KS	06/11/2010	06/18/2010	Fire Safety
KS	06/11/2010	06/25/2010	Fire Safety
KS	06/11/2010	06/17/2010	Fire Safety
KS	06/11/2010	06/25/2010	Fire Safety
KS	06/11/2010	06/22/2010	Fire Safety
KS	06/11/2010	06/15/2010	Fire Safety
KS	08/12/2008	09/10/2008	Fire Safety
KS	08/12/2008	09/10/2008	Fire Safety
KS	08/12/2008	09/10/2008	Fire Safety
KS	08/12/2008	09/10/2008	Fire Safety

	hour.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK
175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK
175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK
175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK
175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK
175240	SPECIALTY HOSPITAL OF MID-AMERICA SNF	OVERLAND PARK
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA

sumner regional medical center

Based on VSDA2

KS	07/16/2009	07/16/2009	Fire Safety
KS	07/16/2009	07/16/2009	Fire Safety
KS	07/16/2009	07/16/2009	Fire Safety
KS	07/16/2009	08/14/2009	Fire Safety
KS	07/16/2009	08/14/2009	Fire Safety
KS	08/30/2010	09/23/2010	Fire Safety
KS	01/14/2008	01/14/2008	Fire Safety
KS	01/14/2008	02/08/2008	Fire Safety
KS	01/14/2008	01/19/2008	Fire Safety
KS	01/14/2008	01/19/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA

sumner regional medical center

Based on VSDA2

KS	01/14/2008	02/08/2008	Fire Safety
KS	01/14/2008	01/18/2008	Fire Safety
KS	01/14/2008	02/08/2008	Fire Safety
KS	01/14/2008	01/14/2008	Fire Safety
KS	02/04/2009	02/28/2009	Fire Safety
KS	02/04/2009	02/05/2009	Fire Safety
KS	02/04/2009	02/28/2009	Fire Safety
KS	02/04/2009	02/28/2009	Fire Safety
KS	02/04/2009	02/28/2009	Fire Safety
KS	02/04/2009	02/28/2009	Fire Safety
KS	02/04/2009	02/05/2009	Fire Safety

	order.	
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA
175241	SABETHA MANOR	SABETHA

sumner regional medical center

Based on VSDA2

KS	02/04/2009	02/04/2009	Fire Safety
KS	04/27/2010	05/26/2010	Fire Safety
KS	04/27/2010	05/26/2010	Fire Safety
KS	04/27/2010	05/26/2010	Fire Safety
KS	04/27/2010	05/05/2010	Fire Safety
KS	04/27/2010	05/26/2010	Fire Safety
KS	04/27/2010	05/26/2010	Fire Safety
KS	04/27/2010	05/26/2010	Fire Safety

	and equipment.	
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA

sumner regional medical center

Based on VSDA2

KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	11/01/2007	12/01/2007	Fire Safety
KS	02/10/2009	02/11/2009	Fire Safety
KS	02/10/2009	02/11/2009	Fire Safety
KS	02/10/2009	03/12/2009	Fire Safety
KS	02/10/2009	03/12/2009	Fire Safety

	testing of generators.	
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Vertical Openings Deficiencies	protected exits that allow the	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175242	LAKEVIEW VILLAGE	LENEXA
175243	MEDICALODGES GARDNER	GARDNER
175243	MEDICALODGES GARDNER	GARDNER
175243	MEDICALODGES GARDNER	GARDNER
175243	MEDICALODGES GARDNER	GARDNER

sumner regional medical center

Based on VSDA2

KS	02/10/2009	03/12/2009	Fire Safety
KS	02/10/2009	03/12/2009	Fire Safety
KS	02/10/2009	03/12/2009	Fire Safety
KS	04/20/2010	04/23/2010	Fire Safety
KS	04/20/2010	04/23/2010	Fire Safety
KS	04/20/2010	04/27/2010	Fire Safety
KS	11/14/2007	11/15/2007	Fire Safety
KS	11/14/2007	11/14/2007	Fire Safety
KS	11/14/2007	11/14/2007	Fire Safety
KS	11/14/2007	11/14/2007	Fire Safety

sumner regional medical center

Based on VSDA2

	resident to escape the building.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175243	MEDICALODGES GARDNER	GARDNER
175243	MEDICALODGES GARDNER	GARDNER
175243	MEDICALODGES GARDNER	GARDNER
175243	MEDICALODGES GARDNER	GARDNER
175243	MEDICALODGES GARDNER	GARDNER
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE

sumner regional medical center

Based on VSDA2

KS	11/14/2007	11/16/2007	Fire Safety
KS	02/09/2009	02/10/2009	Fire Safety
KS	02/09/2009	02/11/2009	Fire Safety
KS	02/09/2009	02/11/2009	Fire Safety
KS	02/09/2009	02/12/2009	Fire Safety
KS	04/03/2008	04/12/2008	Fire Safety
KS	04/03/2008	04/04/2008	Fire Safety
KS	04/03/2008	04/11/2008	Fire Safety
KS	04/03/2008	04/11/2008	Fire Safety
KS	04/03/2008	04/18/2008	Fire Safety

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE
175244	MEMORIAL HOSPITAL LTCU (VILLAGE MANOR)	ABILENE

sumner regional medical center

Based on VSDA2

KS	04/03/2008	04/11/2008	Fire Safety
KS	04/03/2008	04/04/2008	Fire Safety
KS	04/03/2008	04/30/2008	Fire Safety
KS	05/19/2009	05/20/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	05/22/2009	Fire Safety
KS	05/19/2009	05/19/2009	Fire Safety
KS	05/19/2009	05/21/2009	Fire Safety
KS	05/19/2009	05/22/2009	Fire Safety
KS	06/03/2010	06/03/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE

KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety

	order.	
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in	Widespread

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Potential for minimal harm

sumner regional medical center

Based on VSDA2

175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE

sumner regional medical center

Based on VSDA2

KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	11/15/2007	12/15/2007	Fire Safety
KS	01/29/2009	02/20/2009	Fire Safety
KS	01/29/2009	02/20/2009	Fire Safety
KS	01/29/2009	02/20/2009	Fire Safety
KS	03/31/2010	04/28/2010	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Laboratories Deficiencies	proper facilities for the use and storage of combustible liquids.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE

sumner regional medical center

Based on VSDA2

KS	03/31/2010	04/28/2010	Fire Safety
KS	03/31/2010	04/28/2010	Fire Safety
KS	03/31/2010	04/28/2010	Fire Safety
KS	03/31/2010	04/28/2010	Fire Safety
KS	03/31/2010	04/28/2010	Fire Safety
KS	03/31/2010	04/28/2010	Fire Safety
KS	03/31/2010	04/28/2010	Fire Safety
KS	03/31/2010	04/28/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175245	GOLDEN LIVINGCENTER - EDWARDSVILLE	EDWARDSVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE

sumner regional medical center

Based on VSDA2

KS	03/31/2010	04/28/2010	Fire Safety
KS	03/31/2010	04/28/2010	Fire Safety
KS	05/29/2008	06/25/2008	Fire Safety
KS	05/29/2008	06/25/2008	Fire Safety
KS	05/29/2008	06/25/2008	Fire Safety
KS	05/29/2008	06/25/2008	Fire Safety
KS	05/29/2008	06/25/2008	Fire Safety
KS	05/29/2008	06/25/2008	Fire Safety
KS	05/29/2008	06/25/2008	Fire Safety
KS	05/29/2008	06/25/2008	Fire Safety

	that have been properly installed according to the manufacturer's instructions.	
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Isolated
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE

sumner regional medical center

Based on VSDA2

KS	05/29/2008	06/25/2008	Fire Safety
KS	05/29/2008	06/25/2008	Fire Safety
KS	07/28/2009	08/26/2009	Fire Safety
KS	07/28/2009	08/26/2009	Fire Safety
KS	07/28/2009	08/26/2009	Fire Safety
KS	07/28/2009	08/26/2009	Fire Safety
KS	07/28/2009	08/26/2009	Fire Safety
KS	07/28/2009	08/26/2009	Fire Safety
KS	07/15/2010	08/12/2010	Fire Safety
KS	07/15/2010	08/12/2010	Fire Safety
KS	07/15/2010	07/30/2010	Fire Safety
KS	07/15/2010	08/12/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175246	BELLEVILLE HEALTH CARE CENTER	BELLEVILLE
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT	KENSINGTON

sumner regional medical center

Based on VSDA2

KS	07/15/2010	08/12/2010	Fire Safety
KS	07/15/2010	08/12/2010	Fire Safety
KS	05/09/2008	05/16/2008	Fire Safety
KS	05/09/2008	05/16/2008	Fire Safety
KS	05/09/2008	05/18/2008	Fire Safety
KS	05/09/2008	05/18/2008	Fire Safety
KS	05/09/2008	05/18/2008	Fire Safety
KS	05/09/2008	05/18/2008	Fire Safety
KS	05/09/2008	05/18/2008	Fire Safety
KS	05/09/2008	05/18/2008	Fire Safety
KS	05/06/2009	06/06/2009	Fire Safety

	for fire alarm systems.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Electrical Deficiencies	a separate and independent backup electrical power source.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	KENSINGTON	
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON
175248	DESERET NURSING & REHABILITATION AT KENSINGTON	KENSINGTON

sumner regional medical center

Based on VSDA2

KS	05/06/2009	06/06/2009	Fire Safety
KS	05/06/2009	06/06/2009	Fire Safety
KS	05/06/2009	06/06/2009	Fire Safety
KS	05/06/2009	06/06/2009	Fire Safety
KS	05/06/2009	06/06/2009	Fire Safety
KS	05/06/2009	06/06/2009	Fire Safety
KS	05/06/2009	06/06/2009	Fire Safety
KS	05/06/2009	06/06/2009	Fire Safety
KS	05/06/2009	06/06/2009	Fire Safety
KS	07/08/2010	07/10/2010	Fire Safety

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE

sumner regional medical center

Based on VSDA2

KS	11/27/2007	12/12/2007	Fire Safety
KS	11/27/2007	12/12/2007	Fire Safety
KS	11/27/2007	12/12/2007	Fire Safety
KS	11/27/2007	12/12/2007	Fire Safety
KS	11/27/2007	12/12/2007	Fire Safety
KS	11/27/2007	12/12/2007	Fire Safety
KS	11/27/2007	12/12/2007	Fire Safety
KS	11/27/2007	12/12/2007	Fire Safety
KS	11/27/2007	12/12/2007	Fire Safety
KS	12/11/2008	12/11/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE
175249	HERITAGE HEALTH CARE CENTER	CHANUTE

sumner regional medical center

Based on VSDA2

KS	12/11/2008	12/18/2008	Fire Safety
KS	12/11/2008	12/11/2008	Fire Safety
KS	12/11/2008	12/18/2008	Fire Safety
KS	12/11/2008	12/18/2008	Fire Safety
KS	12/02/2009	12/14/2009	Fire Safety
KS	12/02/2009	12/14/2009	Fire Safety
KS	12/02/2009	12/14/2009	Fire Safety
KS	12/02/2009	12/14/2009	Fire Safety
KS	12/02/2009	12/14/2009	Fire Safety
KS	12/02/2009	12/14/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE

KS	05/09/2008	06/08/2008	Fire Safety
KS	05/09/2008	06/08/2008	Fire Safety
KS	05/09/2008	06/08/2008	Fire Safety
KS	05/09/2008	06/08/2008	Fire Safety
KS	05/09/2008	06/08/2008	Fire Safety
KS	05/09/2008	06/08/2008	Fire Safety
KS	05/09/2008	06/08/2008	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE

sumner regional medical center

Based on VSDA2

KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety
KS	05/15/2009	06/15/2009	Fire Safety

	hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175250	WELLSVILLE MANOR	WELLSVILLE
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA

sumner regional medical center

Based on VSDA2

KS	06/10/2010	06/11/2010	Fire Safety
KS	06/10/2010	06/11/2010	Fire Safety
KS	06/10/2010	06/11/2010	Fire Safety
KS	06/10/2010	06/11/2010	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety

	and equipment.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA

sumner regional medical center

Based on VSDA2

KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	12/04/2007	01/04/2008	Fire Safety
KS	11/20/2008	12/18/2008	Fire Safety
KS	11/20/2008	12/18/2008	Fire Safety

	hour.	
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175253	LAKEWOOD SENIOR LIVING OF SEVILLE	WICHITA
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK

sumner regional medical center

Based on VSDA2

KS	11/20/2008	12/18/2008	Fire Safety
KS	11/20/2008	12/18/2008	Fire Safety
KS	11/20/2008	12/18/2008	Fire Safety
KS	11/20/2008	12/18/2008	Fire Safety
KS	01/28/2010	02/19/2010	Fire Safety
KS	06/03/2008	06/06/2008	Fire Safety
KS	06/03/2008	06/06/2008	Fire Safety
KS	06/03/2008	06/06/2008	Fire Safety
KS	06/03/2008	06/06/2008	Fire Safety

	would resist fire for at least one hour.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK

sumner regional medical center

Based on VSDA2

KS	06/03/2008	06/06/2008	Fire Safety
KS	06/03/2008	06/06/2008	Fire Safety
KS	06/03/2008	06/06/2008	Fire Safety
KS	06/03/2008	06/06/2008	Fire Safety
KS	06/03/2008	06/06/2008	Fire Safety
KS	06/03/2008	06/26/2008	Fire Safety
KS	06/03/2008	06/06/2008	Fire Safety
KS	07/23/2009	07/23/2009	Fire Safety
KS	07/23/2009	07/28/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175254	SEDGWICK HEALTHCARE CENTER	SEDGWICK
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	07/23/2009	08/17/2009	Fire Safety
KS	07/23/2009	07/28/2009	Fire Safety
KS	07/23/2009	07/23/2009	Fire Safety
KS	08/23/2010	08/23/2010	Fire Safety
KS	09/05/2008	09/23/2008	Fire Safety
KS	09/05/2008	09/23/2008	Fire Safety
KS	09/05/2008	09/23/2008	Fire Safety
KS	09/05/2008	09/23/2008	Fire Safety
KS	09/05/2008	09/23/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175255	PLAZA WEST REGIONAL HEALTH CENTER	TOPEKA
175256	OSAGE NURSING & REHABILITATION	OSAGE CITY

sumner regional medical center

Based on VSDA2

KS	09/05/2008	09/23/2008	Fire Safety
KS	09/05/2008	09/23/2008	Fire Safety
KS	09/05/2008	09/23/2008	Fire Safety
KS	12/01/2009	12/30/2009	Fire Safety
KS	12/01/2009	12/30/2009	Fire Safety
KS	12/01/2009	12/30/2009	Fire Safety
KS	12/01/2009	12/30/2009	Fire Safety
KS	12/01/2009	12/30/2009	Fire Safety
KS	12/01/2009	12/30/2009	Fire Safety
KS	01/19/2011	01/28/2011	Fire Safety
KS	03/24/2008	04/22/2008	Fire Safety

Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	CENTER	
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION	OSAGE CITY

sumner regional medical center

Based on VSDA2

KS	03/24/2008	04/22/2008	Fire Safety
KS	03/24/2008	04/22/2008	Fire Safety
KS	03/24/2008	04/22/2008	Fire Safety
KS	03/24/2008	04/22/2008	Fire Safety
KS	06/12/2009	07/11/2009	Fire Safety
KS	06/12/2009	07/11/2009	Fire Safety
KS	06/12/2009	07/11/2009	Fire Safety
KS	06/12/2009	07/11/2009	Fire Safety
KS	06/12/2009	07/11/2009	Fire Safety
KS	06/12/2009	07/11/2009	Fire Safety
KS	06/12/2009	07/11/2009	Fire Safety

	times.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	CENTER	
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175256	OSAGE NURSING & REHABILITATION CENTER	OSAGE CITY
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE

sumner regional medical center

Based on VSDA2

KS	06/12/2009	07/11/2009	Fire Safety
KS	06/12/2009	07/11/2009	Fire Safety
KS	07/29/2010	08/03/2010	Fire Safety
KS	04/14/2008	04/21/2008	Fire Safety
KS	04/14/2008	04/18/2008	Fire Safety
KS	04/14/2008	04/15/2008	Fire Safety
KS	04/14/2008	04/18/2008	Fire Safety
KS	04/14/2008	04/21/2008	Fire Safety

	have been maintained in working order.	
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE

sumner regional medical center

Based on VSDA2

KS	04/14/2008	04/18/2008	Fire Safety
KS	04/14/2008	05/14/2008	Fire Safety
KS	04/14/2008	04/18/2008	Fire Safety
KS	04/14/2008	04/18/2008	Fire Safety
KS	04/14/2008	04/18/2008	Fire Safety
KS	04/14/2008	04/21/2008	Fire Safety
KS	04/14/2008	05/14/2008	Fire Safety
KS	04/14/2008	05/14/2008	Fire Safety
KS	04/14/2008	05/14/2008	Fire Safety
KS	04/14/2008	04/21/2008	Fire Safety
KS	07/10/2009	08/07/2009	Fire Safety

	for fire alarm systems.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE

KS	07/10/2009	08/07/2009	Fire Safety
KS	07/10/2009	08/07/2009	Fire Safety
KS	07/10/2009	08/07/2009	Fire Safety
KS	07/10/2009	08/07/2009	Fire Safety
KS	07/10/2009	08/07/2009	Fire Safety
KS	07/10/2009	08/07/2009	Fire Safety
KS	07/10/2009	08/07/2009	Fire Safety
KS	07/10/2009	08/07/2009	Fire Safety
KS	07/10/2009	08/07/2009	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175257	SHARON LANE HEALTH SERVICES	SHAWNEE
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT

sumner regional medical center

Based on VSDA2

KS	07/10/2009	08/07/2009	Fire Safety
KS	08/27/2010	09/24/2010	Fire Safety
KS	08/27/2010	09/24/2010	Fire Safety
KS	08/27/2010	09/24/2010	Fire Safety
KS	08/27/2010	09/24/2010	Fire Safety
KS	02/27/2008	03/27/2008	Fire Safety
KS	02/27/2008	02/27/2008	Fire Safety
KS	02/27/2008	03/27/2008	Fire Safety
KS	02/27/2008	03/27/2008	Fire Safety
KS	02/27/2008	03/27/2008	Fire Safety

	smoke passage.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT

sumner regional medical center

Based on VSDA2

KS	02/27/2008	03/27/2008	Fire Safety
KS	02/27/2008	03/27/2008	Fire Safety
KS	02/19/2009	03/19/2009	Fire Safety
KS	02/19/2009	03/19/2009	Fire Safety
KS	02/19/2009	03/19/2009	Fire Safety
KS	02/19/2009	03/19/2009	Fire Safety
KS	02/19/2009	03/19/2009	Fire Safety
KS	03/15/2010	03/15/2010	Fire Safety
KS	03/15/2010	03/16/2010	Fire Safety
KS	03/15/2010	04/13/2010	Fire Safety

	order.	
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175258	MEDICALODGES FORT SCOTT	FORT SCOTT
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON

sumner regional medical center

Based on VSDA2

KS	03/15/2010	04/13/2010	Fire Safety
KS	03/15/2010	03/15/2010	Fire Safety
KS	04/22/2008	04/30/2008	Fire Safety
KS	04/22/2008	04/30/2008	Fire Safety
KS	04/22/2008	04/30/2008	Fire Safety
KS	04/22/2008	05/15/2008	Fire Safety
KS	04/22/2008	04/24/2008	Fire Safety
KS	04/22/2008	05/15/2008	Fire Safety
KS	04/22/2008	04/30/2008	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175260	GOOD SAMARITAN SOCIETY - HUTCHINSON VILLAGE	HUTCHINSON
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE

sumner regional medical center

Based on VSDA2

KS	04/22/2008	04/30/2008	Fire Safety
KS	04/22/2008	05/15/2008	Fire Safety
KS	06/10/2009	06/11/2009	Fire Safety
KS	06/10/2009	06/11/2009	Fire Safety
KS	06/10/2009	06/11/2009	Fire Safety
KS	06/10/2009	06/19/2009	Fire Safety
KS	08/11/2010	08/17/2010	Fire Safety
KS	08/11/2010	08/17/2010	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE

sumner regional medical center

Based on VSDA2

KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety
KS	08/07/2009	09/03/2009	Fire Safety
KS	08/07/2009	09/03/2009	Fire Safety
KS	08/07/2009	09/03/2009	Fire Safety
KS	08/07/2009	09/03/2009	Fire Safety
KS	08/07/2009	09/03/2009	Fire Safety

	for one hour or an approved fire extinguishing system.	
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175263	GOOD SAMARITAN SOCIETY - OLATHE	OLATHE
175264	MEDICALODGES COLUMBUS	COLUMBUS
175264	MEDICALODGES COLUMBUS	COLUMBUS
175264	MEDICALODGES COLUMBUS	COLUMBUS
175264	MEDICALODGES COLUMBUS	COLUMBUS
175264	MEDICALODGES COLUMBUS	COLUMBUS

sumner regional medical center

Based on VSDA2

KS	08/07/2009	09/03/2009	Fire Safety
KS	11/10/2010	11/29/2010	Fire Safety
KS	11/10/2010	11/10/2010	Fire Safety
KS	11/10/2010	11/30/2010	Fire Safety
KS	11/10/2010	11/24/2010	Fire Safety
KS	08/14/2008	08/22/2008	Fire Safety
KS	08/14/2008	08/14/2008	Fire Safety
KS	08/14/2008	08/18/2008	Fire Safety
KS	08/27/2009	08/27/2009	Fire Safety
KS	08/27/2009	09/23/2009	Fire Safety

	have been maintained in working order.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175264	MEDICALODGES COLUMBUS	COLUMBUS
175264	MEDICALODGES COLUMBUS	COLUMBUS
175264	MEDICALODGES COLUMBUS	COLUMBUS
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE

sumner regional medical center

Based on VSDA2

KS	08/27/2009	09/23/2009	Fire Safety
KS	09/16/2010	09/28/2010	Fire Safety
KS	09/16/2010	09/24/2010	Fire Safety
KS	04/26/2007	04/30/2007	Fire Safety
KS	04/26/2007	06/12/2007	Fire Safety
KS	04/26/2007	06/12/2007	Fire Safety
KS	04/26/2007	05/01/2007	Fire Safety
KS	04/26/2007	05/02/2007	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB	SHAWNEE

sumner regional medical center

Based on VSDA2

KS	04/26/2007	06/12/2007	Fire Safety
KS	04/26/2007	05/03/2007	Fire Safety
KS	04/26/2007	05/03/2007	Fire Safety
KS	04/26/2007	05/05/2007	Fire Safety
KS	05/08/2008	05/15/2008	Fire Safety
KS	05/08/2008	06/06/2008	Fire Safety
KS	05/08/2008	06/06/2008	Fire Safety
KS	05/08/2008	05/15/2008	Fire Safety
KS	05/08/2008	05/14/2008	Fire Safety
KS	05/08/2008	06/06/2008	Fire Safety

	extinguishing system.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	no-smoking signs where oxygen is used.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation,	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	CTR	
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE

sumner regional medical center

Based on VSDA2

KS	05/08/2008	06/06/2008	Fire Safety
KS	05/08/2008	06/06/2008	Fire Safety
KS	05/08/2008	06/06/2008	Fire Safety
KS	05/08/2008	05/15/2008	Fire Safety
KS	05/08/2008	06/06/2008	Fire Safety
KS	05/08/2008	06/06/2008	Fire Safety
KS	05/08/2008	06/06/2008	Fire Safety
KS	05/08/2008	05/15/2008	Fire Safety

	maintenance and testing program for fire alarm systems.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Widespread
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE

KS	08/18/2009	09/17/2009	Fire Safety
KS	08/18/2009	08/18/2009	Fire Safety
KS	08/18/2009	09/17/2009	Fire Safety
KS	08/18/2009	09/17/2009	Fire Safety
KS	08/18/2009	09/17/2009	Fire Safety
KS	08/18/2009	08/19/2009	Fire Safety
KS	08/18/2009	09/17/2009	Fire Safety
KS	08/18/2009	09/17/2009	Fire Safety
KS	08/18/2009	09/17/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175267	SHAWNEE GARDENS HEALTHCARE & REHAB CTR	SHAWNEE
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD

sumner regional medical center

Based on VSDA2

KS	08/18/2009	09/17/2009	Fire Safety
KS	02/14/2008	02/18/2008	Fire Safety
KS	02/14/2008	02/18/2008	Fire Safety
KS	02/14/2008	02/18/2008	Fire Safety
KS	02/14/2008	02/18/2008	Fire Safety
KS	02/14/2008	03/15/2008	Fire Safety
KS	02/14/2008	02/18/2008	Fire Safety
KS	02/14/2008	03/15/2008	Fire Safety
KS	02/14/2008	03/15/2008	Fire Safety
KS	02/14/2008	03/15/2008	Fire Safety

	smoke passage.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Laboratories Deficiencies	emergency showers.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD

KS	05/04/2009	05/15/2009	Fire Safety
KS	05/04/2009	05/31/2009	Fire Safety
KS	05/04/2009	05/11/2009	Fire Safety
KS	05/04/2009	05/31/2009	Fire Safety
KS	05/19/2010	06/10/2010	Fire Safety
KS	05/19/2010	06/10/2010	Fire Safety
KS	05/19/2010	06/10/2010	Fire Safety
KS	05/19/2010	06/10/2010	Fire Safety
KS	05/19/2010	06/10/2010	Fire Safety
KS	05/19/2010	06/10/2010	Fire Safety
KS	05/19/2010	06/10/2010	Fire Safety
KS	05/19/2010	06/10/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175272	GOLDEN LIVINGCENTER - WAKEFIELD	WAKEFIELD
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA

sumner regional medical center

Based on VSDA2

KS	05/19/2010	06/10/2010	Fire Safety
KS	05/19/2010	06/10/2010	Fire Safety
KS	09/05/2007	09/09/2007	Fire Safety
KS	09/05/2007	09/05/2007	Fire Safety
KS	09/05/2007	09/05/2007	Fire Safety
KS	09/05/2007	09/05/2007	Fire Safety
KS	09/05/2007	09/12/2007	Fire Safety
KS	09/05/2007	09/06/2007	Fire Safety
KS	09/05/2007	10/04/2007	Fire Safety
KS	09/05/2007	09/06/2007	Fire Safety
KS	09/05/2007	09/12/2007	Fire Safety

	administration areas.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA

KS	09/05/2007	09/12/2007	Fire Safety
KS	09/05/2007	09/11/2007	Fire Safety
KS	06/12/2008	07/12/2008	Fire Safety
KS	06/12/2008	07/12/2008	Fire Safety
KS	06/12/2008	07/12/2008	Fire Safety
KS	06/12/2008	07/12/2008	Fire Safety
KS	06/12/2008	07/12/2008	Fire Safety
KS	08/20/2009	09/19/2009	Fire Safety
KS	08/20/2009	09/19/2009	Fire Safety
KS	08/20/2009	09/19/2009	Fire Safety

	administration areas.	
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175273	GOLDEN LIVINGCENTER - WICHITA	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	08/20/2009	09/19/2009	Fire Safety
KS	08/20/2009	09/19/2009	Fire Safety
KS	08/20/2009	09/19/2009	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety

	conditions.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety
KS	12/18/2007	01/17/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA

KS	01/07/2009	02/03/2009	Fire Safety
KS	01/07/2009	02/03/2009	Fire Safety
KS	01/07/2009	02/03/2009	Fire Safety
KS	01/07/2009	02/03/2009	Fire Safety
KS	01/07/2009	02/03/2009	Fire Safety
KS	01/07/2009	02/03/2009	Fire Safety
KS	01/07/2009	02/03/2009	Fire Safety
KS	01/07/2009	02/03/2009	Fire Safety
KS	03/23/2010	03/23/2010	Fire Safety
KS	03/23/2010	03/23/2010	Fire Safety
KS	03/23/2010	04/05/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

	CENTER	
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175274	MERIDIAN NURSING & REHABILITATION CENTER	WICHITA
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY

sumner regional medical center

Based on VSDA2

KS	03/23/2010	03/23/2010	Fire Safety
KS	03/23/2010	04/05/2010	Fire Safety
KS	03/23/2010	04/05/2010	Fire Safety
KS	01/02/2008	02/01/2008	Fire Safety
KS	01/02/2008	02/01/2008	Fire Safety
KS	01/02/2008	02/01/2008	Fire Safety
KS	01/02/2008	02/01/2008	Fire Safety
KS	12/31/2008	01/21/2009	Fire Safety
KS	12/31/2008	01/21/2009	Fire Safety
KS	12/31/2008	01/21/2009	Fire Safety

	at least 1 1/2 hours.	
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175275	MEDICALODGES KINSLEY	KINSLEY
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA

KS	12/31/2008	01/21/2009	Fire Safety
KS	12/31/2008	12/31/2008	Fire Safety
KS	02/08/2010	03/05/2010	Fire Safety
KS	02/08/2010	04/08/2010	Fire Safety
KS	02/08/2010	03/05/2010	Fire Safety
KS	02/08/2010	03/05/2010	Fire Safety
KS	10/25/2007	11/24/2007	Fire Safety
KS	10/25/2007	11/24/2007	Fire Safety
KS	10/25/2007	11/24/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA
175276	NORTH POINT SKILLED NURSING CENTER	PAOLA

sumner regional medical center

Based on VSDA2

KS	10/25/2007	11/24/2007	Fire Safety
KS	10/25/2007	11/24/2007	Fire Safety
KS	10/25/2007	11/24/2007	Fire Safety
KS	10/14/2008	11/14/2008	Fire Safety
KS	10/14/2008	11/14/2008	Fire Safety
KS	11/19/2009	12/19/2009	Fire Safety
KS	11/19/2009	12/19/2009	Fire Safety
KS	11/19/2009	12/19/2009	Fire Safety
KS	11/19/2009	12/19/2009	Fire Safety
KS	11/19/2009	12/19/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Widespread
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE

sumner regional medical center

Based on VSDA2

KS	10/24/2007	10/24/2007	Fire Safety
KS	10/24/2007	11/20/2007	Fire Safety
KS	10/24/2007	11/20/2007	Fire Safety
KS	10/24/2007	11/20/2007	Fire Safety
KS	10/24/2007	10/24/2007	Fire Safety
KS	10/24/2007	11/01/2007	Fire Safety
KS	10/24/2007	11/20/2007	Fire Safety
KS	10/24/2007	10/24/2007	Fire Safety
KS	10/24/2007	10/31/2007	Fire Safety

	system connected to the fire alarm system.	
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE

sumner regional medical center

Based on VSDA2

KS	10/24/2007	10/24/2007	Fire Safety
KS	11/26/2008	12/14/2008	Fire Safety
KS	11/26/2008	12/14/2008	Fire Safety
KS	11/26/2008	12/14/2008	Fire Safety
KS	11/26/2008	12/14/2008	Fire Safety
KS	11/26/2008	12/14/2008	Fire Safety
KS	11/26/2008	12/14/2008	Fire Safety
KS	11/26/2008	12/14/2008	Fire Safety
KS	11/26/2008	12/14/2008	Fire Safety
KS	11/26/2008	12/14/2008	Fire Safety
KS	01/11/2010	01/15/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175277	BRANDON WOODS AT ALVAMAR	LAWRENCE
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA

sumner regional medical center

Based on VSDA2

KS	01/11/2010	01/29/2010	Fire Safety
KS	01/11/2010	01/29/2010	Fire Safety
KS	01/11/2010	01/12/2010	Fire Safety
KS	01/11/2010	01/29/2010	Fire Safety
KS	01/11/2010	01/29/2010	Fire Safety
KS	07/10/2007	08/08/2007	Fire Safety
KS	07/10/2007	08/08/2007	Fire Safety
KS	07/10/2007	08/08/2007	Fire Safety
KS	07/10/2007	08/08/2007	Fire Safety
KS	07/10/2007	08/08/2007	Fire Safety

	common walls.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA

sumner regional medical center

Based on VSDA2

KS	07/10/2007	08/08/2007	Fire Safety
KS	07/10/2007	08/08/2007	Fire Safety
KS	07/10/2007	08/08/2007	Fire Safety
KS	06/13/2008	07/11/2008	Fire Safety
KS	06/13/2008	07/11/2008	Fire Safety
KS	06/13/2008	07/11/2008	Fire Safety
KS	06/13/2008	07/11/2008	Fire Safety
KS	06/13/2008	07/11/2008	Fire Safety

	permitted or did not provide ashtrays where smoking was allowed.	
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175280	FLINT HILLS CARE CENTER	EMPORIA
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	06/13/2008	07/11/2008	Fire Safety
KS	06/13/2008	07/11/2008	Fire Safety
KS	08/14/2009	08/31/2009	Fire Safety
KS	08/14/2009	08/31/2009	Fire Safety
KS	08/14/2009	08/31/2009	Fire Safety
KS	08/14/2009	08/31/2009	Fire Safety
KS	07/27/2007	07/27/2007	Fire Safety
KS	07/27/2007	08/25/2007	Fire Safety
KS	07/27/2007	08/25/2007	Fire Safety
KS	07/27/2007	08/25/2007	Fire Safety
KS	07/27/2007	08/25/2007	Fire Safety

	allowed.	
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	07/27/2007	08/25/2007	Fire Safety
KS	07/27/2007	08/25/2007	Fire Safety
KS	07/27/2007	08/25/2007	Fire Safety
KS	10/22/2008	11/21/2008	Fire Safety
KS	10/22/2008	11/21/2008	Fire Safety
KS	10/22/2008	11/21/2008	Fire Safety
KS	10/22/2008	11/21/2008	Fire Safety
KS	10/22/2008	11/21/2008	Fire Safety
KS	10/22/2008	11/21/2008	Fire Safety
KS	10/22/2008	11/21/2008	Fire Safety

	have been maintained in working order.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175281	LIFE CARE CENTER OF KANSAS CITY	KANSAS CITY
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS

KS	12/10/2009	12/10/2009	Fire Safety
KS	12/10/2009	12/19/2009	Fire Safety
KS	12/10/2009	12/14/2009	Fire Safety
KS	12/10/2009	12/10/2009	Fire Safety
KS	12/10/2009	12/10/2009	Fire Safety
KS	06/26/2008	06/26/2008	Fire Safety
KS	06/26/2008	06/26/2008	Fire Safety
KS	06/26/2008	06/26/2008	Fire Safety
KS	06/26/2008	07/02/2008	Fire Safety
KS	06/26/2008	06/28/2008	Fire Safety
KS	06/26/2008	07/02/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	no-smoking signs where oxygen is used.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS

sumner regional medical center

Based on VSDA2

KS	06/26/2008	07/01/2008	Fire Safety
KS	07/21/2009	07/21/2009	Fire Safety
KS	07/21/2009	07/27/2009	Fire Safety
KS	07/21/2009	07/29/2009	Fire Safety
KS	07/21/2009	08/21/2009	Fire Safety
KS	07/21/2009	07/27/2009	Fire Safety
KS	07/21/2009	07/27/2009	Fire Safety
KS	07/21/2009	08/21/2009	Fire Safety
KS	07/27/2010	08/25/2010	Fire Safety
KS	07/27/2010	08/25/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Interior Finish Deficiencies	fire-resistant interior walls.	Isolated
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175282	GOOD SAMARITAN SOCIETY - MINNEAPOLIS	MINNEAPOLIS
175286	WHEATLAND NURSING & REHABILITATION CENTER	RUSSELL
175286	WHEATLAND NURSING & REHABILITATION CENTER	RUSSELL
175286	WHEATLAND NURSING & REHABILITATION CENTER	RUSSELL

sumner regional medical center

Based on VSDA2

KS	07/27/2010	08/25/2010	Fire Safety
KS	07/27/2010	08/25/2010	Fire Safety
KS	07/27/2010	08/25/2010	Fire Safety
KS	07/27/2010	08/25/2010	Fire Safety
KS	07/27/2010	08/25/2010	Fire Safety
KS	07/01/2008	07/31/2008	Fire Safety
KS	07/01/2008	07/31/2008	Fire Safety
KS	07/01/2008	07/31/2008	Fire Safety

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175286	WHEATLAND NURSING & REHABILITATION CENTER	RUSSELL
175286	WHEATLAND NURSING & REHABILITATION CENTER	RUSSELL
175286	WHEATLAND NURSING & REHABILITATION CENTER	RUSSELL
175286	WHEATLAND NURSING & REHABILITATION CENTER	RUSSELL
175286	WHEATLAND NURSING & REHABILITATION CENTER	RUSSELL
175286	WHEATLAND NURSING & REHABILITATION CENTER	RUSSELL
175287	EUREKA NURSING CENTER	EUREKA
175287	EUREKA NURSING CENTER	EUREKA
175287	EUREKA NURSING CENTER	EUREKA
175287	EUREKA NURSING CENTER	EUREKA

sumner regional medical center

Based on VSDA2

KS	07/01/2008	07/31/2008	Fire Safety
KS	07/01/2008	07/31/2008	Fire Safety
KS	07/01/2008	07/31/2008	Fire Safety
KS	07/01/2008	07/31/2008	Fire Safety
KS	07/09/2009	07/09/2009	Fire Safety
KS	07/21/2010	07/23/2010	Fire Safety
KS	03/04/2008	03/14/2008	Fire Safety
KS	03/04/2008	03/14/2008	Fire Safety
KS	02/04/2009	02/04/2009	Fire Safety
KS	02/04/2009	02/04/2009	Fire Safety

	order.	
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit"	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175287	EUREKA NURSING CENTER	EUREKA
175287	EUREKA NURSING CENTER	EUREKA
175287	EUREKA NURSING CENTER	EUREKA
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE

sumner regional medical center

Based on VSDA2

KS	02/04/2009	03/03/2009	Fire Safety
KS	04/28/2010	05/25/2010	Fire Safety
KS	04/28/2010	05/10/2010	Fire Safety
KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	10/18/2007	Fire Safety

	signs.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE

sumner regional medical center

Based on VSDA2

KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	10/18/2007	Fire Safety
KS	06/16/2008	07/16/2008	Fire Safety
KS	06/16/2008	07/16/2008	Fire Safety
KS	06/16/2008	07/16/2008	Fire Safety
KS	06/16/2008	07/16/2008	Fire Safety
KS	06/16/2008	07/16/2008	Fire Safety
KS	06/16/2008	07/16/2008	Fire Safety
KS	06/16/2008	07/16/2008	Fire Safety

	ashtrays where smoking was allowed.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE

sumner regional medical center

Based on VSDA2

KS	06/16/2008	07/16/2008	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175290	WINDSOR PLACE LLC	COFFEYVILLE
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND

sumner regional medical center

Based on VSDA2

KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	09/23/2009	10/23/2009	Fire Safety
KS	01/13/2009	02/13/2009	Fire Safety
KS	01/13/2009	02/13/2009	Fire Safety
KS	01/13/2009	01/13/2009	Fire Safety
KS	01/13/2009	02/13/2009	Fire Safety
KS	01/13/2009	02/13/2009	Fire Safety
KS	01/13/2009	02/13/2009	Fire Safety
KS	01/13/2009	01/21/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND

sumner regional medical center

Based on VSDA2

KS	01/13/2009	02/13/2009	Fire Safety
KS	01/13/2009	02/13/2009	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	01/25/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/25/2011	02/23/2011	Fire Safety
KS	01/25/2011	02/23/2011	Fire Safety
KS	01/25/2011	02/23/2011	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175291	GREAT BEND HEALTH & REHAB CENTER	GREAT BEND
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS

sumner regional medical center

Based on VSDA2

KS	01/25/2011	02/23/2011	Fire Safety
KS	01/25/2011	02/23/2011	Fire Safety
KS	05/16/2008	05/17/2008	Fire Safety
KS	05/16/2008	05/17/2008	Fire Safety
KS	05/16/2008	06/13/2008	Fire Safety
KS	05/16/2008	06/13/2008	Fire Safety
KS	05/16/2008	05/17/2008	Fire Safety
KS	05/16/2008	05/18/2008	Fire Safety
KS	05/16/2008	05/16/2008	Fire Safety
KS	07/01/2009	07/02/2009	Fire Safety
KS	07/01/2009	07/02/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175292	MEDICALODGES DOUGLASS	DOUGLASS
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD

sumner regional medical center

Based on VSDA2

KS	07/01/2009	07/07/2009	Fire Safety
KS	08/11/2010	08/31/2010	Fire Safety
KS	08/11/2010	08/31/2010	Fire Safety
KS	08/11/2010	08/19/2010	Fire Safety
KS	02/25/2008	03/25/2008	Fire Safety
KS	02/25/2008	03/25/2008	Fire Safety
KS	02/25/2008	03/25/2008	Fire Safety
KS	02/25/2008	03/25/2008	Fire Safety
KS	02/25/2008	03/25/2008	Fire Safety

	for one hour or an approved fire extinguishing system.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175294	MEDICALODGES GODDARD	GODDARD
175295	DESERET NURSING & REHABILITATION AT	SMITH CENTER

sumner regional medical center

Based on VSDA2

KS	02/25/2008	03/25/2008	Fire Safety
KS	02/25/2008	03/25/2008	Fire Safety
KS	03/03/2009	03/03/2009	Fire Safety
KS	03/03/2009	03/03/2009	Fire Safety
KS	03/03/2009	03/03/2009	Fire Safety
KS	03/03/2009	03/03/2009	Fire Safety
KS	03/03/2009	03/03/2009	Fire Safety
KS	03/03/2009	03/31/2009	Fire Safety
KS	05/06/2010	05/15/2010	Fire Safety
KS	05/06/2010	05/15/2010	Fire Safety
KS	03/20/2008	04/15/2008	Fire Safety

	facilities.	
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

	SMITH CENTER	
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT	SMITH CENTER

KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	04/17/2008	Fire Safety
KS	03/20/2008	03/24/2008	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	03/31/2008	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	04/11/2008	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety

	materials.	
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	SMITH CENTER	
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER

sumner regional medical center

Based on VSDA2

KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	03/25/2008	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety
KS	04/01/2009	05/01/2009	Fire Safety
KS	04/01/2009	05/01/2009	Fire Safety
KS	04/01/2009	05/01/2009	Fire Safety
KS	04/01/2009	05/01/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175295	DESERET NURSING & REHABILITATION AT SMITH CENTER	SMITH CENTER
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA

KS	04/01/2009	05/01/2009	Fire Safety
KS	04/01/2009	05/01/2009	Fire Safety
KS	04/01/2009	05/01/2009	Fire Safety
KS	04/01/2009	05/01/2009	Fire Safety
KS	04/01/2009	05/01/2009	Fire Safety
KS	05/03/2010	06/01/2010	Fire Safety
KS	05/03/2010	06/01/2010	Fire Safety
KS	05/03/2010	06/01/2010	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA

sumner regional medical center

Based on VSDA2

KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety
KS	03/13/2008	04/11/2008	Fire Safety

	would resist fire for at least one hour.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA

KS	03/13/2008	04/11/2008	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA

sumner regional medical center

Based on VSDA2

KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175297	TOPEKA PRESBYTERIAN MANOR	TOPEKA
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	07/20/2010	08/04/2010	Fire Safety
KS	01/08/2008	02/06/2008	Fire Safety
KS	01/08/2008	02/06/2008	Fire Safety
KS	01/08/2008	02/06/2008	Fire Safety

	times.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	01/08/2008	02/06/2008	Fire Safety
KS	01/08/2008	02/06/2008	Fire Safety
KS	01/08/2008	02/06/2008	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Building Service Equipment Deficiencies	properly constructed linen or trash chutes.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	04/06/2009	04/13/2009	Fire Safety
KS	05/27/2010	06/26/2010	Fire Safety
KS	05/27/2010	06/26/2010	Fire Safety
KS	05/27/2010	06/26/2010	Fire Safety
KS	05/27/2010	06/26/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175298	KANSAS CITY PRESBYTERIAN MANOR	KANSAS CITY
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING

sumner regional medical center

Based on VSDA2

KS	05/27/2010	06/26/2010	Fire Safety
KS	05/21/2008	06/16/2008	Fire Safety
KS	05/21/2008	06/16/2008	Fire Safety
KS	05/21/2008	06/16/2008	Fire Safety
KS	05/21/2008	06/16/2008	Fire Safety
KS	05/21/2008	06/16/2008	Fire Safety
KS	05/21/2008	06/16/2008	Fire Safety
KS	05/21/2008	06/16/2008	Fire Safety
KS	05/21/2008	06/16/2008	Fire Safety
KS	05/21/2008	06/16/2008	Fire Safety

	alarm system.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175299	STERLING PRESBYTERIAN MANOR	STERLING
175300	SALINA PRESBYTERIAN MANOR	SALINA
175300	SALINA PRESBYTERIAN MANOR	SALINA
175300	SALINA PRESBYTERIAN MANOR	SALINA
175300	SALINA PRESBYTERIAN MANOR	SALINA
175300	SALINA PRESBYTERIAN MANOR	SALINA
175300	SALINA PRESBYTERIAN MANOR	SALINA

sumner regional medical center

Based on VSDA2

KS	06/02/2009	07/01/2009	Fire Safety
KS	06/02/2009	07/01/2009	Fire Safety
KS	06/02/2009	07/01/2009	Fire Safety
KS	06/08/2010	06/24/2010	Fire Safety
KS	06/08/2010	06/24/2010	Fire Safety
KS	07/16/2008	07/23/2008	Fire Safety
KS	07/16/2008	07/23/2008	Fire Safety
KS	07/16/2008	07/23/2008	Fire Safety
KS	07/15/2009	07/16/2009	Fire Safety
KS	07/15/2009	07/23/2009	Fire Safety
KS	07/15/2009	07/23/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175300	SALINA PRESBYTERIAN MANOR	SALINA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA

sumner regional medical center

Based on VSDA2

KS	09/17/2010	09/27/2010	Fire Safety
KS	12/10/2007	01/09/2008	Fire Safety
KS	12/10/2007	01/09/2008	Fire Safety
KS	12/10/2007	01/09/2008	Fire Safety
KS	12/10/2007	01/09/2008	Fire Safety
KS	12/10/2007	01/09/2008	Fire Safety
KS	12/10/2007	01/09/2008	Fire Safety
KS	12/10/2007	01/09/2008	Fire Safety
KS	12/10/2007	01/09/2008	Fire Safety
KS	01/14/2009	01/28/2009	Fire Safety
KS	01/14/2009	01/28/2009	Fire Safety

	order.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175301	WICHITA PRESBYTERIAN MANOR	WICHITA
175302	NEWTON PRESBYTERIAN MANOR	NEWTON
175302	NEWTON PRESBYTERIAN MANOR	NEWTON
175302	NEWTON PRESBYTERIAN MANOR	NEWTON
175302	NEWTON PRESBYTERIAN MANOR	NEWTON
175302	NEWTON PRESBYTERIAN MANOR	NEWTON

sumner regional medical center

Based on VSDA2

KS	01/14/2009	01/28/2009	Fire Safety
KS	02/25/2010	03/10/2010	Fire Safety
KS	02/25/2010	03/10/2010	Fire Safety
KS	02/25/2010	03/10/2010	Fire Safety
KS	02/25/2010	03/10/2010	Fire Safety
KS	05/21/2008	06/20/2008	Fire Safety
KS	05/21/2008	06/20/2008	Fire Safety
KS	05/21/2008	06/20/2008	Fire Safety
KS	05/21/2008	06/20/2008	Fire Safety
KS	05/14/2009	05/18/2009	Fire Safety

	obstructions and can be used at all times.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175302	NEWTON PRESBYTERIAN MANOR	NEWTON
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS

sumner regional medical center

Based on VSDA2

KS	05/14/2009	05/18/2009	Fire Safety
KS	01/24/2008	01/31/2008	Fire Safety
KS	01/24/2008	01/31/2008	Fire Safety
KS	01/24/2008	02/21/2008	Fire Safety
KS	01/15/2009	01/28/2009	Fire Safety
KS	01/15/2009	01/28/2009	Fire Safety
KS	01/22/2010	02/19/2010	Fire Safety
KS	01/22/2010	02/08/2010	Fire Safety
KS	01/22/2010	02/19/2010	Fire Safety

	extinguishing system.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175303	PARSONS PRESBYTERIAN MANOR	PARSONS
175304	EMPORIA PRESBYTERIAN MANOR	EMPORIA
175304	EMPORIA PRESBYTERIAN MANOR	EMPORIA
175304	EMPORIA PRESBYTERIAN MANOR	EMPORIA
175304	EMPORIA PRESBYTERIAN MANOR	EMPORIA
175304	EMPORIA PRESBYTERIAN MANOR	EMPORIA
175304	EMPORIA PRESBYTERIAN MANOR	EMPORIA

KS	01/22/2010	02/01/2010	Fire Safety
KS	01/22/2010	02/19/2010	Fire Safety
KS	01/22/2010	02/19/2010	Fire Safety
KS	03/04/2008	04/01/2008	Fire Safety
KS	03/04/2008	04/01/2008	Fire Safety
KS	03/04/2008	04/01/2008	Fire Safety
KS	03/04/2008	04/01/2008	Fire Safety
KS	05/19/2009	05/20/2009	Fire Safety
KS	05/19/2009	05/20/2009	Fire Safety

	at least 1 1/2 hours.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	a separate and independent backup electrical power source.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175304	EMPORIA PRESBYTERIAN MANOR	EMPORIA
175304	EMPORIA PRESBYTERIAN MANOR	EMPORIA
175305	LAWRENCE PRESBYTERIAN MANOR	LAWRENCE
175305	LAWRENCE PRESBYTERIAN MANOR	LAWRENCE
175305	LAWRENCE PRESBYTERIAN MANOR	LAWRENCE
175306	MANOR OF THE PLAINS	DODGE CITY
175306	MANOR OF THE PLAINS	DODGE CITY
175306	MANOR OF THE PLAINS	DODGE CITY
175306	MANOR OF THE PLAINS	DODGE CITY
175306	MANOR OF THE PLAINS	DODGE CITY

sumner regional medical center

Based on VSDA2

KS	05/19/2009	05/20/2009	Fire Safety
KS	07/12/2010	07/13/2010	Fire Safety
KS	11/27/2007	12/19/2007	Fire Safety
KS	11/27/2007	12/19/2007	Fire Safety
KS	11/27/2007	12/19/2007	Fire Safety
KS	04/08/2008	04/21/2008	Fire Safety
KS	04/08/2008	04/21/2008	Fire Safety
KS	04/08/2008	04/21/2008	Fire Safety
KS	04/08/2008	04/21/2008	Fire Safety
KS	04/08/2008	04/21/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY

KS	07/02/2007	08/01/2007	Fire Safety
KS	07/02/2007	08/01/2007	Fire Safety
KS	07/02/2007	08/01/2007	Fire Safety
KS	07/02/2007	07/02/2007	Fire Safety
KS	07/02/2007	08/01/2007	Fire Safety
KS	07/02/2007	08/01/2007	Fire Safety
KS	07/02/2007	08/01/2007	Fire Safety
KS	07/02/2007	08/01/2007	Fire Safety

	and equipment.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY

sumner regional medical center

Based on VSDA2

KS	12/01/2008	12/30/2008	Fire Safety
KS	12/01/2008	12/30/2008	Fire Safety
KS	12/01/2008	12/30/2008	Fire Safety
KS	12/01/2008	12/04/2008	Fire Safety
KS	12/01/2008	12/01/2008	Fire Safety
KS	12/01/2008	12/05/2008	Fire Safety
KS	12/01/2008	12/12/2008	Fire Safety
KS	12/01/2008	12/30/2008	Fire Safety

	hand rub.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175307	MEDICALODGES KANSAS CITY	KANSAS CITY
175309	ARKANSAS CITY PRESBYTERIAN MANOR	ARKANSAS CITY

sumner regional medical center

Based on VSDA2

KS	12/01/2008	12/30/2008	Fire Safety
KS	12/01/2008	12/01/2008	Fire Safety
KS	01/20/2010	01/20/2010	Fire Safety
KS	01/20/2010	02/14/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	01/20/2010	02/10/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	01/20/2010	01/20/2010	Fire Safety
KS	01/20/2010	02/19/2010	Fire Safety
KS	03/06/2008	04/01/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175309	ARKANSAS CITY PRESBYTERIAN MANOR	ARKANSAS CITY
175309	ARKANSAS CITY PRESBYTERIAN MANOR	ARKANSAS CITY
175309	ARKANSAS CITY PRESBYTERIAN MANOR	ARKANSAS CITY
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER

sumner regional medical center

Based on VSDA2

KS	03/06/2008	04/01/2008	Fire Safety
KS	05/17/2010	06/08/2010	Fire Safety
KS	05/17/2010	06/16/2010	Fire Safety
KS	01/22/2008	02/21/2008	Fire Safety
KS	01/22/2008	02/21/2008	Fire Safety
KS	01/22/2008	02/21/2008	Fire Safety
KS	01/22/2008	02/21/2008	Fire Safety
KS	01/22/2008	02/21/2008	Fire Safety

	would resist fire for at least one hour.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER

sumner regional medical center

Based on VSDA2

KS	01/22/2008	02/21/2008	Fire Safety
KS	01/22/2008	02/21/2008	Fire Safety
KS	04/15/2009	05/13/2009	Fire Safety
KS	04/15/2009	05/13/2009	Fire Safety
KS	04/15/2009	05/13/2009	Fire Safety
KS	04/15/2009	05/13/2009	Fire Safety
KS	04/15/2009	05/13/2009	Fire Safety
KS	04/15/2009	05/13/2009	Fire Safety
KS	05/04/2010	05/04/2010	Fire Safety
KS	05/04/2010	06/01/2010	Fire Safety
KS	05/04/2010	05/04/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Pattern
Vertical Openings Deficiencies	protected exits that allow the resident to escape the building.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175310	CLAY CENTER PRESBYTERIAN MANOR	CLAY CENTER
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY
175313	MEDICALODGES ARKANSAS CITY	ARKANSAS CITY

KS	05/04/2010	06/01/2010	Fire Safety
KS	07/08/2008	08/07/2008	Fire Safety
KS	07/08/2008	08/07/2008	Fire Safety
KS	07/08/2008	08/07/2008	Fire Safety
KS	07/08/2008	08/07/2008	Fire Safety
KS	07/08/2008	08/07/2008	Fire Safety
KS	07/08/2008	08/07/2008	Fire Safety
KS	07/08/2008	08/07/2008	Fire Safety
KS	08/18/2009	08/24/2009	Fire Safety
KS	09/09/2010	09/24/2010	Fire Safety
KS	09/09/2010	10/08/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly constructed linen or trash chutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT

sumner regional medical center

Based on VSDA2

KS	01/07/2008	02/05/2008	Fire Safety
KS	01/07/2008	02/05/2008	Fire Safety
KS	01/07/2008	02/05/2008	Fire Safety
KS	01/07/2008	02/05/2008	Fire Safety
KS	01/07/2008	02/05/2008	Fire Safety
KS	01/07/2008	01/10/2008	Fire Safety
KS	02/24/2009	03/24/2009	Fire Safety
KS	02/24/2009	03/24/2009	Fire Safety
KS	02/24/2009	03/24/2009	Fire Safety

	and equipment.	
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175315	LAKEWOOD SENIOR LIVING OF PRATT	PRATT
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA

sumner regional medical center

Based on VSDA2

KS	02/24/2009	03/24/2009	Fire Safety
KS	02/24/2009	03/24/2009	Fire Safety
KS	02/24/2009	03/24/2009	Fire Safety
KS	02/24/2009	03/24/2009	Fire Safety
KS	02/24/2009	03/24/2009	Fire Safety
KS	02/09/2010	03/10/2010	Fire Safety
KS	02/09/2010	03/10/2010	Fire Safety
KS	02/09/2010	03/10/2010	Fire Safety
KS	02/09/2010	03/10/2010	Fire Safety
KS	02/09/2010	03/10/2010	Fire Safety
KS	02/18/2008	03/18/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Hazardous Area Deficiencies	construction that can resist fire	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA
175317	GOLDEN LIVINGCENTER - NEODESHA	NEODESHA

sumner regional medical center

Based on VSDA2

KS	02/18/2008	02/19/2008	Fire Safety
KS	02/18/2008	02/19/2008	Fire Safety
KS	02/18/2008	03/18/2008	Fire Safety
KS	02/18/2008	03/18/2008	Fire Safety
KS	02/18/2008	03/18/2008	Fire Safety
KS	02/18/2008	03/18/2008	Fire Safety
KS	01/21/2009	01/21/2009	Fire Safety
KS	01/21/2009	01/23/2009	Fire Safety
KS	01/21/2009	01/23/2009	Fire Safety
KS	02/15/2010	02/23/2010	Fire Safety
KS	02/15/2010	03/10/2010	Fire Safety

	for one hour or an approved fire extinguishing system.	
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS

sumner regional medical center

Based on VSDA2

KS	11/04/2008	11/26/2008	Fire Safety
KS	11/04/2008	11/06/2008	Fire Safety
KS	11/04/2008	11/14/2008	Fire Safety
KS	11/04/2008	11/26/2008	Fire Safety
KS	11/04/2008	11/04/2008	Fire Safety
KS	11/04/2008	11/26/2008	Fire Safety
KS	11/04/2008	11/26/2008	Fire Safety
KS	11/04/2008	11/14/2008	Fire Safety
KS	11/04/2008	11/10/2008	Fire Safety
KS	11/04/2009	11/04/2009	Fire Safety

	and equipment.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175322	GOOD SAMARITAN SOCIETY - HAYS	HAYS
175323	VILLAGE VILLA	NORTONVILLE

KS	11/04/2009	11/04/2009	Fire Safety
KS	11/04/2009	11/04/2009	Fire Safety
KS	11/04/2009	11/16/2009	Fire Safety
KS	11/04/2009	11/09/2009	Fire Safety
KS	11/04/2009	11/06/2009	Fire Safety
KS	11/04/2009	11/13/2009	Fire Safety
KS	11/04/2009	11/24/2009	Fire Safety
KS	11/23/2010	12/10/2010	Fire Safety
KS	11/23/2010	12/10/2010	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE

sumner regional medical center

Based on VSDA2

KS	05/21/2008	06/19/2008	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety
KS	05/21/2008	06/19/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE

sumner regional medical center

Based on VSDA2

KS	05/21/2008	06/19/2008	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Laboratories Deficiencies	emergency showers.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175323	VILLAGE VILLA	NORTONVILLE
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO

sumner regional medical center

Based on VSDA2

KS	07/13/2009	08/12/2009	Fire Safety
KS	07/13/2009	08/12/2009	Fire Safety
KS	08/11/2010	09/09/2010	Fire Safety
KS	08/11/2010	09/09/2010	Fire Safety
KS	08/11/2010	09/09/2010	Fire Safety
KS	08/11/2010	08/20/2010	Fire Safety
KS	08/11/2010	08/20/2010	Fire Safety
KS	08/11/2010	08/11/2010	Fire Safety
KS	07/21/2008	08/30/2008	Fire Safety
KS	07/21/2008	08/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	an externally vented heating system.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO

sumner regional medical center

Based on VSDA2

KS	07/21/2008	08/30/2008	Fire Safety
KS	07/21/2008	08/30/2008	Fire Safety
KS	07/21/2008	08/30/2008	Fire Safety
KS	07/21/2008	08/30/2008	Fire Safety
KS	07/21/2008	08/30/2008	Fire Safety
KS	08/20/2009	09/11/2009	Fire Safety
KS	08/20/2009	09/11/2009	Fire Safety
KS	08/20/2009	09/20/2009	Fire Safety
KS	08/20/2009	09/20/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175324	GOLDEN LIVINGCENTER - EL DORADO	EL DORADO
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD

sumner regional medical center

Based on VSDA2

KS	08/20/2009	09/28/2009	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	12/06/2007	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Interior Finish Deficiencies	fire-resistant interior walls.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD

KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/06/2007	01/04/2008	Fire Safety
KS	12/30/2008	01/29/2009	Fire Safety
KS	12/30/2008	01/29/2009	Fire Safety
KS	12/30/2008	01/29/2009	Fire Safety
KS	12/30/2008	01/29/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD

sumner regional medical center

Based on VSDA2

KS	12/30/2008	01/29/2009	Fire Safety
KS	12/30/2008	01/29/2009	Fire Safety
KS	12/30/2008	01/29/2009	Fire Safety
KS	12/30/2008	01/29/2009	Fire Safety
KS	12/30/2008	01/29/2009	Fire Safety
KS	12/30/2008	01/29/2009	Fire Safety
KS	02/11/2010	02/19/2010	Fire Safety
KS	02/11/2010	02/19/2010	Fire Safety
KS	02/11/2010	02/19/2010	Fire Safety
KS	02/11/2010	02/19/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175327	GOOD SAMARITAN SOCIETY - WINFIELD	WINFIELD
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS

sumner regional medical center

Based on VSDA2

KS	02/11/2010	02/26/2010	Fire Safety
KS	02/11/2010	02/19/2010	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS

sumner regional medical center

Based on VSDA2

KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175328	GOOD SAMARITAN SOCIETY - ELLIS	ELLIS
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA

sumner regional medical center

Based on VSDA2

KS	05/04/2010	05/07/2010	Fire Safety
KS	05/04/2010	05/07/2010	Fire Safety
KS	07/23/2008	08/22/2008	Fire Safety
KS	07/23/2008	08/09/2008	Fire Safety
KS	07/23/2008	08/22/2008	Fire Safety
KS	07/23/2008	08/22/2008	Fire Safety
KS	07/23/2008	08/22/2008	Fire Safety
KS	07/23/2008	07/29/2008	Fire Safety
KS	07/23/2008	08/22/2008	Fire Safety

	and equipment.	
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175332	OTTAWA RETIREMENT VILLAGE	OTTAWA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA

sumner regional medical center

Based on VSDA2

KS	07/23/2008	08/22/2008	Fire Safety
KS	07/20/2009	07/31/2009	Fire Safety
KS	07/20/2009	08/08/2009	Fire Safety
KS	07/20/2009	08/07/2009	Fire Safety
KS	07/20/2009	07/21/2009	Fire Safety
KS	08/18/2010	08/19/2010	Fire Safety
KS	08/18/2010	09/17/2010	Fire Safety
KS	10/17/2007	10/23/2007	Fire Safety
KS	10/17/2007	10/23/2007	Fire Safety

	at least 1 1/2 hours.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA

sumner regional medical center

Based on VSDA2

KS	10/17/2007	10/18/2007	Fire Safety
KS	01/21/2009	02/16/2009	Fire Safety
KS	01/21/2009	02/16/2009	Fire Safety
KS	01/21/2009	02/16/2009	Fire Safety
KS	01/21/2009	02/16/2009	Fire Safety
KS	01/21/2009	02/16/2009	Fire Safety
KS	01/21/2009	02/16/2009	Fire Safety
KS	03/16/2010	03/16/2010	Fire Safety
KS	03/16/2010	03/16/2010	Fire Safety
KS	03/16/2010	03/16/2010	Fire Safety
KS	03/16/2010	03/16/2010	Fire Safety
KS	03/16/2010	03/16/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175333	HICKORY POINTE CARE & REHAB CENTER	OSKALOOSA
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL

sumner regional medical center

Based on VSDA2

KS	03/16/2010	03/16/2010	Fire Safety
KS	07/03/2007	07/27/2007	Fire Safety
KS	07/03/2007	10/01/2007	Fire Safety
KS	07/03/2007	07/30/2007	Fire Safety
KS	07/03/2007	08/01/2007	Fire Safety
KS	07/03/2007	08/01/2007	Fire Safety
KS	07/03/2007	10/01/2007	Fire Safety
KS	07/03/2007	08/01/2007	Fire Safety
KS	07/03/2007	07/11/2007	Fire Safety
KS	07/03/2007	07/17/2007	Fire Safety

	order.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL

sumner regional medical center

Based on VSDA2

KS	07/03/2007	10/01/2007	Fire Safety
KS	07/03/2007	10/01/2007	Fire Safety
KS	07/03/2007	10/01/2007	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	08/15/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	08/20/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety

	all times.	
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL

KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	08/20/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	08/20/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	08/12/2008	09/11/2008	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175334	GOOD SAMARITAN SOCIETY - LIBERAL	LIBERAL
175335	CHERRYVALE NURSING AND REHABILITATION CENTER	CHERRYVALE
175335	CHERRYVALE NURSING AND REHABILITATION CENTER	CHERRYVALE
175335	CHERRYVALE NURSING AND REHABILITATION CENTER	CHERRYVALE
175335	CHERRYVALE NURSING AND REHABILITATION CENTER	CHERRYVALE
175335	CHERRYVALE NURSING AND REHABILITATION CENTER	CHERRYVALE
175335	CHERRYVALE NURSING AND REHABILITATION CENTER	CHERRYVALE

sumner regional medical center

Based on VSDA2

KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	04/22/2008	05/16/2008	Fire Safety
KS	04/22/2008	05/16/2008	Fire Safety
KS	04/22/2008	05/16/2008	Fire Safety
KS	06/24/2009	07/17/2009	Fire Safety
KS	06/24/2009	07/17/2009	Fire Safety
KS	06/24/2009	07/17/2009	Fire Safety

	materials.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175335	CHERRYVALE NURSING AND REHABILITATION CENTER	CHERRYVALE
175335	CHERRYVALE NURSING AND REHABILITATION CENTER	CHERRYVALE
175335	CHERRYVALE NURSING AND REHABILITATION CENTER	CHERRYVALE
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS

sumner regional medical center

Based on VSDA2

KS	06/24/2009	07/17/2009	Fire Safety
KS	08/13/2010	09/10/2010	Fire Safety
KS	08/13/2010	09/10/2010	Fire Safety
KS	01/23/2008	02/22/2008	Fire Safety
KS	01/23/2008	02/22/2008	Fire Safety
KS	01/23/2008	02/22/2008	Fire Safety
KS	01/23/2008	02/22/2008	Fire Safety
KS	01/23/2008	02/22/2008	Fire Safety
KS	01/23/2008	02/22/2008	Fire Safety
KS	01/23/2008	02/22/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS
175336	GOOD SAMARITAN SOCIETY - LYONS	LYONS

KS	01/23/2008	02/22/2008	Fire Safety
KS	01/23/2008	02/22/2008	Fire Safety
KS	02/17/2009	02/25/2009	Fire Safety
KS	02/17/2009	03/16/2009	Fire Safety
KS	02/17/2009	03/15/2009	Fire Safety
KS	02/17/2009	03/15/2009	Fire Safety
KS	02/17/2009	02/19/2009	Fire Safety
KS	02/17/2009	03/15/2009	Fire Safety
KS	06/02/2010	06/03/2010	Fire Safety
KS	06/02/2010	06/04/2010	Fire Safety
KS	06/02/2010	06/04/2010	Fire Safety

	order.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Electrical Deficiencies	properly installed electrical wiring	Isolated

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON

sumner regional medical center

Based on VSDA2

KS	05/30/2008	06/29/2008	Fire Safety
KS	05/30/2008	06/29/2008	Fire Safety
KS	05/30/2008	06/29/2008	Fire Safety
KS	05/30/2008	06/29/2008	Fire Safety
KS	05/30/2008	06/29/2008	Fire Safety
KS	05/30/2008	06/29/2008	Fire Safety
KS	05/30/2008	06/29/2008	Fire Safety
KS	05/30/2008	06/29/2008	Fire Safety
KS	05/30/2008	06/29/2008	Fire Safety

	and equipment.	
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175337	GOLDEN LIVINGCENTER - WELLINGTON	WELLINGTON
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY

sumner regional medical center

Based on VSDA2

KS	05/30/2008	06/29/2008	Fire Safety
KS	05/30/2008	06/29/2008	Fire Safety
KS	08/19/2009	09/18/2009	Fire Safety
KS	08/19/2009	09/18/2009	Fire Safety
KS	10/22/2010	10/22/2010	Fire Safety
KS	10/22/2010	10/26/2010	Fire Safety
KS	10/22/2010	10/29/2010	Fire Safety
KS	09/18/2007	09/20/2007	Fire Safety
KS	09/18/2007	09/24/2007	Fire Safety
KS	09/18/2007	09/20/2007	Fire Safety

	obstructions and can be used at all times.	
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY

sumner regional medical center

Based on VSDA2

KS	09/18/2007	09/21/2007	Fire Safety
KS	09/18/2007	09/21/2007	Fire Safety
KS	09/18/2007	09/20/2007	Fire Safety
KS	09/18/2007	09/20/2007	Fire Safety
KS	09/18/2007	09/21/2007	Fire Safety
KS	09/18/2007	09/21/2007	Fire Safety
KS	09/18/2007	09/24/2007	Fire Safety
KS	09/18/2007	09/21/2007	Fire Safety
KS	12/11/2008	12/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY

KS	12/11/2008	12/30/2008	Fire Safety
KS	12/11/2008	12/11/2008	Fire Safety
KS	12/11/2008	12/30/2008	Fire Safety
KS	12/11/2008	12/15/2008	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	12/12/2008	Fire Safety
KS	12/11/2008	12/12/2008	Fire Safety
KS	12/11/2008	12/12/2008	Fire Safety
KS	02/16/2010	02/16/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls	Widespread

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175338	BALDWIN HEALTHCARE & REHAB CTR	BALDWIN CITY
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA

KS	02/16/2010	02/16/2010	Fire Safety
KS	02/16/2010	02/16/2010	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/05/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/07/2008	Fire Safety

	common areas by walls constructed to limit the passage of smoke.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA

sumner regional medical center

Based on VSDA2

KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	02/29/2008	03/29/2008	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA
175340	ALDERSGATE VILLAGE	TOPEKA

KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	03/04/2009	04/04/2009	Fire Safety
KS	05/27/2010	05/27/2010	Fire Safety
KS	05/27/2010	05/27/2010	Fire Safety
KS	05/27/2010	05/27/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175340	ALDERSGATE VILLAGE	TOPEKA
175343	CLARIDGE COURT	PRAIRIE VILLAGE
175343	CLARIDGE COURT	PRAIRIE VILLAGE
175343	CLARIDGE COURT	PRAIRIE VILLAGE
175343	CLARIDGE COURT	PRAIRIE VILLAGE
175343	CLARIDGE COURT	PRAIRIE VILLAGE
175343	CLARIDGE COURT	PRAIRIE VILLAGE
175343	CLARIDGE COURT	PRAIRIE VILLAGE

sumner regional medical center

Based on VSDA2

KS	05/27/2010	05/27/2010	Fire Safety
KS	12/18/2007	12/20/2007	Fire Safety
KS	12/18/2007	12/26/2007	Fire Safety
KS	12/18/2007	12/18/2007	Fire Safety
KS	12/18/2007	12/27/2007	Fire Safety
KS	03/24/2010	03/30/2010	Fire Safety
KS	03/24/2010	03/26/2010	Fire Safety
KS	03/24/2010	03/26/2010	Fire Safety

	obstructions and can be used at all times.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175343	CLARIDGE COURT	PRAIRIE VILLAGE
175343	CLARIDGE COURT	PRAIRIE VILLAGE
175343	CLARIDGE COURT	PRAIRIE VILLAGE
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA

sumner regional medical center

Based on VSDA2

KS	03/24/2010	03/26/2010	Fire Safety
KS	03/24/2010	03/26/2010	Fire Safety
KS	03/24/2010	03/29/2010	Fire Safety
KS	10/18/2007	11/16/2007	Fire Safety
KS	10/18/2007	11/16/2007	Fire Safety
KS	10/18/2007	11/16/2007	Fire Safety
KS	10/18/2007	11/16/2007	Fire Safety
KS	10/18/2007	11/16/2007	Fire Safety
KS	10/18/2007	11/16/2007	Fire Safety
KS	10/18/2007	10/31/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA

sumner regional medical center

Based on VSDA2

KS	10/18/2007	11/16/2007	Fire Safety
KS	10/18/2007	11/16/2007	Fire Safety
KS	10/18/2007	11/16/2007	Fire Safety
KS	10/18/2007	11/16/2007	Fire Safety
KS	01/09/2009	02/06/2009	Fire Safety
KS	01/09/2009	02/06/2009	Fire Safety
KS	01/09/2009	02/06/2009	Fire Safety
KS	01/09/2009	02/06/2009	Fire Safety
KS	01/09/2009	02/06/2009	Fire Safety

	permitted or did not provide ashtrays where smoking was allowed.	
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175344	SANDPIPER HEALTHCARE & REHABILITATION CENTER LLC	WICHITA
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT

KS	01/09/2009	02/06/2009	Fire Safety
KS	01/09/2009	02/06/2009	Fire Safety
KS	02/15/2010	02/23/2010	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety

	allowed.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT

KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety
KS	04/22/2008	05/22/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT
175345	PINECREST NURSING HOME	HUMBOLDT

sumner regional medical center

Based on VSDA2

KS	04/22/2008	05/22/2008	Fire Safety
KS	05/20/2009	06/15/2009	Fire Safety
KS	05/20/2009	06/15/2009	Fire Safety
KS	05/20/2009	06/15/2009	Fire Safety
KS	05/20/2009	06/15/2009	Fire Safety
KS	08/17/2010	09/15/2010	Fire Safety
KS	08/17/2010	09/15/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175345	PINECREST NURSING HOME	HUMBOLDT
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA

sumner regional medical center

Based on VSDA2

KS	08/17/2010	09/15/2010	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety
KS	12/03/2007	12/31/2007	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety
KS	03/23/2009	04/22/2009	Fire Safety
KS	03/23/2009	04/22/2009	Fire Safety
KS	03/23/2009	04/22/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA

sumner regional medical center

Based on VSDA2

KS	03/23/2009	04/22/2009	Fire Safety
KS	03/23/2009	04/22/2009	Fire Safety
KS	03/23/2009	04/22/2009	Fire Safety
KS	03/23/2009	04/22/2009	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety

	for fire alarm systems.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175346	ALMA MANOR	ALMA
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS

KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	08/15/2007	10/02/2007	Fire Safety
KS	08/15/2007	09/15/2007	Fire Safety
KS	08/15/2007	09/15/2007	Fire Safety
KS	08/15/2007	09/15/2007	Fire Safety
KS	08/15/2007	09/15/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS

sumner regional medical center

Based on VSDA2

KS	08/15/2007	09/15/2007	Fire Safety
KS	08/15/2007	09/15/2007	Fire Safety
KS	08/15/2007	09/15/2007	Fire Safety
KS	08/15/2007	09/15/2007	Fire Safety
KS	08/15/2007	09/15/2007	Fire Safety
KS	08/15/2007	09/15/2007	Fire Safety
KS	09/30/2008	10/10/2008	Fire Safety
KS	09/30/2008	10/29/2008	Fire Safety
KS	09/30/2008	10/30/2008	Fire Safety
KS	09/30/2008	10/30/2008	Fire Safety
KS	09/30/2008	10/30/2008	Fire Safety
KS	09/30/2008	10/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation,	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS
175347	GOOD SAMARITAN SOCIETY - ST FRANCIS	ST FRANCIS

sumner regional medical center

Based on VSDA2

KS	09/30/2008	10/30/2008	Fire Safety
KS	09/30/2008	10/30/2008	Fire Safety
KS	09/30/2008	10/30/2008	Fire Safety
KS	09/30/2008	10/30/2008	Fire Safety
KS	09/30/2008	10/30/2008	Fire Safety
KS	10/27/2009	10/27/2009	Fire Safety
KS	10/27/2009	10/27/2009	Fire Safety
KS	10/27/2009	10/27/2009	Fire Safety
KS	10/27/2009	11/27/2009	Fire Safety
KS	10/27/2009	11/27/2009	Fire Safety

	maintenance and testing program for fire alarm systems.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT

KS	04/30/2008	05/06/2008	Fire Safety
KS	04/30/2008	05/05/2008	Fire Safety
KS	04/30/2008	05/07/2008	Fire Safety
KS	04/30/2008	05/02/2008	Fire Safety
KS	04/30/2008	05/26/2008	Fire Safety
KS	04/30/2008	05/26/2008	Fire Safety
KS	04/30/2008	05/07/2008	Fire Safety
KS	04/30/2008	05/15/2008	Fire Safety
KS	04/30/2008	05/07/2008	Fire Safety
KS	04/30/2008	05/07/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT

sumner regional medical center

Based on VSDA2

KS	04/30/2008	05/07/2008	Fire Safety
KS	04/30/2008	05/07/2008	Fire Safety
KS	04/30/2008	05/07/2008	Fire Safety
KS	04/30/2008	05/07/2008	Fire Safety
KS	04/30/2008	05/07/2008	Fire Safety
KS	04/30/2008	05/07/2008	Fire Safety
KS	04/30/2008	05/26/2008	Fire Safety
KS	06/18/2009	07/03/2009	Fire Safety
KS	06/18/2009	07/10/2009	Fire Safety
KS	06/18/2009	07/08/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT
175348	HILLTOP LODGE NURSING HOME	BELOIT

sumner regional medical center

Based on VSDA2

KS	06/18/2009	07/03/2009	Fire Safety
KS	06/18/2009	06/24/2009	Fire Safety
KS	06/18/2009	06/30/2009	Fire Safety
KS	06/18/2009	06/23/2009	Fire Safety
KS	06/18/2009	06/30/2009	Fire Safety
KS	06/18/2009	07/03/2009	Fire Safety
KS	06/18/2009	07/17/2009	Fire Safety
KS	06/18/2009	06/25/2009	Fire Safety
KS	06/18/2009	06/18/2009	Fire Safety
KS	06/18/2009	06/23/2009	Fire Safety
KS	09/09/2010	09/14/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175348	HILLTOP LODGE NURSING HOME	BELOIT
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE

sumner regional medical center

Based on VSDA2

KS	09/09/2010	09/15/2010	Fire Safety
KS	10/04/2007	12/05/2007	Fire Safety
KS	10/04/2007	11/03/2007	Fire Safety
KS	10/04/2007	11/03/2007	Fire Safety
KS	10/04/2007	12/05/2007	Fire Safety
KS	10/04/2007	12/05/2007	Fire Safety
KS	10/04/2007	11/03/2007	Fire Safety
KS	10/04/2007	10/12/2007	Fire Safety
KS	10/04/2007	10/31/2007	Fire Safety
KS	10/04/2007	11/03/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE

KS	10/04/2007	10/04/2007	Fire Safety
KS	10/04/2007	10/31/2007	Fire Safety
KS	10/04/2007	12/26/2007	Fire Safety
KS	10/04/2007	11/03/2007	Fire Safety
KS	10/04/2007	10/08/2007	Fire Safety
KS	10/04/2007	10/04/2007	Fire Safety
KS	11/24/2008	12/01/2008	Fire Safety
KS	11/24/2008	12/01/2008	Fire Safety
KS	11/24/2008	12/01/2008	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

harm

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE

sumner regional medical center

Based on VSDA2

KS	11/24/2008	12/01/2008	Fire Safety
KS	11/24/2008	12/01/2008	Fire Safety
KS	11/24/2008	12/01/2008	Fire Safety
KS	11/24/2008	12/01/2008	Fire Safety
KS	11/24/2008	12/01/2008	Fire Safety
KS	11/24/2008	12/01/2008	Fire Safety
KS	12/01/2009	12/31/2009	Fire Safety
KS	12/01/2009	12/10/2009	Fire Safety
KS	12/01/2009	12/31/2009	Fire Safety
KS	12/01/2009	12/31/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175350	CAMBRIDGE PLACE	MARYSVILLE
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER

KS	12/01/2009	12/31/2009	Fire Safety
KS	12/01/2009	12/03/2009	Fire Safety
KS	12/01/2009	12/15/2009	Fire Safety
KS	12/01/2009	12/31/2009	Fire Safety
KS	12/01/2009	12/31/2009	Fire Safety
KS	08/14/2007	09/13/2007	Fire Safety
KS	08/14/2007	09/13/2007	Fire Safety
KS	08/14/2007	09/13/2007	Fire Safety
KS	08/14/2007	09/13/2007	Fire Safety

	detectors.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER

sumner regional medical center

Based on VSDA2

KS	08/14/2007	09/13/2007	Fire Safety
KS	08/14/2007	09/13/2007	Fire Safety
KS	08/14/2007	09/13/2007	Fire Safety
KS	08/14/2007	09/13/2007	Fire Safety
KS	10/17/2008	10/21/2008	Fire Safety
KS	10/17/2008	11/06/2008	Fire Safety
KS	10/17/2008	10/20/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety

	at least 1 1/2 hours.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER

sumner regional medical center

Based on VSDA2

KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	10/20/2008	Fire Safety
KS	10/13/2009	11/10/2009	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175351	MEDICALODGES CLAY CENTER	CLAY CENTER
175353	ARMA CARE CENTER LLC	ARMA

sumner regional medical center

Based on VSDA2

KS	10/13/2009	11/10/2009	Fire Safety
KS	10/13/2009	10/15/2009	Fire Safety
KS	10/13/2009	11/10/2009	Fire Safety
KS	10/13/2009	11/10/2009	Fire Safety
KS	10/13/2009	11/10/2009	Fire Safety
KS	10/13/2009	11/10/2009	Fire Safety
KS	10/13/2009	11/10/2009	Fire Safety
KS	07/15/2008	08/13/2008	Fire Safety

	extinguishing system.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	no-smoking signs where oxygen is used.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175353	ARMA CARE CENTER LLC	ARMA
175353	ARMA CARE CENTER LLC	ARMA
175353	ARMA CARE CENTER LLC	ARMA
175353	ARMA CARE CENTER LLC	ARMA
175353	ARMA CARE CENTER LLC	ARMA
175353	ARMA CARE CENTER LLC	ARMA
175353	ARMA CARE CENTER LLC	ARMA
175354	WOODHAVEN CARE CENTER	ELLINWOOD
175354	WOODHAVEN CARE CENTER	ELLINWOOD
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE

sumner regional medical center

Based on VSDA2

KS	07/15/2008	08/13/2008	Fire Safety
KS	07/15/2008	08/13/2008	Fire Safety
KS	07/15/2008	08/13/2008	Fire Safety
KS	07/15/2008	08/15/2008	Fire Safety
KS	07/15/2008	08/13/2008	Fire Safety
KS	07/15/2008	08/13/2008	Fire Safety
KS	07/15/2008	08/13/2008	Fire Safety
KS	07/15/2008	08/13/2008	Fire Safety
KS	08/16/2010	09/14/2010	Fire Safety
KS	08/16/2010	09/14/2010	Fire Safety
KS	06/03/2008	07/02/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	COUNTY	
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE

KS	06/03/2008	07/02/2008	Fire Safety
KS	06/03/2008	07/02/2008	Fire Safety
KS	06/03/2008	07/02/2008	Fire Safety
KS	06/03/2008	07/02/2008	Fire Safety
KS	06/03/2008	07/02/2008	Fire Safety
KS	06/03/2008	07/02/2008	Fire Safety
KS	06/03/2008	07/02/2008	Fire Safety
KS	06/03/2008	07/02/2008	Fire Safety
KS	08/05/2009	08/05/2009	Fire Safety

	common walls.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175355	EVERGREEN COMMUNITY OF JOHNSON COUNTY	OLATHE
175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN
175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN
175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN
175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN
175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN
175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN

sumner regional medical center

Based on VSDA2

KS	08/05/2009	08/07/2009	Fire Safety
KS	08/05/2009	08/12/2009	Fire Safety
KS	11/03/2010	11/03/2010	Fire Safety
KS	11/03/2010	11/03/2010	Fire Safety
KS	11/03/2010	11/12/2010	Fire Safety
KS	03/25/2008	04/24/2008	Fire Safety
KS	03/25/2008	04/24/2008	Fire Safety
KS	03/25/2008	04/24/2008	Fire Safety
KS	03/25/2008	04/24/2008	Fire Safety
KS	03/25/2008	03/27/2008	Fire Safety
KS	03/31/2009	04/30/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN
175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN
175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN
175356	GOOD SAMARITAN SOCIETY - DECATUR COUNTY	OBERLIN
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON

KS	03/31/2009	04/30/2009	Fire Safety
KS	03/31/2009	04/30/2009	Fire Safety
KS	03/31/2009	04/30/2009	Fire Safety
KS	04/20/2010	04/23/2010	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON

sumner regional medical center

Based on VSDA2

KS	10/24/2007	11/23/2007	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety
KS	10/24/2007	11/23/2007	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety

	allowed.	
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON

sumner regional medical center

Based on VSDA2

KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	10/07/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175357	SUMNER COUNTY CARE CENTER LLC	WELLINGTON
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO

KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	10/07/2008	11/06/2008	Fire Safety
KS	01/19/2010	02/11/2010	Fire Safety
KS	01/19/2010	02/11/2010	Fire Safety
KS	01/19/2010	02/11/2010	Fire Safety
KS	01/19/2010	02/11/2010	Fire Safety
KS	01/19/2010	02/11/2010	Fire Safety
KS	01/19/2010	02/11/2010	Fire Safety
KS	01/19/2010	02/11/2010	Fire Safety
KS	09/10/2008	10/09/2008	Fire Safety

	flammable curtains.	
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO

sumner regional medical center

Based on VSDA2

KS	09/10/2008	10/09/2008	Fire Safety
KS	09/10/2008	10/09/2008	Fire Safety
KS	09/10/2008	10/09/2008	Fire Safety
KS	09/10/2008	10/02/2008	Fire Safety
KS	09/10/2008	10/02/2008	Fire Safety
KS	09/10/2008	09/18/2008	Fire Safety
KS	09/10/2008	10/09/2008	Fire Safety
KS	09/10/2008	10/09/2008	Fire Safety
KS	09/10/2008	10/09/2008	Fire Safety
KS	10/01/2009	10/30/2009	Fire Safety
KS	10/01/2009	10/30/2009	Fire Safety

	materials.	
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO

sumner regional medical center

Based on VSDA2

KS	10/01/2009	10/30/2009	Fire Safety
KS	10/01/2009	10/30/2009	Fire Safety
KS	11/19/2010	12/15/2010	Fire Safety
KS	11/19/2010	11/23/2010	Fire Safety
KS	11/19/2010	12/15/2010	Fire Safety
KS	11/19/2010	12/15/2010	Fire Safety
KS	11/19/2010	11/19/2010	Fire Safety
KS	11/19/2010	12/15/2010	Fire Safety
KS	11/19/2010	11/19/2010	Fire Safety
KS	11/19/2010	12/15/2010	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Interior Finish Deficiencies	fire-resistant interior walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Fire Alarm Systems Deficiencies	an approved installation,	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175359	GOOD SAMARITAN SOCIETY - VALLEY VISTA	WAMEGO
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY

sumner regional medical center

Based on VSDA2

KS	11/19/2010	11/23/2010	Fire Safety
KS	11/19/2010	12/15/2010	Fire Safety
KS	11/19/2010	12/15/2010	Fire Safety
KS	09/18/2007	10/01/2007	Fire Safety
KS	09/18/2007	10/17/2007	Fire Safety
KS	09/18/2007	10/01/2007	Fire Safety
KS	09/18/2007	10/01/2007	Fire Safety
KS	09/18/2007	10/01/2007	Fire Safety
KS	09/15/2008	10/13/2008	Fire Safety
KS	09/15/2008	09/22/2008	Fire Safety

	maintenance and testing program for fire alarm systems.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY

sumner regional medical center

Based on VSDA2

KS	09/15/2008	10/13/2008	Fire Safety
KS	09/15/2008	10/13/2008	Fire Safety
KS	09/15/2008	10/13/2008	Fire Safety
KS	09/15/2008	09/22/2008	Fire Safety
KS	09/15/2008	10/16/2008	Fire Safety
KS	09/15/2008	09/29/2008	Fire Safety
KS	10/22/2009	10/30/2009	Fire Safety
KS	10/22/2009	10/30/2009	Fire Safety
KS	10/22/2009	10/30/2009	Fire Safety

	would resist fire for at least one hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175360	PETERSON NURSING HOME	OSAGE CITY
175360	PETERSON NURSING HOME	OSAGE CITY
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND

sumner regional medical center

Based on VSDA2

KS	10/22/2009	10/30/2009	Fire Safety
KS	10/22/2009	10/30/2009	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety
KS	11/27/2007	12/28/2007	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN	GOODLAND

sumner regional medical center

Based on VSDA2

KS	11/27/2007	12/26/2007	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety
KS	11/27/2007	12/26/2007	Fire Safety
KS	12/17/2008	01/17/2009	Fire Safety
KS	12/17/2008	01/17/2009	Fire Safety
KS	12/17/2008	01/17/2009	Fire Safety
KS	12/17/2008	01/17/2009	Fire Safety
KS	12/17/2008	01/17/2009	Fire Safety
KS	12/17/2008	01/17/2009	Fire Safety
KS	12/17/2008	01/17/2009	Fire Safety
KS	12/17/2008	01/17/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Furnishings and Decorations Deficiencies	properly sized and located linen	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	COUNTY	
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175361	GOOD SAMARITAN SOCIETY - SHERMAN COUNTY	GOODLAND
175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC

KS	12/17/2008	01/17/2009	Fire Safety
KS	12/17/2008	01/17/2009	Fire Safety
KS	04/18/2008	04/21/2008	Fire Safety
KS	04/18/2008	04/21/2008	Fire Safety
KS	04/18/2008	04/21/2008	Fire Safety
KS	04/18/2008	04/21/2008	Fire Safety
KS	04/18/2008	04/21/2008	Fire Safety
KS	04/08/2009	04/10/2009	Fire Safety
KS	04/08/2009	04/10/2009	Fire Safety
KS	04/08/2009	04/10/2009	Fire Safety

	or trash receptacles.	
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Electrical Deficiencies	properly installed electrical wiring	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC
175363	SUNSET MANOR	FRONTENAC
175366	GOOD SAMARITAN SOCIETY - ATWOOD	ATWOOD
175366	GOOD SAMARITAN SOCIETY - ATWOOD	ATWOOD
175366	GOOD SAMARITAN SOCIETY - ATWOOD	ATWOOD
175366	GOOD SAMARITAN SOCIETY - ATWOOD	ATWOOD
175366	GOOD SAMARITAN SOCIETY - ATWOOD	ATWOOD
175366	GOOD SAMARITAN SOCIETY - ATWOOD	ATWOOD

sumner regional medical center

Based on VSDA2

KS	05/13/2010	05/13/2010	Fire Safety
KS	05/13/2010	06/10/2010	Fire Safety
KS	05/13/2010	05/20/2010	Fire Safety
KS	05/13/2010	05/13/2010	Fire Safety
KS	02/21/2008	03/21/2008	Fire Safety
KS	02/21/2008	03/21/2008	Fire Safety
KS	03/10/2009	04/08/2009	Fire Safety
KS	03/10/2009	04/08/2009	Fire Safety
KS	03/10/2009	04/08/2009	Fire Safety
KS	03/10/2009	04/08/2009	Fire Safety

	and equipment.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	corridors or aisles that are unobstructed and are at least 8 feet in width.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175366	GOOD SAMARITAN SOCIETY - ATWOOD	ATWOOD
175366	GOOD SAMARITAN SOCIETY - ATWOOD	ATWOOD
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE

sumner regional medical center

Based on VSDA2

KS	03/10/2009	04/08/2009	Fire Safety
KS	03/08/2010	03/08/2010	Fire Safety
KS	05/22/2008	06/19/2008	Fire Safety
KS	05/22/2008	06/19/2008	Fire Safety
KS	05/22/2008	06/19/2008	Fire Safety
KS	05/22/2008	06/19/2008	Fire Safety
KS	05/22/2008	06/19/2008	Fire Safety
KS	05/22/2008	06/19/2008	Fire Safety
KS	05/22/2008	06/19/2008	Fire Safety

	have been maintained in working order.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175369	RUSH COUNTY NURSING HOME	LA CROSSE
175373	LIFE CARE CENTER OF BURLINGTON	BURLINGTON
175373	LIFE CARE CENTER OF BURLINGTON	BURLINGTON
175373	LIFE CARE CENTER OF BURLINGTON	BURLINGTON

sumner regional medical center

Based on VSDA2

KS	05/22/2008	06/19/2008	Fire Safety
KS	05/22/2008	06/19/2008	Fire Safety
KS	05/21/2009	06/17/2009	Fire Safety
KS	05/21/2009	06/17/2009	Fire Safety
KS	05/21/2009	06/17/2009	Fire Safety
KS	05/21/2009	06/17/2009	Fire Safety
KS	06/01/2010	06/21/2010	Fire Safety
KS	06/01/2010	06/08/2010	Fire Safety
KS	06/10/2008	06/21/2008	Fire Safety
KS	06/10/2008	06/26/2008	Fire Safety
KS	06/10/2008	06/25/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175373	LIFE CARE CENTER OF BURLINGTON	BURLINGTON
175373	LIFE CARE CENTER OF BURLINGTON	BURLINGTON
175373	LIFE CARE CENTER OF BURLINGTON	BURLINGTON
175373	LIFE CARE CENTER OF BURLINGTON	BURLINGTON
175373	LIFE CARE CENTER OF BURLINGTON	BURLINGTON
175373	LIFE CARE CENTER OF BURLINGTON	BURLINGTON
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA

KS	06/10/2008	06/11/2008	Fire Safety
KS	06/10/2008	06/15/2008	Fire Safety
KS	06/11/2009	06/11/2009	Fire Safety
KS	06/11/2009	06/22/2009	Fire Safety
KS	06/11/2009	06/11/2009	Fire Safety
KS	08/16/2010	08/23/2010	Fire Safety
KS	11/28/2007	12/30/2007	Fire Safety
KS	11/28/2007	12/03/2007	Fire Safety
KS	11/28/2007	11/30/2007	Fire Safety
KS	11/28/2007	12/28/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175374	EASTRIDGE	CENTRALIA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA

sumner regional medical center

Based on VSDA2

KS	11/28/2007	12/03/2007	Fire Safety
KS	11/28/2007	12/28/2007	Fire Safety
KS	10/13/2008	11/12/2008	Fire Safety
KS	10/13/2008	11/12/2008	Fire Safety
KS	10/13/2008	11/12/2008	Fire Safety
KS	01/08/2010	01/28/2010	Fire Safety
KS	01/08/2010	01/28/2010	Fire Safety
KS	01/08/2010	01/28/2010	Fire Safety
KS	01/08/2010	01/28/2010	Fire Safety
KS	01/08/2010	01/28/2010	Fire Safety
KS	07/17/2008	08/17/2008	Fire Safety
KS	07/17/2008	08/17/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA

sumner regional medical center

Based on VSDA2

KS	07/17/2008	08/17/2008	Fire Safety
KS	07/17/2008	08/17/2008	Fire Safety
KS	07/17/2008	08/17/2008	Fire Safety
KS	07/17/2008	08/17/2008	Fire Safety
KS	07/17/2008	08/17/2008	Fire Safety
KS	07/17/2008	08/17/2008	Fire Safety
KS	07/17/2008	08/17/2008	Fire Safety
KS	07/17/2008	08/17/2008	Fire Safety
KS	08/27/2009	09/02/2009	Fire Safety
KS	08/27/2009	09/02/2009	Fire Safety

	close on the activation of a fire alarm or smoke detectors.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA

sumner regional medical center

Based on VSDA2

KS	08/27/2009	09/25/2009	Fire Safety
KS	08/27/2009	09/02/2009	Fire Safety
KS	08/27/2009	09/02/2009	Fire Safety
KS	08/27/2009	09/02/2009	Fire Safety
KS	08/27/2009	09/02/2009	Fire Safety
KS	08/27/2009	09/15/2009	Fire Safety
KS	08/27/2009	09/18/2009	Fire Safety
KS	12/02/2010	12/08/2010	Fire Safety
KS	12/02/2010	12/28/2010	Fire Safety
KS	12/02/2010	12/02/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175376	APOSTOLIC CHRISTIAN HOME	SABETHA
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY

KS	12/02/2010	12/10/2010	Fire Safety
KS	12/02/2010	12/13/2010	Fire Safety
KS	12/02/2010	12/03/2010	Fire Safety
KS	12/02/2010	12/15/2010	Fire Safety
KS	12/02/2010	12/03/2010	Fire Safety
KS	12/02/2010	12/08/2010	Fire Safety
KS	12/02/2010	12/29/2010	Fire Safety
KS	12/02/2010	12/17/2010	Fire Safety
KS	05/13/2008	05/22/2008	Fire Safety
KS	05/13/2008	06/11/2008	Fire Safety

	resist smoke for at least 20 minutes.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY

sumner regional medical center

Based on VSDA2

KS	05/13/2008	06/11/2008	Fire Safety
KS	05/13/2008	05/15/2008	Fire Safety
KS	05/13/2008	06/11/2008	Fire Safety
KS	05/13/2008	06/11/2008	Fire Safety
KS	05/13/2008	06/11/2008	Fire Safety
KS	05/13/2008	05/27/2008	Fire Safety
KS	05/13/2008	06/11/2008	Fire Safety
KS	05/13/2008	06/11/2008	Fire Safety
KS	05/13/2008	06/11/2008	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175377	TRINITY MANOR	DODGE CITY
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH

KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	05/19/2009	06/19/2009	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety

	and equipment.	
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Exits and Egress Deficiencies	corridors or aisles that are unobstructed and are at least 8 feet in width.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

		HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON

sumner regional medical center

Based on VSDA2

KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety

	common areas by walls constructed to limit the passage of smoke.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON

sumner regional medical center

Based on VSDA2

KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety
KS	12/20/2007	12/31/2007	Fire Safety
KS	12/20/2007	12/20/2007	Fire Safety
KS	12/20/2007	01/19/2008	Fire Safety
KS	03/18/2009	03/27/2009	Fire Safety
KS	03/18/2009	04/10/2009	Fire Safety
KS	03/18/2009	03/27/2009	Fire Safety
KS	03/18/2009	03/18/2009	Fire Safety
KS	05/27/2010	06/04/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175379	MENNONITE FRIENDSHIP MANOR INC	SOUTH HUTCHINSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON

sumner regional medical center

Based on VSDA2

KS	05/27/2010	06/26/2010	Fire Safety
KS	12/12/2007	12/21/2007	Fire Safety
KS	12/12/2007	12/21/2007	Fire Safety
KS	12/12/2007	01/04/2008	Fire Safety
KS	12/12/2007	02/11/2008	Fire Safety
KS	12/12/2007	12/17/2007	Fire Safety
KS	12/12/2007	01/12/2008	Fire Safety
KS	12/12/2007	12/31/2007	Fire Safety
KS	12/12/2007	01/12/2008	Fire Safety
KS	12/24/2008	12/24/2008	Fire Safety
KS	12/24/2008	01/23/2009	Fire Safety

sumner regional medical center

Based on VSDA2

	alarm system.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175380	THE CEDARS	MCPHERSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON

KS	12/24/2008	01/09/2009	Fire Safety
KS	12/24/2008	01/23/2009	Fire Safety
KS	01/25/2010	02/24/2010	Fire Safety
KS	01/25/2010	02/24/2010	Fire Safety
KS	05/28/2008	06/27/2008	Fire Safety
KS	05/28/2008	06/06/2008	Fire Safety
KS	05/28/2008	06/27/2008	Fire Safety
KS	05/28/2008	06/27/2008	Fire Safety
KS	05/28/2008	06/06/2008	Fire Safety
KS	05/28/2008	06/27/2008	Fire Safety

	times.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175383	WESLEY TOWERS INC	HUTCHINSON
175384	FORT SCOTT MANOR	FORT SCOTT

sumner regional medical center

Based on VSDA2

KS	07/23/2009	07/27/2009	Fire Safety
KS	07/23/2009	08/22/2009	Fire Safety
KS	07/23/2009	07/27/2009	Fire Safety
KS	07/23/2009	07/27/2009	Fire Safety
KS	07/23/2009	07/27/2009	Fire Safety
KS	07/23/2009	07/27/2009	Fire Safety
KS	09/21/2010	10/05/2010	Fire Safety
KS	09/21/2010	10/10/2010	Fire Safety
KS	09/26/2007	10/26/2007	Fire Safety

	and equipment.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT

sumner regional medical center

Based on VSDA2

KS	09/26/2007	09/28/2007	Fire Safety
KS	09/26/2007	10/26/2007	Fire Safety
KS	09/26/2007	10/26/2007	Fire Safety
KS	09/26/2007	10/26/2007	Fire Safety
KS	09/26/2007	10/26/2007	Fire Safety
KS	09/26/2007	09/26/2007	Fire Safety
KS	09/26/2007	10/26/2007	Fire Safety
KS	09/26/2007	10/26/2007	Fire Safety
KS	09/26/2007	10/26/2007	Fire Safety
KS	09/26/2007	10/26/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT

KS	08/13/2008	08/13/2008	Fire Safety
KS	08/13/2008	08/14/2008	Fire Safety
KS	08/13/2008	08/14/2008	Fire Safety
KS	08/13/2008	08/20/2008	Fire Safety
KS	08/13/2008	08/22/2008	Fire Safety
KS	08/13/2008	08/22/2008	Fire Safety
KS	08/13/2008	08/14/2008	Fire Safety
KS	08/06/2009	08/12/2009	Fire Safety
KS	08/06/2009	08/12/2009	Fire Safety

	and equipment.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175384	FORT SCOTT MANOR	FORT SCOTT
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON

KS	08/06/2009	08/18/2009	Fire Safety
KS	08/06/2009	08/13/2009	Fire Safety
KS	08/06/2009	08/14/2009	Fire Safety
KS	08/06/2009	08/21/2009	Fire Safety
KS	08/06/2009	08/12/2009	Fire Safety
KS	08/06/2009	08/12/2009	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety

	for one hour or an approved fire extinguishing system.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON

KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	04/09/2008	04/09/2008	Fire Safety
KS	04/09/2008	05/09/2008	Fire Safety
KS	05/13/2009	06/01/2009	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can	Widespread

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Potential for minimal harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175385	ASBURY PARK	NEWTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON

sumner regional medical center

Based on VSDA2

KS	05/13/2009	06/01/2009	Fire Safety
KS	05/13/2009	06/01/2009	Fire Safety
KS	05/13/2009	06/01/2009	Fire Safety
KS	05/13/2009	06/01/2009	Fire Safety
KS	05/13/2009	06/01/2009	Fire Safety
KS	05/13/2009	06/01/2009	Fire Safety
KS	04/29/2008	05/26/2008	Fire Safety
KS	04/29/2008	05/26/2008	Fire Safety
KS	04/29/2008	05/26/2008	Fire Safety

	resist smoke for at least 20 minutes.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Potential for minimal harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON

sumner regional medical center

Based on VSDA2

KS	04/29/2008	05/26/2008	Fire Safety
KS	04/29/2008	05/26/2008	Fire Safety
KS	04/29/2008	05/26/2008	Fire Safety
KS	04/29/2008	05/26/2008	Fire Safety
KS	04/29/2008	05/26/2008	Fire Safety
KS	06/17/2009	07/15/2009	Fire Safety
KS	06/17/2009	07/15/2009	Fire Safety
KS	06/17/2009	07/15/2009	Fire Safety
KS	06/17/2009	07/15/2009	Fire Safety
KS	06/17/2009	07/15/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175386	SCHOWALTER VILLA	HESSTON
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO

sumner regional medical center

Based on VSDA2

KS	06/17/2009	07/15/2009	Fire Safety
KS	06/14/2010	07/13/2010	Fire Safety
KS	06/14/2010	07/13/2010	Fire Safety
KS	06/14/2010	07/13/2010	Fire Safety
KS	06/14/2010	07/13/2010	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	11/21/2007	Fire Safety
KS	11/21/2007	11/30/2007	Fire Safety
KS	11/21/2007	11/25/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO

sumner regional medical center

Based on VSDA2

KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	11/30/2007	Fire Safety
KS	11/21/2007	11/21/2007	Fire Safety
KS	11/21/2007	11/30/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	12/16/2008	12/23/2008	Fire Safety
KS	12/16/2008	12/23/2008	Fire Safety
KS	12/16/2008	01/14/2009	Fire Safety
KS	12/16/2008	12/23/2008	Fire Safety
KS	12/16/2008	01/14/2009	Fire Safety

	times.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175387	PARKSIDE HOMES	HILLSBORO
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER

sumner regional medical center

Based on VSDA2

KS	12/16/2008	12/19/2008	Fire Safety
KS	01/27/2010	01/27/2010	Fire Safety
KS	01/27/2010	01/27/2010	Fire Safety
KS	02/26/2008	03/26/2008	Fire Safety
KS	02/26/2008	03/26/2008	Fire Safety
KS	02/26/2008	03/26/2008	Fire Safety
KS	02/26/2008	02/29/2008	Fire Safety
KS	02/26/2008	03/26/2008	Fire Safety
KS	02/26/2008	02/27/2008	Fire Safety

	each shift under varying conditions.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175389	YATES CENTER NURSING & REHABILITATION LLC	YATES CENTER
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA

sumner regional medical center

Based on VSDA2

KS	02/26/2008	02/26/2008	Fire Safety
KS	02/26/2008	02/26/2008	Fire Safety
KS	03/11/2009	04/09/2009	Fire Safety
KS	03/11/2009	04/09/2009	Fire Safety
KS	03/11/2009	03/17/2009	Fire Safety
KS	03/11/2009	03/31/2009	Fire Safety
KS	03/11/2009	03/23/2009	Fire Safety
KS	07/16/2008	08/12/2008	Fire Safety
KS	07/16/2008	08/12/2008	Fire Safety
KS	07/16/2008	08/12/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Isolated
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA
175396	CHETOPA MANOR	CHETOPA

KS	07/16/2008	08/12/2008	Fire Safety
KS	07/16/2008	07/16/2008	Fire Safety
KS	07/16/2008	08/12/2008	Fire Safety
KS	07/16/2008	08/12/2008	Fire Safety
KS	07/16/2008	07/16/2008	Fire Safety
KS	07/16/2008	08/12/2008	Fire Safety
KS	08/26/2009	08/26/2009	Fire Safety
KS	08/26/2009	09/01/2009	Fire Safety
KS	08/26/2009	08/28/2009	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE

KS	06/25/2008	07/24/2008	Fire Safety
KS	06/25/2008	06/25/2008	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety

	order.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE

KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety
KS	08/06/2009	09/05/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175397	ROSSVILLE HEALTHCARE & REHAB CTR	ROSSVILLE
175399	CHENEY GOLDEN AGE HOME	CHENEY
175399	CHENEY GOLDEN AGE HOME	CHENEY

sumner regional medical center

Based on VSDA2

KS	08/06/2009	09/05/2009	Fire Safety
KS	11/30/2010	12/27/2010	Fire Safety
KS	11/30/2010	12/27/2010	Fire Safety
KS	11/30/2010	12/15/2010	Fire Safety
KS	11/30/2010	12/27/2010	Fire Safety
KS	11/30/2010	12/30/2010	Fire Safety
KS	11/30/2010	12/27/2010	Fire Safety
KS	07/30/2008	08/01/2008	Fire Safety
KS	07/30/2008	08/01/2008	Fire Safety

	and equipment.	
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175399	CHENEY GOLDEN AGE HOME	CHENEY
175399	CHENEY GOLDEN AGE HOME	CHENEY
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS

sumner regional medical center

Based on VSDA2

KS	07/30/2008	08/07/2008	Fire Safety
KS	09/22/2009	09/23/2009	Fire Safety
KS	10/16/2007	10/18/2007	Fire Safety
KS	10/16/2007	10/22/2007	Fire Safety
KS	10/16/2007	10/22/2007	Fire Safety
KS	10/16/2007	10/23/2007	Fire Safety
KS	01/14/2009	01/29/2009	Fire Safety
KS	01/14/2009	01/29/2009	Fire Safety
KS	01/14/2009	01/29/2009	Fire Safety
KS	01/14/2009	01/29/2009	Fire Safety

	have been maintained in working order.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS

sumner regional medical center

Based on VSDA2

KS	01/14/2009	01/21/2009	Fire Safety
KS	01/14/2009	01/17/2009	Fire Safety
KS	01/14/2009	01/29/2009	Fire Safety
KS	01/14/2009	01/29/2009	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175401	BONNER SPRINGS NURSING & REHABILITATION CENTER	BONNER SPRINGS
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON

sumner regional medical center

Based on VSDA2

KS	05/06/2010	06/03/2010	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety
KS	05/06/2010	06/03/2010	Fire Safety
KS	03/11/2008	03/27/2008	Fire Safety
KS	03/11/2008	03/11/2008	Fire Safety
KS	03/11/2008	03/17/2008	Fire Safety
KS	03/11/2008	03/13/2008	Fire Safety
KS	03/11/2008	04/08/2008	Fire Safety
KS	03/11/2008	03/12/2008	Fire Safety
KS	03/11/2008	03/13/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	an externally vented heating system.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175402	BETHEL HEALTH CARE CENTRE	NORTH NEWTON
175403	BETHESDA HOME	GOESSEL
175403	BETHESDA HOME	GOESSEL
175403	BETHESDA HOME	GOESSEL
175403	BETHESDA HOME	GOESSEL

sumner regional medical center

Based on VSDA2

KS	03/11/2008	03/18/2008	Fire Safety
KS	06/16/2009	08/25/2009	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety
KS	09/23/2010	10/08/2010	Fire Safety
KS	01/17/2008	01/17/2008	Fire Safety
KS	01/06/2009	01/06/2009	Fire Safety
KS	01/06/2009	01/09/2009	Fire Safety
KS	01/06/2009	01/07/2009	Fire Safety

sumner regional medical center

Based on VSDA2

	testing of generators.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175403	BETHESDA HOME	GOESSEL
175403	BETHESDA HOME	GOESSEL
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER

sumner regional medical center

Based on VSDA2

KS	01/06/2009	01/10/2009	Fire Safety
KS	01/06/2009	01/07/2009	Fire Safety
KS	02/26/2008	03/26/2008	Fire Safety
KS	02/26/2008	03/26/2008	Fire Safety
KS	02/26/2008	03/26/2008	Fire Safety
KS	02/26/2008	03/14/2008	Fire Safety
KS	02/26/2008	03/26/2008	Fire Safety
KS	02/26/2008	03/14/2008	Fire Safety
KS	02/26/2008	03/26/2008	Fire Safety
KS	02/26/2008	03/04/2008	Fire Safety

	for one hour or an approved fire extinguishing system.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175404	BUHLER SUNSHINE HOME	BUHLER
175405	RAY E DILLON LIVING CENTER	HUTCHINSON

sumner regional medical center

Based on VSDA2

KS	02/26/2008	03/07/2008	Fire Safety
KS	03/17/2009	03/30/2009	Fire Safety
KS	03/17/2009	04/08/2009	Fire Safety
KS	03/17/2009	03/17/2009	Fire Safety
KS	03/17/2009	03/27/2009	Fire Safety
KS	03/17/2009	03/24/2009	Fire Safety
KS	04/26/2010	05/12/2010	Fire Safety
KS	04/26/2010	05/10/2010	Fire Safety
KS	04/26/2010	05/20/2010	Fire Safety
KS	03/04/2008	04/01/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON

sumner regional medical center

Based on VSDA2

KS	03/04/2008	04/01/2008	Fire Safety
KS	03/04/2008	04/01/2008	Fire Safety
KS	03/04/2008	04/01/2008	Fire Safety
KS	03/04/2008	04/01/2008	Fire Safety
KS	03/04/2008	04/01/2008	Fire Safety
KS	03/19/2009	03/23/2009	Fire Safety
KS	03/19/2009	04/15/2009	Fire Safety
KS	03/19/2009	04/15/2009	Fire Safety
KS	03/19/2009	04/15/2009	Fire Safety

	resist smoke for at least 20 minutes.	
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175405	RAY E DILLON LIVING CENTER	HUTCHINSON
175406	PLEASANT VIEW HOME	INMAN
175406	PLEASANT VIEW HOME	INMAN
175406	PLEASANT VIEW HOME	INMAN
175406	PLEASANT VIEW HOME	INMAN
175406	PLEASANT VIEW HOME	INMAN

sumner regional medical center

Based on VSDA2

KS	03/19/2009	03/20/2009	Fire Safety
KS	03/19/2009	04/15/2009	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	06/24/2010	Fire Safety
KS	06/02/2010	06/25/2010	Fire Safety
KS	06/02/2010	06/10/2010	Fire Safety
KS	11/13/2007	12/13/2007	Fire Safety
KS	11/13/2007	12/13/2007	Fire Safety
KS	11/18/2008	11/18/2008	Fire Safety
KS	11/18/2008	11/19/2008	Fire Safety
KS	11/18/2008	11/20/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Laboratories Deficiencies	emergency showers.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175407	LIFE CARE CENTER OF WICHITA	WICHITA
175407	LIFE CARE CENTER OF WICHITA	WICHITA
175407	LIFE CARE CENTER OF WICHITA	WICHITA
175407	LIFE CARE CENTER OF WICHITA	WICHITA
175407	LIFE CARE CENTER OF WICHITA	WICHITA
175407	LIFE CARE CENTER OF WICHITA	WICHITA
175407	LIFE CARE CENTER OF WICHITA	WICHITA
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE

sumner regional medical center

Based on VSDA2

KS	09/11/2008	10/02/2008	Fire Safety
KS	09/11/2008	10/02/2008	Fire Safety
KS	09/11/2008	10/02/2008	Fire Safety
KS	09/11/2008	10/02/2008	Fire Safety
KS	09/11/2008	10/02/2008	Fire Safety
KS	10/06/2009	10/06/2009	Fire Safety
KS	10/06/2009	10/06/2009	Fire Safety
KS	01/29/2008	02/29/2008	Fire Safety
KS	01/29/2008	02/29/2008	Fire Safety

	at least 1 1/2 hours.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE

KS	01/29/2008	02/29/2008	Fire Safety
KS	01/29/2008	01/29/2008	Fire Safety
KS	01/29/2008	02/05/2008	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	04/03/2009	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	04/03/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175409	PARKVIEW CARE CENTER	OSBORNE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE

sumner regional medical center

Based on VSDA2

KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	04/08/2009	Fire Safety
KS	06/04/2010	06/30/2010	Fire Safety
KS	10/11/2007	10/31/2007	Fire Safety
KS	10/11/2007	10/31/2007	Fire Safety
KS	10/11/2007	10/31/2007	Fire Safety
KS	10/11/2007	10/31/2007	Fire Safety
KS	10/11/2007	10/31/2007	Fire Safety
KS	10/11/2007	10/31/2007	Fire Safety
KS	10/11/2007	10/31/2007	Fire Safety

	have been maintained in working order.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE

sumner regional medical center

Based on VSDA2

KS	10/11/2007	10/31/2007	Fire Safety
KS	10/11/2007	10/31/2007	Fire Safety
KS	10/11/2007	10/31/2007	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety

	ashtrays where smoking was allowed.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175410	CATHOLIC CARE CENTER	BEL AIRE
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON

sumner regional medical center

Based on VSDA2

KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	10/15/2008	11/14/2008	Fire Safety
KS	12/01/2009	12/16/2009	Fire Safety
KS	08/27/2007	08/30/2007	Fire Safety
KS	08/27/2007	08/28/2007	Fire Safety
KS	08/27/2007	09/27/2007	Fire Safety
KS	08/27/2007	09/27/2007	Fire Safety

	at least 1 1/2 hours.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON

sumner regional medical center

Based on VSDA2

KS	08/27/2007	08/28/2007	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety
KS	11/17/2008	12/17/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON
175411	COUNTRY CARE INC	EASTON

sumner regional medical center

Based on VSDA2

KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety
KS	11/10/2009	12/10/2009	Fire Safety

	and equipment.	
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND

sumner regional medical center

Based on VSDA2

KS	01/07/2008	02/06/2008	Fire Safety
KS	01/07/2008	01/07/2008	Fire Safety
KS	01/07/2008	01/07/2008	Fire Safety
KS	01/07/2008	02/06/2008	Fire Safety
KS	01/07/2008	02/06/2008	Fire Safety
KS	01/07/2008	01/14/2008	Fire Safety
KS	01/07/2008	01/14/2008	Fire Safety
KS	01/07/2008	02/06/2008	Fire Safety
KS	01/07/2008	02/06/2008	Fire Safety

	and equipment.	
Interior Finish Deficiencies	fire-resistant interior walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND

sumner regional medical center

Based on VSDA2

KS	01/07/2008	02/06/2008	Fire Safety
KS	01/07/2008	02/06/2008	Fire Safety
KS	01/07/2008	02/06/2008	Fire Safety
KS	01/07/2008	02/06/2008	Fire Safety
KS	01/07/2008	02/06/2008	Fire Safety
KS	01/07/2008	02/06/2008	Fire Safety
KS	03/11/2009	03/12/2009	Fire Safety
KS	03/11/2009	03/12/2009	Fire Safety
KS	03/11/2009	03/12/2009	Fire Safety
KS	03/11/2009	03/19/2009	Fire Safety
KS	05/03/2010	06/02/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175412	HIGHLAND HEALTHCARE & REHAB CTR	HIGHLAND
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA

sumner regional medical center

Based on VSDA2

KS	05/03/2010	06/02/2010	Fire Safety
KS	05/03/2010	06/02/2010	Fire Safety
KS	05/03/2010	06/02/2010	Fire Safety
KS	05/03/2010	06/02/2010	Fire Safety
KS	05/03/2010	06/02/2010	Fire Safety
KS	05/03/2010	06/02/2010	Fire Safety
KS	05/03/2010	06/02/2010	Fire Safety
KS	09/20/2007	11/08/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	properly working sprinkler alarm system.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Exits and Egress Deficiencies	rooms that can be unlocked from inside without a key.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA

sumner regional medical center

Based on VSDA2

KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/20/2007	10/19/2007	Fire Safety
KS	09/24/2008	10/20/2008	Fire Safety
KS	09/24/2008	10/20/2008	Fire Safety
KS	09/24/2008	10/20/2008	Fire Safety
KS	09/24/2008	10/20/2008	Fire Safety

	at least 1 1/2 hours.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175413	MEDICALODGES PAOLA	PAOLA
175414	MEMORIAL HOME	MOUNDRIDGE
175414	MEMORIAL HOME	MOUNDRIDGE
175414	MEMORIAL HOME	MOUNDRIDGE

sumner regional medical center

Based on VSDA2

KS	10/22/2009	10/28/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	11/06/2007	11/12/2007	Fire Safety
KS	11/06/2007	11/12/2007	Fire Safety
KS	11/06/2007	11/12/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175414	MEMORIAL HOME	MOUNDRIDGE
175414	MEMORIAL HOME	MOUNDRIDGE
175414	MEMORIAL HOME	MOUNDRIDGE
175414	MEMORIAL HOME	MOUNDRIDGE
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS

sumner regional medical center

Based on VSDA2

KS	11/06/2007	11/12/2007	Fire Safety
KS	01/16/2009	01/21/2009	Fire Safety
KS	01/16/2009	01/21/2009	Fire Safety
KS	01/16/2009	02/09/2009	Fire Safety
KS	11/28/2007	12/06/2007	Fire Safety
KS	11/28/2007	12/03/2007	Fire Safety
KS	11/28/2007	11/30/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	11/30/2007	Fire Safety
KS	11/28/2007	12/06/2007	Fire Safety
KS	11/28/2007	12/03/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS

sumner regional medical center

Based on VSDA2

KS	11/28/2007	12/03/2007	Fire Safety
KS	01/14/2009	01/20/2009	Fire Safety
KS	01/14/2009	01/15/2009	Fire Safety
KS	01/14/2009	01/15/2009	Fire Safety
KS	01/14/2009	01/19/2009	Fire Safety
KS	01/14/2009	01/19/2009	Fire Safety
KS	01/14/2009	01/15/2009	Fire Safety
KS	01/14/2009	01/20/2009	Fire Safety
KS	02/19/2010	03/20/2010	Fire Safety

	have been maintained in working order.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175415	ELMHAVEN EAST	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS

sumner regional medical center

Based on VSDA2

KS	02/19/2010	02/19/2010	Fire Safety
KS	02/19/2010	02/19/2010	Fire Safety
KS	02/19/2010	03/20/2010	Fire Safety
KS	02/19/2010	03/20/2010	Fire Safety
KS	02/19/2010	02/19/2010	Fire Safety
KS	04/23/2008	04/25/2008	Fire Safety
KS	04/23/2008	04/29/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	04/25/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	a separate and independent backup electrical power source.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS
175416	ELMHAVEN WEST NURSING HOME	PARSONS

sumner regional medical center

Based on VSDA2

KS	04/23/2008	04/24/2008	Fire Safety
KS	04/23/2008	04/28/2008	Fire Safety
KS	04/15/2009	04/16/2009	Fire Safety
KS	04/15/2009	04/16/2009	Fire Safety
KS	04/15/2009	04/24/2009	Fire Safety
KS	04/15/2009	04/25/2009	Fire Safety
KS	04/15/2009	04/16/2009	Fire Safety
KS	04/15/2009	04/16/2009	Fire Safety
KS	06/07/2010	06/07/2010	Fire Safety

	permitted or did not provide ashtrays where smoking was allowed.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175416	ELMHAVEN WEST NURSING HOME	PARSONS
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT

sumner regional medical center

Based on VSDA2

KS	06/07/2010	06/29/2010	Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Electrical Deficiencies	weekly inspections and monthly	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT

sumner regional medical center

Based on VSDA2

KS			Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety
KS	05/27/2008	06/26/2008	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety
KS	06/16/2009	07/10/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT

sumner regional medical center

Based on VSDA2

KS	06/16/2009	07/10/2009	Fire Safety
KS	06/04/2010	06/29/2010	Fire Safety
KS	06/04/2010	06/18/2010	Fire Safety
KS	06/04/2010	06/09/2010	Fire Safety
KS	06/04/2010	06/10/2010	Fire Safety
KS	06/04/2010	06/10/2010	Fire Safety
KS	06/04/2010	06/29/2010	Fire Safety
KS	06/04/2010	06/22/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175417	FRANKFORT COMMUNITY CARE HOME	FRANKFORT
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	06/04/2010	06/10/2010	Fire Safety
KS	06/04/2010	06/29/2010	Fire Safety
KS	01/16/2008	02/15/2008	Fire Safety
KS	01/16/2008	02/15/2008	Fire Safety
KS	01/16/2008	02/15/2008	Fire Safety
KS	01/16/2008	02/15/2008	Fire Safety
KS	01/16/2008	02/15/2008	Fire Safety
KS	01/16/2008	02/15/2008	Fire Safety
KS	01/16/2008	02/15/2008	Fire Safety
KS	01/16/2008	02/15/2008	Fire Safety
KS	01/16/2008	02/15/2008	Fire Safety

	instructions.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Electrical Deficiencies	a separate and independent backup electrical power source.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	03/09/2009	05/14/2009	Fire Safety
KS	03/09/2009	05/14/2009	Fire Safety
KS	03/09/2009	04/07/2009	Fire Safety
KS	03/09/2009	05/14/2009	Fire Safety
KS	03/09/2009	04/07/2009	Fire Safety
KS	03/09/2009	05/14/2009	Fire Safety
KS	03/09/2009	05/14/2009	Fire Safety
KS	03/09/2009	05/14/2009	Fire Safety
KS	03/09/2009	05/14/2009	Fire Safety

	and equipment.	
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	03/09/2009	05/14/2009	Fire Safety
KS	03/09/2009	04/07/2009	Fire Safety
KS	03/09/2009	05/14/2009	Fire Safety
KS	03/09/2009	05/14/2009	Fire Safety
KS	03/09/2009	05/14/2009	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175418	PROVIDENCE LIVING CENTER	TOPEKA
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN

KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	10/31/2007	10/31/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN

KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	02/05/2009	02/05/2009	Fire Safety
KS	02/05/2009	03/06/2009	Fire Safety

	at least 1 1/2 hours.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175419	LINCOLN PARK MANOR INC	LINCOLN
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA

KS	02/05/2009	02/05/2009	Fire Safety
KS	02/05/2009	03/06/2009	Fire Safety
KS	02/05/2009	03/06/2009	Fire Safety
KS	03/25/2010	04/02/2010	Fire Safety
KS	03/25/2010	04/02/2010	Fire Safety
KS	01/15/2008	02/08/2008	Fire Safety
KS	01/15/2008	02/08/2008	Fire Safety
KS	01/15/2008	02/08/2008	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA

sumner regional medical center

Based on VSDA2

KS	01/15/2008	02/08/2008	Fire Safety
KS	01/15/2008	02/08/2008	Fire Safety
KS	01/15/2008	02/08/2008	Fire Safety
KS	01/15/2008	02/13/2008	Fire Safety
KS	12/03/2008	12/31/2008	Fire Safety
KS	12/03/2008	12/24/2008	Fire Safety
KS	12/03/2008	12/05/2008	Fire Safety
KS	12/03/2008	01/01/2009	Fire Safety
KS	12/03/2008	12/08/2008	Fire Safety
KS	12/03/2008	01/01/2009	Fire Safety

	extinguishing system.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA

sumner regional medical center

Based on VSDA2

KS	12/03/2008	01/01/2009	Fire Safety
KS	12/03/2008	01/01/2009	Fire Safety
KS	12/02/2009	12/30/2009	Fire Safety
KS	12/02/2009	12/30/2009	Fire Safety
KS	12/02/2009	12/30/2009	Fire Safety
KS	12/02/2009	12/30/2009	Fire Safety
KS	12/02/2009	12/10/2009	Fire Safety
KS	12/02/2009	12/30/2009	Fire Safety
KS	12/02/2009	12/30/2009	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exit and Exit Access Deficiencies	at least two remote exits on each floor or fire section of the building.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175420	MOUNT JOSEPH SENIOR VILLAGE LLC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA

KS	12/02/2009	12/30/2009	Fire Safety
KS	12/02/2009	12/30/2009	Fire Safety
KS	12/02/2009	12/10/2009	Fire Safety
KS	12/02/2009	12/30/2009	Fire Safety
KS	12/02/2009	12/30/2009	Fire Safety
KS	03/06/2008	04/06/2008	Fire Safety
KS	03/06/2008	04/06/2008	Fire Safety
KS	03/06/2008	04/06/2008	Fire Safety
KS	03/06/2008	04/06/2008	Fire Safety
KS	03/06/2008	04/06/2008	Fire Safety

	at least 1 1/2 hours.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Laboratories Deficiencies	emergency showers.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175422	SUNSET HOME INC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA
175422	SUNSET HOME INC	CONCORDIA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA

KS	03/06/2008	04/06/2008	Fire Safety
KS	02/04/2009	02/11/2009	Fire Safety
KS	02/04/2009	02/13/2009	Fire Safety
KS	02/04/2009	03/04/2009	Fire Safety
KS	02/04/2009	02/13/2009	Fire Safety
KS	02/04/2009	02/13/2009	Fire Safety
KS	12/18/2007	12/19/2007	Fire Safety
KS	12/18/2007	12/19/2007	Fire Safety
KS	12/18/2007	12/19/2007	Fire Safety
KS	12/18/2007	12/19/2007	Fire Safety
KS	12/18/2007	12/19/2007	Fire Safety

Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA

sumner regional medical center

Based on VSDA2

KS	01/27/2009	01/28/2009	Fire Safety
KS	01/27/2009	01/28/2009	Fire Safety
KS	01/27/2009	01/30/2009	Fire Safety
KS	01/27/2009	02/02/2009	Fire Safety
KS	01/27/2009	01/28/2009	Fire Safety
KS	01/27/2009	01/28/2009	Fire Safety
KS	01/27/2009	01/28/2009	Fire Safety
KS	02/12/2010	02/18/2010	Fire Safety
KS	02/12/2010	02/18/2010	Fire Safety

	order.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175423	HOLIDAY RESORT OF SALINA	SALINA
175424	LAKEPOINT NURSING CENTER	AUGUSTA

sumner regional medical center

Based on VSDA2

KS	02/12/2010	03/04/2010	Fire Safety
KS	02/12/2010	02/25/2010	Fire Safety
KS	02/12/2010	02/12/2010	Fire Safety
KS	02/12/2010	02/18/2010	Fire Safety
KS	02/12/2010	02/25/2010	Fire Safety
KS	02/12/2010	02/12/2010	Fire Safety
KS	02/12/2010	02/12/2010	Fire Safety
KS	02/12/2010	02/12/2010	Fire Safety
KS	02/12/2010	03/04/2010	Fire Safety
KS	02/12/2010	03/04/2010	Fire Safety
KS	05/14/2008	06/13/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Building Service Equipment Deficiencies	an externally vented heating system.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175424	LAKEPOINT NURSING CENTER	AUGUSTA
175424	LAKEPOINT NURSING CENTER	AUGUSTA
175424	LAKEPOINT NURSING CENTER	AUGUSTA
175424	LAKEPOINT NURSING CENTER	AUGUSTA
175424	LAKEPOINT NURSING CENTER	AUGUSTA
175424	LAKEPOINT NURSING CENTER	AUGUSTA
175424	LAKEPOINT NURSING CENTER	AUGUSTA
175424	LAKEPOINT NURSING CENTER	AUGUSTA
175424	LAKEPOINT NURSING CENTER	AUGUSTA

sumner regional medical center

Based on VSDA2

KS	05/14/2008	06/13/2008	Fire Safety
KS	05/14/2008	06/13/2008	Fire Safety
KS	05/14/2008	06/13/2008	Fire Safety
KS	05/14/2008	06/13/2008	Fire Safety
KS	04/14/2009	04/22/2009	Fire Safety
KS	04/14/2009	04/22/2009	Fire Safety
KS	04/14/2009	04/22/2009	Fire Safety
KS	07/07/2010	07/22/2010	Fire Safety
KS	07/07/2010	07/22/2010	Fire Safety

	hour.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175424	LAKEPOINT NURSING CENTER	AUGUSTA
175424	LAKEPOINT NURSING CENTER	AUGUSTA
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL

KS	07/07/2010	07/22/2010	Fire Safety
KS	07/07/2010	07/22/2010	Fire Safety
KS	08/29/2007	09/06/2007	Fire Safety
KS	08/29/2007	09/06/2007	Fire Safety
KS	08/29/2007	09/06/2007	Fire Safety
KS	08/29/2007	08/29/2007	Fire Safety
KS	08/29/2007	09/07/2007	Fire Safety
KS	08/29/2007	09/06/2007	Fire Safety
KS	08/29/2007	09/06/2007	Fire Safety
KS	08/29/2007	09/06/2007	Fire Safety

	at least 1 1/2 hours.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL

sumner regional medical center

Based on VSDA2

KS	08/29/2007	09/06/2007	Fire Safety
KS	09/16/2008	09/17/2008	Fire Safety
KS	09/16/2008	09/17/2008	Fire Safety
KS	09/16/2008	09/23/2008	Fire Safety
KS	09/16/2008	09/17/2008	Fire Safety
KS	09/16/2008	09/16/2008	Fire Safety
KS	09/16/2008	09/16/2008	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175425	GOLDEN LIVINGCENTER - SPRINGHILL	SPRING HILL
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA

sumner regional medical center

Based on VSDA2

KS	09/16/2008	09/17/2008	Fire Safety
KS	09/16/2008	09/16/2008	Fire Safety
KS	11/04/2009	12/04/2009	Fire Safety
KS	11/04/2009	12/04/2009	Fire Safety
KS	11/04/2009	12/04/2009	Fire Safety
KS	11/04/2009	12/04/2009	Fire Safety
KS	07/24/2007	08/23/2007	Fire Safety
KS	07/24/2007	07/24/2007	Fire Safety
KS	07/24/2007	08/23/2007	Fire Safety
KS	07/24/2007	08/23/2007	Fire Safety
KS	07/24/2007	08/23/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA

sumner regional medical center

Based on VSDA2

KS	07/24/2007	08/23/2007	Fire Safety
KS	07/24/2007	07/24/2007	Fire Safety
KS	07/24/2007	08/23/2007	Fire Safety
KS	07/24/2007	08/23/2007	Fire Safety
KS	07/24/2007	08/23/2007	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety

	have been maintained in working order.	
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Widespread
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA

sumner regional medical center

Based on VSDA2

KS	10/09/2008	01/01/1900	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	01/12/2010	02/12/2010	Fire Safety
KS	01/12/2010	02/12/2010	Fire Safety

	resist smoke for at least 20 minutes.	
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175426	CRESTVIEW MANOR NURSING HOME	SENECA
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY

sumner regional medical center

Based on VSDA2

KS	01/12/2010	02/12/2010	Fire Safety
KS	01/12/2010	02/12/2010	Fire Safety
KS	01/12/2010	02/12/2010	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY

KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	09/22/2009	01/01/1900	Fire Safety
KS	09/22/2009	01/01/1900	Fire Safety
KS	09/22/2009	01/01/1900	Fire Safety
KS	09/22/2009	01/01/1900	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Isolated

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175429	THE HOMESTEAD HEALTH & REHAB CENTER	GARDEN CITY
175433	GOLDEN HEIGHTS LIVING CENTER	GARNETT

sumner regional medical center

Based on VSDA2

KS	09/22/2009	01/01/1900	Fire Safety
KS	09/22/2009	01/01/1900	Fire Safety
KS	09/22/2009	01/01/1900	Fire Safety
KS	09/22/2009	01/01/1900	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety
KS	09/21/2010	09/30/2010	Fire Safety
KS	09/21/2010	09/21/2010	Fire Safety
KS	09/21/2010	09/30/2010	Fire Safety
KS	04/09/2008	05/08/2008	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175433	GOLDEN HEIGHTS LIVING CENTER	GARNETT
175433	GOLDEN HEIGHTS LIVING CENTER	GARNETT
175433	GOLDEN HEIGHTS LIVING CENTER	GARNETT
175433	GOLDEN HEIGHTS LIVING CENTER	GARNETT
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO

sumner regional medical center

Based on VSDA2

KS	04/09/2008	05/08/2008	Fire Safety
KS	04/09/2008	05/08/2008	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	06/10/2009	07/09/2009	Fire Safety
KS	02/07/2008	06/27/2008	Fire Safety
KS	02/07/2008	06/27/2008	Fire Safety
KS	02/07/2008	06/27/2008	Fire Safety
KS	02/07/2008	06/27/2008	Fire Safety
KS	02/07/2008	06/27/2008	Fire Safety
KS	02/07/2008	06/27/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT	OSWEGO

KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	04/28/2009	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	04/20/2009	Fire Safety
KS	04/16/2009	04/23/2009	Fire Safety
KS	04/16/2009	04/24/2009	Fire Safety
KS	04/16/2009	04/17/2009	Fire Safety
KS	04/16/2009	05/15/2009	Fire Safety
KS	04/16/2009	04/16/2009	Fire Safety

	permitted or did not provide ashtrays where smoking was allowed.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

	OSWEGO	
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175434	DESERET NURSING & REHABILITATION AT OSWEGO	OSWEGO
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON

sumner regional medical center

Based on VSDA2

KS	04/16/2009	04/16/2009	Fire Safety
KS	05/10/2010	05/28/2010	Fire Safety
KS	05/10/2010	05/10/2010	Fire Safety
KS	05/10/2010	05/10/2010	Fire Safety
KS	05/10/2010	05/28/2010	Fire Safety
KS	05/10/2010	05/28/2010	Fire Safety
KS	05/10/2010	05/28/2010	Fire Safety
KS	05/10/2010	06/04/2010	Fire Safety
KS	07/09/2008	07/31/2008	Fire Safety
KS	07/09/2008	07/31/2008	Fire Safety
KS	07/09/2008	07/31/2008	Fire Safety

sumner regional medical center

Based on VSDA2

	faulty automatic sprinkler system.	
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit"	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON
175435	MEDICALODGES JACKSON COUNTY	HOLTON

sumner regional medical center

Based on VSDA2

KS	10/05/2009	11/03/2009	Fire Safety
KS	10/05/2009	11/03/2009	Fire Safety
KS	10/05/2009	11/02/2009	Fire Safety
KS	12/16/2010	12/17/2010	Fire Safety
KS	12/16/2010	12/17/2010	Fire Safety
KS	12/16/2010	01/15/2011	Fire Safety
KS	12/16/2010	12/17/2010	Fire Safety
KS	12/16/2010	01/15/2011	Fire Safety
KS	12/16/2010	12/17/2010	Fire Safety
KS	12/16/2010	01/15/2011	Fire Safety

	signs.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175435	MEDICALODGES JACKSON COUNTY	HOLTON
175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD

sumner regional medical center

Based on VSDA2

KS	12/16/2010	01/15/2011	Fire Safety
KS	09/11/2007	09/30/2007	Fire Safety
KS	09/11/2007	09/30/2007	Fire Safety
KS	09/11/2007	10/10/2007	Fire Safety
KS	09/11/2007	10/10/2007	Fire Safety
KS	09/11/2007	10/10/2007	Fire Safety
KS	09/11/2007	10/10/2007	Fire Safety
KS	10/01/2008	10/15/2008	Fire Safety
KS	10/01/2008	10/15/2008	Fire Safety
KS	10/01/2008	10/15/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175436	HOWARD TWILIGHT MANOR	HOWARD
175436	HOWARD TWILIGHT MANOR	HOWARD
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON

KS	10/01/2008	10/15/2008	Fire Safety
KS	10/01/2008	10/15/2008	Fire Safety
KS	11/14/2007	12/14/2007	Fire Safety
KS	11/14/2007	12/14/2007	Fire Safety
KS	11/14/2007	12/14/2007	Fire Safety
KS	11/14/2007	12/14/2007	Fire Safety
KS	11/14/2007	12/14/2007	Fire Safety
KS	11/14/2007	12/14/2007	Fire Safety
KS	11/14/2007	12/14/2007	Fire Safety

	at least 1 1/2 hours.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON

sumner regional medical center

Based on VSDA2

KS	11/14/2007	12/14/2007	Fire Safety
KS	11/14/2007	12/14/2007	Fire Safety
KS	11/14/2007	12/14/2007	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175437	MCPHERSON CARE CENTER LLC	MCPHERSON
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA

sumner regional medical center

Based on VSDA2

KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	10/17/2008	11/16/2008	Fire Safety
KS	12/02/2009	12/03/2009	Fire Safety
KS	05/23/2008	06/17/2008	Fire Safety
KS	05/23/2008	06/17/2008	Fire Safety
KS	05/23/2008	06/17/2008	Fire Safety

	at least 1 1/2 hours.	
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA

sumner regional medical center

Based on VSDA2

KS	05/23/2008	06/17/2008	Fire Safety
KS	05/23/2008	06/17/2008	Fire Safety
KS	05/23/2008	06/17/2008	Fire Safety
KS	05/23/2008	06/17/2008	Fire Safety
KS	05/23/2008	06/17/2008	Fire Safety
KS	05/23/2008	06/17/2008	Fire Safety
KS	06/10/2009	06/16/2009	Fire Safety
KS	06/10/2009	06/11/2009	Fire Safety
KS	06/10/2009	06/24/2009	Fire Safety
KS	06/10/2009	06/24/2009	Fire Safety

	times.	
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175439	LIFE CARE CENTER OF SENECA	SENECA
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD

sumner regional medical center

Based on VSDA2

KS	08/16/2010	09/10/2010	Fire Safety
KS	08/16/2010	09/10/2010	Fire Safety
KS	08/16/2010	09/10/2010	Fire Safety
KS	08/16/2010	09/10/2010	Fire Safety
KS	08/16/2010	09/10/2010	Fire Safety
KS	08/16/2010	09/10/2010	Fire Safety
KS	08/16/2010	09/10/2010	Fire Safety
KS	08/16/2010	09/10/2010	Fire Safety
KS	08/16/2010	09/10/2010	Fire Safety
KS	08/16/2010	09/10/2010	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Exits and Egress Deficiencies	rooms that can be unlocked from inside without a key.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD

sumner regional medical center

Based on VSDA2

KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	HERITAGE	
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175440	TWG NURSING HOME INC DBA THE HERITAGE	GIRARD
175441	VILLAGE SHALOM INC	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/04/2008	03/05/2008	Fire Safety
KS	02/17/2009	03/17/2009	Fire Safety
KS	02/17/2009	03/17/2009	Fire Safety
KS	02/17/2009	03/17/2009	Fire Safety
KS	04/26/2010	05/25/2010	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Isolated
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	08/06/2008	09/05/2008	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety
KS	08/06/2008	09/05/2008	Fire Safety
KS	09/30/2009	10/30/2009	Fire Safety
KS	09/30/2009	10/30/2009	Fire Safety

	hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175441	VILLAGE SHALOM INC	OVERLAND PARK
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE

KS	09/30/2009	10/30/2009	Fire Safety
KS	09/30/2009	10/30/2009	Fire Safety
KS	09/30/2009	10/30/2009	Fire Safety
KS	09/30/2009	10/30/2009	Fire Safety
KS	11/23/2010	12/20/2010	Fire Safety
KS	11/23/2010	11/23/2010	Fire Safety
KS	11/23/2010	12/16/2010	Fire Safety
KS	11/23/2010	11/23/2010	Fire Safety
KS	09/18/2007	10/05/2007	Fire Safety
KS	09/18/2007	09/20/2007	Fire Safety

	resist smoke for at least 20 minutes.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE

sumner regional medical center

Based on VSDA2

KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	09/20/2007	Fire Safety
KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	09/21/2007	Fire Safety
KS	09/18/2007	09/19/2007	Fire Safety
KS	09/18/2007	10/02/2007	Fire Safety
KS	09/18/2007	10/01/2007	Fire Safety

	common areas by walls constructed to limit the passage of smoke.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE

sumner regional medical center

Based on VSDA2

KS	09/18/2007	10/18/2007	Fire Safety
KS	09/18/2007	09/20/2007	Fire Safety
KS	09/18/2007	09/21/2007	Fire Safety
KS	09/18/2007	09/21/2007	Fire Safety
KS	12/11/2008	12/11/2008	Fire Safety
KS	12/11/2008	12/11/2008	Fire Safety
KS	12/11/2008	12/11/2008	Fire Safety
KS	12/11/2008	12/23/2008	Fire Safety
KS	03/09/2010	03/09/2010	Fire Safety

	that have been properly installed according to the manufacturer's instructions.	
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Isolated
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175443	APPLEWOOD REHABILITATION INC	CHANUTE
175443	APPLEWOOD REHABILITATION INC	CHANUTE
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND

sumner regional medical center

Based on VSDA2

KS	03/09/2010	03/09/2010	Fire Safety
KS	03/09/2010	04/01/2010	Fire Safety
KS	07/18/2008	08/15/2008	Fire Safety
KS	07/18/2008	08/15/2008	Fire Safety
KS	07/18/2008	08/15/2008	Fire Safety
KS	07/18/2008	08/15/2008	Fire Safety
KS	07/18/2008	08/15/2008	Fire Safety
KS	07/18/2008	08/15/2008	Fire Safety
KS	07/18/2008	08/15/2008	Fire Safety
KS	07/18/2008	08/15/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175444	RICHMOND HEALTHCARE & REHAB CTR	RICHMOND
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE

sumner regional medical center

Based on VSDA2

KS	07/18/2008	08/15/2008	Fire Safety
KS	09/21/2009	10/21/2009	Fire Safety
KS	09/21/2009	10/21/2009	Fire Safety
KS	09/21/2009	10/21/2009	Fire Safety
KS	09/21/2009	10/21/2009	Fire Safety
KS	09/21/2009	10/21/2009	Fire Safety
KS	10/20/2010	11/10/2010	Fire Safety
KS	05/28/2008	06/26/2008	Fire Safety
KS	05/28/2008	06/26/2008	Fire Safety
KS	05/28/2008	06/26/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE

sumner regional medical center

Based on VSDA2

KS	05/28/2008	06/26/2008	Fire Safety
KS	05/28/2008	06/26/2008	Fire Safety
KS	05/28/2008	06/26/2008	Fire Safety
KS	05/28/2008	06/26/2008	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	01/01/1900	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	01/01/1900	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE

sumner regional medical center

Based on VSDA2

KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/04/2009	09/02/2009	Fire Safety
KS	08/16/2010	08/16/2010	Fire Safety

	detectors.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175445	PIONEER RIDGE RETIREMENT COMMUNITY	LAWRENCE
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175446	HALSTEAD HEALTH AND REHABILITATION	HALSTEAD

KS	08/16/2010	08/16/2010	Fire Safety
KS	08/16/2010	08/16/2010	Fire Safety
KS	08/16/2010	08/16/2010	Fire Safety
KS	08/16/2010	08/16/2010	Fire Safety
KS	01/08/2008	02/07/2008	Fire Safety
KS	01/08/2008	02/07/2008	Fire Safety
KS	01/08/2008	02/07/2008	Fire Safety
KS	01/08/2008	02/07/2008	Fire Safety
KS	01/08/2008	02/07/2008	Fire Safety
KS	01/08/2008	02/07/2008	Fire Safety

	hour.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Laboratories Deficiencies	emergency showers.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	CENTER	
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175446	HALSTEAD HEALTH AND REHABILITATION CENTER	HALSTEAD
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE

sumner regional medical center

Based on VSDA2

KS	01/08/2008	02/07/2008	Fire Safety
KS	02/16/2009	02/16/2009	Fire Safety
KS	02/16/2009	02/16/2009	Fire Safety
KS	02/16/2009	02/16/2009	Fire Safety
KS	02/16/2009	02/20/2009	Fire Safety
KS	09/19/2007	09/19/2007	Fire Safety
KS	09/19/2007	10/01/2007	Fire Safety
KS	09/19/2007	10/01/2007	Fire Safety
KS	09/19/2007	10/19/2007	Fire Safety
KS	09/19/2007	10/19/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Vertical Openings Deficiencies	protected exits that allow the resident to escape the building.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Miscellaneous Deficiencies	fire safety features required by	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE

sumner regional medical center

Based on VSDA2

KS	10/09/2008	12/31/2008	Fire Safety
KS	10/09/2008	12/31/2008	Fire Safety
KS	10/09/2008	12/31/2008	Fire Safety
KS	10/09/2008	12/09/2008	Fire Safety
KS	10/09/2008	12/09/2008	Fire Safety
KS	10/09/2008	12/09/2008	Fire Safety
KS	10/09/2008	12/31/2008	Fire Safety
KS	10/09/2008	12/09/2008	Fire Safety
KS	10/09/2008	12/09/2008	Fire Safety

	current fire safety codes.	
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175448	ABERDEEN VILLAGE	OLATHE
175450	RIVERVIEW MANOR	OXFORD
175450	RIVERVIEW MANOR	OXFORD
175450	RIVERVIEW MANOR	OXFORD
175450	RIVERVIEW MANOR	OXFORD
175450	RIVERVIEW MANOR	OXFORD
175450	RIVERVIEW MANOR	OXFORD
175450	RIVERVIEW MANOR	OXFORD

sumner regional medical center

Based on VSDA2

KS	10/09/2008	12/09/2008	Fire Safety
KS	10/09/2008	12/09/2008	Fire Safety
KS	10/06/2009	10/16/2009	Fire Safety
KS	03/26/2008	04/17/2008	Fire Safety
KS	03/26/2008	04/17/2008	Fire Safety
KS	03/26/2008	04/10/2008	Fire Safety
KS	03/26/2008	04/10/2008	Fire Safety
KS	03/26/2008	04/07/2008	Fire Safety
KS	03/26/2008	04/01/2008	Fire Safety
KS	03/26/2008	04/24/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Interior Finish Deficiencies	fire-resistant interior walls.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175450	RIVERVIEW MANOR	OXFORD
175450	RIVERVIEW MANOR	OXFORD
175450	RIVERVIEW MANOR	OXFORD
175450	RIVERVIEW MANOR	OXFORD
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER

sumner regional medical center

Based on VSDA2

KS	03/26/2008	04/18/2008	Fire Safety
KS	03/12/2009	03/24/2009	Fire Safety
KS	03/03/2010	03/03/2010	Fire Safety
KS	03/03/2010	03/03/2010	Fire Safety
KS	04/04/2008	05/02/2008	Fire Safety
KS	04/04/2008	05/02/2008	Fire Safety
KS	04/04/2008	05/02/2008	Fire Safety
KS	04/04/2008	05/02/2008	Fire Safety
KS	04/04/2008	05/02/2008	Fire Safety

Laboratories Deficiencies	emergency showers.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER

sumner regional medical center

Based on VSDA2

KS	04/04/2008	05/02/2008	Fire Safety
KS	04/04/2008	05/02/2008	Fire Safety
KS	04/04/2008	05/02/2008	Fire Safety
KS	05/20/2009	05/29/2009	Fire Safety
KS	05/20/2009	05/29/2009	Fire Safety
KS	05/20/2009	05/29/2009	Fire Safety
KS	05/20/2009	05/29/2009	Fire Safety
KS	05/20/2009	05/29/2009	Fire Safety
KS	05/20/2009	05/29/2009	Fire Safety
KS	05/20/2009	05/29/2009	Fire Safety

	have been maintained in working order.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Electrical Deficiencies	weekly inspections and monthly	Widespread

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175451	WHEAT STATE MANOR	WHITEWATER
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA

sumner regional medical center

Based on VSDA2

KS	05/12/2010	05/17/2010	Fire Safety
KS	05/12/2010	05/28/2010	Fire Safety
KS	05/12/2010	05/21/2010	Fire Safety
KS	05/12/2010	05/28/2010	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety

	testing of generators.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA

sumner regional medical center

Based on VSDA2

KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	10/15/2009	10/20/2009	Fire Safety
KS	10/15/2009	10/20/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA

KS	10/15/2009	10/15/2009	Fire Safety
KS	10/15/2009	10/22/2009	Fire Safety
KS	10/15/2009	11/15/2009	Fire Safety
KS	10/15/2009	11/15/2009	Fire Safety
KS	10/15/2009	11/15/2009	Fire Safety
KS	10/15/2009	10/22/2009	Fire Safety
KS	10/15/2009	11/15/2009	Fire Safety
KS	10/15/2009	10/15/2009	Fire Safety
KS	10/15/2009	11/15/2009	Fire Safety
KS	10/15/2009	10/17/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	WICHITA LLC	
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT WICHITA LLC	WICHITA
175452	DESERET NURSING & REHABILITATION AT	WICHITA

KS	11/23/2010	11/23/2010	Fire Safety
KS	11/23/2010	12/17/2010	Fire Safety
KS	11/23/2010	12/17/2010	Fire Safety
KS	11/23/2010	11/23/2010	Fire Safety
KS	11/23/2010	11/23/2010	Fire Safety
KS	11/23/2010	12/03/2010	Fire Safety
KS	11/23/2010	12/17/2010	Fire Safety
KS	11/23/2010	11/30/2010	Fire Safety
KS	11/23/2010	11/23/2010	Fire Safety
KS	11/23/2010	12/02/2010	Fire Safety

	and equipment.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	WICHITA LLC	
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER

sumner regional medical center

Based on VSDA2

KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/18/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety

	and equipment.	
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER

sumner regional medical center

Based on VSDA2

KS	01/17/2008	01/18/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	01/17/2008	02/17/2008	Fire Safety
KS	02/25/2009	03/20/2009	Fire Safety
KS	02/25/2009	02/26/2009	Fire Safety
KS	02/25/2009	03/10/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	INC	
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER

sumner regional medical center

Based on VSDA2

KS	02/25/2009	03/20/2009	Fire Safety
KS	02/25/2009	02/26/2009	Fire Safety
KS	02/25/2009	03/20/2009	Fire Safety
KS	02/25/2009	03/02/2009	Fire Safety
KS	02/25/2009	03/20/2009	Fire Safety
KS	02/25/2009	03/10/2009	Fire Safety
KS	04/26/2010	04/29/2010	Fire Safety
KS	04/26/2010	04/28/2010	Fire Safety
KS	04/26/2010	04/27/2010	Fire Safety

	times.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175454	CLEARWATER RETIREMENT COMMUNITY INC	CLEARWATER
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE

sumner regional medical center

Based on VSDA2

KS	04/26/2010	05/20/2010	Fire Safety
KS	08/05/2008	09/04/2008	Fire Safety
KS	08/05/2008	09/04/2008	Fire Safety
KS	08/05/2008	09/04/2008	Fire Safety
KS	08/05/2008	09/04/2008	Fire Safety
KS	08/05/2008	09/04/2008	Fire Safety
KS	08/05/2008	09/04/2008	Fire Safety
KS	08/05/2008	09/04/2008	Fire Safety
KS	08/05/2008	09/04/2008	Fire Safety

	for fire alarm systems.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE

sumner regional medical center

Based on VSDA2

KS	08/05/2008	09/04/2008	Fire Safety
KS	09/16/2009	09/16/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety

	facilities.	
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175455	GOLDEN LIVINGCENTER - ESKRIDGE	ESKRIDGE
175456	VILLA MARIA	MULVANE
175456	VILLA MARIA	MULVANE

sumner regional medical center

Based on VSDA2

KS	09/16/2009	10/15/2009	Fire Safety
KS	11/17/2010	12/08/2010	Fire Safety
KS	11/17/2010	12/08/2010	Fire Safety
KS	11/17/2010	12/08/2010	Fire Safety
KS	11/17/2010	12/08/2010	Fire Safety
KS	11/17/2010	12/08/2010	Fire Safety
KS	11/17/2010	12/08/2010	Fire Safety
KS	11/17/2010	12/08/2010	Fire Safety
KS	11/17/2010	12/08/2010	Fire Safety
KS	08/07/2008	09/03/2008	Fire Safety
KS	08/07/2008	09/03/2008	Fire Safety

	all times.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175456	VILLA MARIA	MULVANE
175456	VILLA MARIA	MULVANE
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY

KS	08/07/2008	09/03/2008	Fire Safety
KS	08/07/2008	09/03/2008	Fire Safety
KS	04/17/2008	04/18/2008	Fire Safety
KS	04/17/2008	04/18/2008	Fire Safety
KS	04/17/2008	04/30/2008	Fire Safety
KS	04/17/2008	04/18/2008	Fire Safety
KS	06/02/2009	06/02/2009	Fire Safety
KS	06/02/2009	06/02/2009	Fire Safety
KS	06/02/2009	06/02/2009	Fire Safety
KS	06/02/2009	06/02/2009	Fire Safety

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY

sumner regional medical center

Based on VSDA2

KS	06/02/2009	06/02/2009	Fire Safety
KS	06/02/2009	06/02/2009	Fire Safety
KS	06/02/2009	06/02/2009	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit"	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175457	LEGACY PARK	PEABODY
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL

sumner regional medical center

Based on VSDA2

KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	05/19/2010	06/18/2010	Fire Safety
KS	10/17/2007	11/16/2007	Fire Safety
KS	10/17/2007	11/16/2007	Fire Safety

	signs.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL

sumner regional medical center

Based on VSDA2

KS	10/17/2007	11/16/2007	Fire Safety
KS	10/17/2007	11/16/2007	Fire Safety
KS	10/17/2007	10/17/2007	Fire Safety
KS	10/17/2007	11/16/2007	Fire Safety
KS	08/14/2008	09/11/2008	Fire Safety
KS	08/14/2008	08/18/2008	Fire Safety
KS	08/14/2008	09/11/2008	Fire Safety
KS	08/14/2008	09/11/2008	Fire Safety
KS	08/14/2008	09/11/2008	Fire Safety
KS	08/14/2008	09/11/2008	Fire Safety

	conditions.	
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175459	WHEATRIDGE PARK CARE CENTER	LIBERAL
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA

sumner regional medical center

Based on VSDA2

KS	10/28/2009	10/30/2009	Fire Safety
KS	10/28/2009	10/28/2009	Fire Safety
KS	02/06/2008	03/04/2008	Fire Safety
KS	02/06/2008	03/04/2008	Fire Safety
KS	02/06/2008	03/04/2008	Fire Safety
KS	02/06/2008	03/04/2008	Fire Safety
KS	02/06/2008	03/04/2008	Fire Safety
KS	02/06/2008	03/04/2008	Fire Safety
KS	02/06/2008	03/04/2008	Fire Safety

	flammable curtains.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA

sumner regional medical center

Based on VSDA2

KS	02/06/2008	03/04/2008	Fire Safety
KS	02/06/2008	03/04/2008	Fire Safety
KS	02/06/2008	03/04/2008	Fire Safety
KS	04/07/2009	05/01/2009	Fire Safety
KS	04/07/2009	05/01/2009	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety

	according to the manufacturer's instructions.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175461	EMERALD POINTE HEALTH & REHABILITATION CENTER	GALENA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA

sumner regional medical center

Based on VSDA2

KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/22/2010	05/22/2010	Fire Safety
KS	04/21/2008	04/23/2008	Fire Safety
KS	04/21/2008	05/09/2008	Fire Safety
KS	04/21/2008	04/21/2008	Fire Safety
KS	04/21/2008	05/09/2008	Fire Safety
KS	04/21/2008	04/23/2008	Fire Safety
KS	04/21/2008	05/02/2008	Fire Safety
KS	04/21/2008	04/22/2008	Fire Safety

	conditions.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Widespread
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA

KS	04/21/2008	05/01/2008	Fire Safety
KS	04/21/2008	04/24/2008	Fire Safety
KS	04/21/2008	04/24/2008	Fire Safety
KS	04/21/2008	04/25/2008	Fire Safety
KS	04/21/2008	04/23/2008	Fire Safety
KS	04/21/2008	04/25/2008	Fire Safety
KS	07/07/2009	07/13/2009	Fire Safety
KS	07/07/2009	07/10/2009	Fire Safety
KS	07/07/2009	07/09/2009	Fire Safety
KS	07/07/2009	07/07/2009	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA

sumner regional medical center

Based on VSDA2

KS	07/07/2009	07/27/2009	Fire Safety
KS	07/07/2009	07/27/2009	Fire Safety
KS	07/07/2009	07/27/2009	Fire Safety
KS	07/07/2009	07/10/2009	Fire Safety
KS	07/07/2009	07/27/2009	Fire Safety
KS	07/07/2009	07/07/2009	Fire Safety
KS	07/07/2009	07/15/2009	Fire Safety
KS	07/07/2009	07/27/2009	Fire Safety
KS	07/07/2009	07/27/2009	Fire Safety
KS	08/18/2010	09/16/2010	Fire Safety

sumner regional medical center

Based on VSDA2

	times.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175463	WESTWOOD MANOR	TOPEKA
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE

sumner regional medical center

Based on VSDA2

KS	08/18/2010	09/16/2010	Fire Safety
KS	08/18/2010	09/16/2010	Fire Safety
KS	08/18/2010	09/16/2010	Fire Safety
KS	08/18/2010	09/16/2010	Fire Safety
KS	08/18/2010	09/16/2010	Fire Safety
KS	08/18/2010	09/16/2010	Fire Safety
KS	11/30/2007	12/05/2007	Fire Safety
KS	11/30/2007	12/28/2007	Fire Safety
KS	11/30/2007	11/30/2007	Fire Safety
KS	11/30/2007	12/03/2007	Fire Safety
KS	11/30/2007	12/03/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE

sumner regional medical center

Based on VSDA2

KS	11/30/2007	11/30/2007	Fire Safety
KS	11/30/2007	12/28/2007	Fire Safety
KS	11/30/2007	12/28/2007	Fire Safety
KS	11/30/2007	12/28/2007	Fire Safety
KS	12/16/2008	12/16/2008	Fire Safety
KS	12/16/2008	12/16/2008	Fire Safety
KS	12/16/2008	12/17/2008	Fire Safety
KS	01/28/2010	01/31/2010	Fire Safety
KS	01/28/2010	01/31/2010	Fire Safety
KS	01/28/2010	01/31/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175464	THE REGAL ESTATE OF GLENWOOD	INDEPENDENCE
175465	VIA CHRISTI VILLAGE PITTSBURG INC	PITTSBURG
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA

sumner regional medical center

Based on VSDA2

KS	01/28/2010	01/28/2010	Fire Safety
KS	04/18/2008	04/21/2008	Fire Safety
KS	09/05/2007	09/30/2007	Fire Safety
KS	09/05/2007	09/30/2007	Fire Safety
KS	09/05/2007	09/30/2007	Fire Safety
KS	09/05/2007	09/30/2007	Fire Safety
KS	09/05/2007	09/30/2007	Fire Safety
KS	09/05/2007	09/30/2007	Fire Safety
KS	09/05/2007	09/30/2007	Fire Safety
KS	09/05/2007	09/30/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	OF WICHITA	
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER OF WICHITA	WICHITA
175466	LAKEPOINT RETIREMENT & REHAB CENTER	WICHITA

KS	11/19/2008	11/19/2008	Fire Safety
KS	11/19/2008	12/20/2008	Fire Safety
KS	11/19/2008	11/19/2008	Fire Safety
KS	11/19/2008	12/20/2008	Fire Safety
KS	11/19/2008	11/19/2008	Fire Safety
KS	01/19/2010	01/31/2010	Fire Safety
KS	01/19/2010	01/19/2010	Fire Safety
KS	01/19/2010	01/19/2010	Fire Safety
KS	01/19/2010	01/19/2010	Fire Safety
KS	01/19/2010	01/22/2010	Fire Safety

	and equipment.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	properly installed electrical wiring	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

	OF WICHITA	
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON

sumner regional medical center

Based on VSDA2

KS	02/13/2008	03/13/2008	Fire Safety
KS	02/13/2008	02/18/2008	Fire Safety
KS	02/13/2008	02/18/2008	Fire Safety
KS	02/13/2008	03/13/2008	Fire Safety
KS	02/13/2008	03/13/2008	Fire Safety
KS	02/13/2008	02/18/2008	Fire Safety
KS	02/13/2008	03/13/2008	Fire Safety
KS	02/13/2008	03/13/2008	Fire Safety
KS	02/13/2008	02/13/2008	Fire Safety
KS	02/17/2009	03/13/2009	Fire Safety
KS	02/17/2009	03/13/2009	Fire Safety

	and equipment.	
Interior Finish Deficiencies	fire-resistant interior walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON

sumner regional medical center

Based on VSDA2

KS	02/17/2009	03/13/2009	Fire Safety
KS	02/17/2009	03/13/2009	Fire Safety
KS	02/17/2009	03/13/2009	Fire Safety
KS	02/17/2009	02/24/2009	Fire Safety
KS	02/17/2009	03/13/2009	Fire Safety
KS	02/17/2009	03/13/2009	Fire Safety
KS	04/29/2010	05/26/2010	Fire Safety
KS	04/29/2010	05/24/2010	Fire Safety
KS	04/29/2010	05/10/2010	Fire Safety
KS	04/29/2010	05/27/2010	Fire Safety

	extinguishing system.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175467	KANSAS CHRISTIAN HOME	NEWTON
175468	PRAIRIE MISSION RETIREMENT VILLAGE	SAINT PAUL
175468	PRAIRIE MISSION RETIREMENT VILLAGE	SAINT PAUL
175468	PRAIRIE MISSION RETIREMENT VILLAGE	SAINT PAUL
175468	PRAIRIE MISSION RETIREMENT VILLAGE	SAINT PAUL
175468	PRAIRIE MISSION RETIREMENT VILLAGE	SAINT PAUL
175468	PRAIRIE MISSION RETIREMENT VILLAGE	SAINT PAUL
175468	PRAIRIE MISSION RETIREMENT VILLAGE	SAINT PAUL
175468	PRAIRIE MISSION RETIREMENT VILLAGE	SAINT PAUL

sumner regional medical center

Based on VSDA2

KS	04/29/2010	05/28/2010	Fire Safety
KS	04/29/2010	05/21/2010	Fire Safety
KS	04/29/2010	05/06/2010	Fire Safety
KS	10/12/2007	10/12/2007	Fire Safety
KS	10/12/2007	10/12/2007	Fire Safety
KS	10/07/2008	11/01/2008	Fire Safety
KS	10/07/2008	11/01/2008	Fire Safety
KS	10/07/2008	11/01/2008	Fire Safety
KS	12/01/2009	12/15/2009	Fire Safety
KS	12/01/2009	12/15/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS

sumner regional medical center

Based on VSDA2

KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	11/21/2007	12/20/2007	Fire Safety
KS	12/03/2008	01/03/2009	Fire Safety
KS	12/03/2008	01/03/2009	Fire Safety
KS	12/03/2008	01/03/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS

sumner regional medical center

Based on VSDA2

KS	12/03/2008	01/03/2009	Fire Safety
KS	12/03/2008	01/03/2009	Fire Safety
KS	12/03/2008	01/03/2009	Fire Safety
KS	12/03/2008	01/03/2009	Fire Safety
KS	12/03/2008	01/03/2009	Fire Safety
KS	12/14/2009	01/14/2010	Fire Safety
KS	12/14/2009	01/14/2010	Fire Safety
KS	12/14/2009	01/14/2010	Fire Safety
KS	12/14/2009	01/14/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175470	QUAKER HILL MANOR	BAXTER SPRINGS
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND

sumner regional medical center

Based on VSDA2

KS	12/14/2009	01/14/2010	Fire Safety
KS	12/14/2009	01/14/2010	Fire Safety
KS	12/14/2009	01/14/2010	Fire Safety
KS	12/14/2009	01/14/2010	Fire Safety
KS	04/10/2008	05/01/2008	Fire Safety
KS	04/10/2008	04/18/2008	Fire Safety
KS	04/10/2008	05/08/2008	Fire Safety
KS	04/10/2008	05/01/2008	Fire Safety
KS	04/10/2008	05/01/2008	Fire Safety
KS	04/10/2008	04/17/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND

sumner regional medical center

Based on VSDA2

KS	04/10/2008	05/01/2008	Fire Safety
KS	04/10/2008	04/22/2008	Fire Safety
KS	04/10/2008	05/08/2008	Fire Safety
KS	05/05/2009	05/13/2009	Fire Safety
KS	05/05/2009	05/06/2009	Fire Safety
KS	05/05/2009	06/02/2009	Fire Safety
KS	05/05/2009	05/29/2009	Fire Safety
KS	05/05/2009	06/02/2009	Fire Safety
KS	05/05/2009	06/02/2009	Fire Safety
KS	05/05/2009	05/19/2009	Fire Safety
KS	05/05/2009	05/20/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND

sumner regional medical center

Based on VSDA2

KS	06/02/2010	06/02/2010	Fire Safety
KS	06/02/2010	06/30/2010	Fire Safety
KS	06/02/2010	06/14/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	06/21/2010	Fire Safety
KS	06/02/2010	06/11/2010	Fire Safety
KS	06/02/2010	06/11/2010	Fire Safety
KS	06/02/2010	06/11/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175471	WESTY COMMUNITY CARE HOME	WESTMORELAND
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO

sumner regional medical center

Based on VSDA2

KS	06/02/2010	06/07/2010	Fire Safety
KS	06/02/2010	07/02/2010	Fire Safety
KS	06/02/2010	06/02/2010	Fire Safety
KS	06/02/2010	06/02/2010	Fire Safety
KS	06/02/2010	06/02/2010	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety

	instructions.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	no-smoking signs where oxygen is used.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO

sumner regional medical center

Based on VSDA2

KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	12/31/2007	Fire Safety
KS	10/31/2007	12/31/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Laboratories Deficiencies	emergency showers.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO

sumner regional medical center

Based on VSDA2

KS	10/31/2007	11/30/2007	Fire Safety
KS	10/31/2007	11/30/2007	Fire Safety
KS	10/30/2008	11/06/2008	Fire Safety
KS	10/30/2008	11/06/2008	Fire Safety
KS	10/30/2008	11/03/2008	Fire Safety
KS	10/30/2008	11/15/2008	Fire Safety
KS	10/30/2008	11/06/2008	Fire Safety
KS	10/30/2008	11/06/2008	Fire Safety
KS	10/30/2008	11/30/2008	Fire Safety
KS	10/30/2008	11/25/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO

KS	10/30/2008	11/30/2008	Fire Safety
KS	10/30/2008	11/06/2008	Fire Safety
KS	10/30/2008	10/30/2008	Fire Safety
KS	10/30/2008	11/06/2008	Fire Safety
KS	10/30/2008	11/25/2008	Fire Safety
KS	10/30/2008	11/25/2008	Fire Safety
KS	10/30/2008	11/25/2008	Fire Safety
KS	11/17/2009	12/17/2009	Fire Safety
KS	11/17/2009	12/17/2009	Fire Safety

	alarm system.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175472	HILLSIDE VILLAGE OF DESOTO	DE SOTO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO

sumner regional medical center

Based on VSDA2

KS	11/17/2009	12/17/2009	Fire Safety
KS	11/17/2009	12/17/2009	Fire Safety
KS	11/17/2009	12/17/2009	Fire Safety
KS	11/17/2009	12/17/2009	Fire Safety
KS	11/17/2009	12/17/2009	Fire Safety
KS	11/17/2009	12/17/2009	Fire Safety
KS	11/17/2009	12/17/2009	Fire Safety
KS	12/04/2007	01/02/2008	Fire Safety
KS	12/04/2007	01/02/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO

sumner regional medical center

Based on VSDA2

KS	12/04/2007	01/02/2008	Fire Safety
KS	12/04/2007	01/02/2008	Fire Safety
KS	12/04/2007	01/02/2008	Fire Safety
KS	12/04/2007	01/02/2008	Fire Safety
KS	12/04/2007	01/02/2008	Fire Safety
KS	03/18/2009	04/16/2009	Fire Safety
KS	03/18/2009	04/16/2009	Fire Safety
KS	03/18/2009	04/16/2009	Fire Safety
KS	03/18/2009	04/16/2009	Fire Safety
KS	03/18/2009	04/16/2009	Fire Safety
KS	03/18/2009	04/16/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175473	THE NICOL HOME	GLASCO
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN

sumner regional medical center

Based on VSDA2

KS	03/18/2009	04/16/2009	Fire Safety
KS	03/18/2009	04/16/2009	Fire Safety
KS	03/18/2009	04/16/2009	Fire Safety
KS	03/18/2009	04/16/2009	Fire Safety
KS	05/03/2010	06/01/2010	Fire Safety
KS	05/03/2010	06/01/2010	Fire Safety
KS	07/10/2008	07/11/2008	Fire Safety
KS	07/10/2008	07/17/2008	Fire Safety
KS	07/10/2008	07/14/2008	Fire Safety
KS	07/10/2008	07/14/2008	Fire Safety

	detectors.	
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN

sumner regional medical center

Based on VSDA2

KS	07/10/2008	07/17/2008	Fire Safety
KS	07/10/2008	07/14/2008	Fire Safety
KS	07/10/2008	07/17/2008	Fire Safety
KS	07/10/2008	07/11/2008	Fire Safety
KS	07/10/2008	07/17/2008	Fire Safety
KS	07/10/2008	07/17/2008	Fire Safety
KS	07/10/2008	07/17/2008	Fire Safety
KS	08/10/2009	09/04/2009	Fire Safety
KS	08/10/2009	09/04/2009	Fire Safety
KS	08/10/2009	09/04/2009	Fire Safety
KS	08/10/2009	09/04/2009	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN
175474	CHAPMAN VALLEY MANOR	CHAPMAN

sumner regional medical center

Based on VSDA2

KS	08/10/2009	09/04/2009	Fire Safety
KS	08/10/2009	08/13/2009	Fire Safety
KS	08/10/2009	09/04/2009	Fire Safety
KS	08/10/2009	09/04/2009	Fire Safety
KS	08/10/2009	08/10/2009	Fire Safety
KS	08/10/2009	09/04/2009	Fire Safety
KS	08/10/2009	08/12/2009	Fire Safety
KS	08/10/2009	08/12/2009	Fire Safety
KS	08/10/2009	09/04/2009	Fire Safety
KS	08/10/2009	09/04/2009	Fire Safety

	for one hour or an approved fire extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175475	ENTERPRISE ESTATES NURSING CENTER	ENTERPRISE
175475	ENTERPRISE ESTATES NURSING CENTER	ENTERPRISE
175475	ENTERPRISE ESTATES NURSING CENTER	ENTERPRISE
175475	ENTERPRISE ESTATES NURSING CENTER	ENTERPRISE
175475	ENTERPRISE ESTATES NURSING CENTER	ENTERPRISE
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS

sumner regional medical center

Based on VSDA2

KS	05/18/2009	06/17/2009	Fire Safety
KS	05/18/2009	06/17/2009	Fire Safety
KS	05/18/2009	05/19/2009	Fire Safety
KS	05/18/2009	05/19/2009	Fire Safety
KS	05/18/2009	05/19/2009	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE	SHARON

sumner regional medical center

Based on VSDA2

KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	08/21/2008	09/20/2008	Fire Safety
KS	07/20/2009	08/18/2009	Fire Safety
KS	07/20/2009	08/18/2009	Fire Safety
KS	07/20/2009	08/18/2009	Fire Safety
KS	07/20/2009	08/18/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

	MANOR	SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175476	GOOD SAMARITAN SOCIETY - PRAIRIE MANOR	SHARON SPRINGS
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE

sumner regional medical center

Based on VSDA2

KS	07/20/2009	08/18/2009	Fire Safety
KS	08/04/2010	09/04/2010	Fire Safety
KS	08/04/2010	09/03/2010	Fire Safety
KS	08/04/2010	09/03/2010	Fire Safety
KS	08/04/2010	09/03/2010	Fire Safety
KS	08/04/2010	09/03/2010	Fire Safety
KS	08/22/2007	09/20/2007	Fire Safety
KS	08/22/2007	09/20/2007	Fire Safety
KS	08/22/2007	09/20/2007	Fire Safety

	obstructions and can be used at all times.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE

sumner regional medical center

Based on VSDA2

KS	08/22/2007	09/20/2007	Fire Safety
KS	08/22/2007	09/20/2007	Fire Safety
KS	08/22/2007	09/20/2007	Fire Safety
KS	08/22/2007	09/20/2007	Fire Safety
KS	08/22/2007	09/20/2007	Fire Safety
KS	08/22/2008	09/19/2008	Fire Safety
KS	08/22/2008	08/22/2008	Fire Safety
KS	08/22/2008	09/19/2008	Fire Safety
KS	08/22/2008	09/19/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Widespread
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175477	LEONARDVILLE NURSING HOME	LEONARDVILLE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE

sumner regional medical center

Based on VSDA2

KS	08/22/2008	09/19/2008	Fire Safety
KS	08/22/2008	09/19/2008	Fire Safety
KS	08/22/2008	09/19/2008	Fire Safety
KS	08/22/2008	08/29/2008	Fire Safety
KS	08/22/2008	09/19/2008	Fire Safety
KS	08/22/2008	09/19/2008	Fire Safety
KS	08/22/2008	09/04/2008	Fire Safety
KS	08/22/2008	09/19/2008	Fire Safety
KS	08/22/2008	09/19/2008	Fire Safety
KS	09/22/2009	10/20/2009	Fire Safety
KS	09/18/2007	09/22/2007	Fire Safety

	hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE

sumner regional medical center

Based on VSDA2

KS	09/18/2007	09/18/2007	Fire Safety
KS	09/18/2007	10/17/2007	Fire Safety
KS	09/18/2007	11/20/2007	Fire Safety
KS	09/18/2007	09/18/2007	Fire Safety
KS	09/18/2007	09/18/2007	Fire Safety
KS	09/18/2007	09/18/2007	Fire Safety
KS	07/23/2008	08/21/2008	Fire Safety
KS	07/23/2008	08/15/2008	Fire Safety
KS	07/23/2008	07/29/2008	Fire Safety

	times.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175478	THE SWEET LIFE AT ROSEHILL	SHAWNEE
175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON

sumner regional medical center

Based on VSDA2

KS	07/23/2008	07/29/2008	Fire Safety
KS	10/06/2009	10/16/2009	Fire Safety
KS	10/06/2009	10/16/2009	Fire Safety
KS	10/06/2009	10/16/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	01/08/2009	Fire Safety

	administration areas.	
Laboratories Deficiencies	emergency showers.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON
175479	SOLOMON VALLEY MANOR	STOCKTON
175480	LOGAN MANOR COMMUNITY HEALTH SERVICES	LOGAN
175480	LOGAN MANOR COMMUNITY HEALTH SERVICES	LOGAN
175480	LOGAN MANOR COMMUNITY HEALTH SERVICES	LOGAN
175480	LOGAN MANOR COMMUNITY HEALTH SERVICES	LOGAN
175480	LOGAN MANOR COMMUNITY HEALTH	LOGAN

sumner regional medical center

Based on VSDA2

KS	12/09/2008	01/08/2009	Fire Safety
KS	12/09/2008	12/17/2008	Fire Safety
KS	12/01/2009	12/01/2009	Fire Safety
KS	01/11/2011	01/24/2011	Fire Safety
KS	01/11/2011	01/19/2011	Fire Safety
KS	01/11/2011	01/11/2011	Fire Safety
KS	09/30/2008	10/27/2008	Fire Safety
KS	09/30/2008	10/27/2008	Fire Safety
KS	09/30/2008	10/27/2008	Fire Safety
KS	09/30/2008	10/27/2008	Fire Safety
KS	09/30/2008	10/27/2008	Fire Safety

	facilities.	
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	SERVICES	
175480	LOGAN MANOR COMMUNITY HEALTH SERVICES	LOGAN
175480	LOGAN MANOR COMMUNITY HEALTH SERVICES	LOGAN
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE

sumner regional medical center

Based on VSDA2

KS	08/06/2009	08/19/2009	Fire Safety
KS	08/11/2010	09/01/2010	Fire Safety
KS	07/23/2008	07/24/2008	Fire Safety
KS	07/23/2008	08/12/2008	Fire Safety
KS	07/23/2008	07/28/2008	Fire Safety
KS	07/23/2008	07/24/2008	Fire Safety
KS	07/23/2008	08/12/2008	Fire Safety
KS	07/23/2008	07/30/2008	Fire Safety
KS	07/23/2008	08/20/2008	Fire Safety

	have been maintained in working order.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE

sumner regional medical center

Based on VSDA2

KS	07/23/2008	07/30/2008	Fire Safety
KS	07/23/2008	07/30/2008	Fire Safety
KS	07/23/2008	07/30/2008	Fire Safety
KS	07/23/2008	07/30/2008	Fire Safety
KS	09/28/2009	10/26/2009	Fire Safety
KS	09/28/2009	09/28/2009	Fire Safety
KS	09/28/2009	10/09/2009	Fire Safety
KS	09/28/2009	10/26/2009	Fire Safety
KS	09/28/2009	09/28/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175481	MOUNT HOPE NURSING CENTER	MOUNT HOPE
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO

sumner regional medical center

Based on VSDA2

KS	10/22/2010	10/23/2010	Fire Safety
KS	10/22/2010	10/29/2010	Fire Safety
KS	10/22/2010	10/23/2010	Fire Safety
KS	10/30/2007	11/02/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/30/2007	10/30/2007	Fire Safety
KS	10/30/2007	11/28/2007	Fire Safety
KS	10/08/2008	10/24/2008	Fire Safety
KS	10/08/2008	10/24/2008	Fire Safety
KS	10/08/2008	10/24/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Electrical Deficiencies	proper power supply for life support equipment.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175484	SALEM HOME	HILLSBORO
175486	THE KANSAS REHABILITATION HOSPITAL	TOPEKA

sumner regional medical center

Based on VSDA2

KS	10/08/2008	10/24/2008	Fire Safety
KS	10/08/2008	10/24/2008	Fire Safety
KS	10/08/2008	10/24/2008	Fire Safety
KS	10/08/2008	10/24/2008	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	10/22/2009	11/20/2009	Fire Safety
KS	08/25/2008	09/05/2008	Fire Safety

	extinguishing system.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Building Construction Deficiencies	approved construction type or	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	LTCU	
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL	TOPEKA

KS	08/25/2008	09/12/2008	Fire Safety
KS	08/25/2008	09/12/2008	Fire Safety
KS	08/25/2008	09/17/2008	Fire Safety
KS	08/25/2008	09/17/2008	Fire Safety
KS	08/25/2008	09/05/2008	Fire Safety
KS	08/25/2008	09/23/2008	Fire Safety
KS	08/25/2008	09/23/2008	Fire Safety
KS	08/25/2008	09/12/2008	Fire Safety
KS	08/25/2008	09/23/2008	Fire Safety
KS	08/25/2008	09/12/2008	Fire Safety

	materials.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	LTCU	
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA

sumner regional medical center

Based on VSDA2

KS	08/25/2008	09/12/2008	Fire Safety
KS	08/25/2008	09/19/2008	Fire Safety
KS	08/25/2008	09/19/2008	Fire Safety
KS	08/25/2008	09/12/2008	Fire Safety
KS	08/25/2008	09/19/2008	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety

	have been maintained in working order.	
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	LTCU	
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA

sumner regional medical center

Based on VSDA2

KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	09/16/2009	10/15/2009	Fire Safety
KS	12/02/2010	12/02/2010	Fire Safety
KS	12/02/2010	12/13/2010	Fire Safety
KS	12/02/2010	12/02/2010	Fire Safety
KS	12/02/2010	12/20/2010	Fire Safety
KS	12/02/2010	12/17/2010	Fire Safety

	resist smoke for at least 20 minutes.	
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175486	THE KANSAS REHABILITATION HOSPITAL LTCU	TOPEKA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	12/02/2010	12/17/2010	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety

	all times.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/05/2008	07/04/2008	Fire Safety
KS	06/11/2009	07/10/2009	Fire Safety
KS	06/11/2009	07/10/2009	Fire Safety
KS	07/14/2010	07/30/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175487	HOMESTEAD HEALTH CENTER	WICHITA
175487	HOMESTEAD HEALTH CENTER	WICHITA
175488	WINFIELD REST HAVEN II, LLC	WINFIELD
175488	WINFIELD REST HAVEN II, LLC	WINFIELD
175488	WINFIELD REST HAVEN II, LLC	WINFIELD
175488	WINFIELD REST HAVEN II, LLC	WINFIELD
175488	WINFIELD REST HAVEN II, LLC	WINFIELD
175488	WINFIELD REST HAVEN II, LLC	WINFIELD
175488	WINFIELD REST HAVEN II, LLC	WINFIELD

sumner regional medical center

Based on VSDA2

KS	07/14/2010	07/30/2010	Fire Safety
KS	07/14/2010	07/30/2010	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	07/09/2008	08/08/2008	Fire Safety
KS	08/18/2009	09/17/2009	Fire Safety
KS	10/12/2010	11/06/2010	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175488	WINFIELD REST HAVEN II, LLC	WINFIELD
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE

sumner regional medical center

Based on VSDA2

KS	10/12/2010	11/06/2010	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE

KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/07/2009	04/10/2009	Fire Safety
KS	04/07/2009	04/17/2009	Fire Safety
KS	04/07/2009	04/10/2009	Fire Safety
KS	04/07/2009	04/10/2009	Fire Safety
KS	04/07/2009	04/10/2009	Fire Safety
KS	04/07/2009	05/07/2009	Fire Safety

	heard throughout the facility.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175489	PRAIRIE SUNSET HOME INC	PRETTY PRAIRIE
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON

sumner regional medical center

Based on VSDA2

KS	04/07/2009	05/07/2009	Fire Safety
KS	04/07/2009	04/10/2009	Fire Safety
KS	05/26/2010	06/01/2010	Fire Safety
KS	05/26/2010	06/03/2010	Fire Safety
KS	05/26/2010	06/15/2010	Fire Safety
KS	05/26/2010	06/01/2010	Fire Safety
KS	02/11/2008	03/10/2008	Fire Safety
KS	02/11/2008	03/10/2008	Fire Safety

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON

sumner regional medical center

Based on VSDA2

KS	02/11/2008	03/10/2008	Fire Safety
KS	02/11/2008	03/10/2008	Fire Safety
KS	02/11/2008	03/10/2008	Fire Safety
KS	02/09/2009	03/09/2009	Fire Safety
KS	02/09/2009	03/09/2009	Fire Safety
KS	02/09/2009	03/09/2009	Fire Safety
KS	02/09/2009	03/09/2009	Fire Safety
KS	02/09/2009	03/09/2009	Fire Safety
KS	02/09/2009	03/09/2009	Fire Safety

	for one hour or an approved fire extinguishing system.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON

sumner regional medical center

Based on VSDA2

KS	02/09/2009	03/09/2009	Fire Safety
KS	02/09/2009	03/09/2009	Fire Safety
KS	02/09/2009	03/09/2009	Fire Safety
KS	01/20/2010	02/18/2010	Fire Safety
KS	01/20/2010	02/18/2010	Fire Safety
KS	01/20/2010	01/20/2010	Fire Safety
KS	01/20/2010	02/18/2010	Fire Safety
KS	01/20/2010	02/18/2010	Fire Safety
KS	01/20/2010	02/18/2010	Fire Safety
KS	01/20/2010	02/18/2010	Fire Safety
KS	01/20/2010	02/18/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175490	MEDICALODGES HERINGTON	HERINGTON
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE

sumner regional medical center

Based on VSDA2

KS	01/20/2010	01/20/2010	Fire Safety
KS	01/20/2010	01/20/2010	Fire Safety
KS	01/20/2010	02/18/2010	Fire Safety
KS	10/17/2007	10/29/2007	Fire Safety
KS	10/17/2007	10/19/2007	Fire Safety
KS	10/17/2007	10/25/2007	Fire Safety
KS	10/17/2007	11/08/2007	Fire Safety
KS	10/17/2007	10/22/2007	Fire Safety
KS	10/17/2007	10/31/2007	Fire Safety
KS	10/17/2007	10/31/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE

sumner regional medical center

Based on VSDA2

KS	10/17/2007	11/08/2007	Fire Safety
KS	12/22/2008	12/31/2008	Fire Safety
KS	12/22/2008	12/31/2008	Fire Safety
KS	12/22/2008	12/31/2008	Fire Safety
KS	12/22/2008	12/29/2008	Fire Safety
KS	12/22/2008	12/29/2008	Fire Safety
KS	01/12/2010	01/12/2010	Fire Safety
KS	01/12/2010	01/12/2010	Fire Safety
KS	01/12/2010	01/18/2010	Fire Safety
KS	01/12/2010	01/18/2010	Fire Safety
KS	01/12/2010	01/12/2010	Fire Safety

	administration areas.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Building Service Equipment Deficiencies	restrictions on the use of portable	Widespread

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175491	HOEGER HOUSE	OLATHE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE

sumner regional medical center

Based on VSDA2

KS	01/12/2010	01/20/2010	Fire Safety
KS	01/12/2010	02/11/2010	Fire Safety
KS	01/12/2010	01/19/2010	Fire Safety
KS	07/31/2007	08/30/2007	Fire Safety
KS	07/31/2007	08/23/2007	Fire Safety
KS	07/31/2007	08/13/2007	Fire Safety
KS	07/31/2007	08/10/2007	Fire Safety
KS	07/31/2007	08/30/2007	Fire Safety
KS	07/31/2007	08/09/2007	Fire Safety
KS	07/31/2007	08/16/2007	Fire Safety

	space heaters.	
Medical Gases and Anesthetizing Areas Deficiencies	proper fire barriers, ventilation and signs for the transport of oxygen.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE

sumner regional medical center

Based on VSDA2

KS	07/31/2007	08/30/2007	Fire Safety
KS	07/31/2007	07/31/2007	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety

	conditions.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE

sumner regional medical center

Based on VSDA2

KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	08/29/2008	09/28/2008	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety

	conditions.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175492	PARK VILLA	CLYDE
175494	LINN COMMUNITY NURSING HOME	LINN

KS	09/22/2009	10/22/2009	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety
KS	09/22/2009	10/22/2009	Fire Safety
KS	12/10/2007	12/12/2007	Fire Safety

	for one hour or an approved fire extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN

KS	12/10/2007	12/12/2007	Fire Safety
KS	12/10/2007	01/09/2008	Fire Safety
KS	02/25/2009	03/26/2009	Fire Safety
KS	02/25/2009	03/26/2009	Fire Safety
KS	02/25/2009	03/06/2009	Fire Safety
KS	02/25/2009	03/26/2009	Fire Safety
KS	02/25/2009	03/26/2009	Fire Safety
KS	02/25/2009	03/04/2009	Fire Safety
KS	02/25/2009	03/05/2009	Fire Safety

	for one hour or an approved fire extinguishing system.	
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175494	LINN COMMUNITY NURSING HOME	LINN
175496	PRATT REHABILITATION AND RESIDENCE	PRATT

sumner regional medical center

Based on VSDA2

KS	02/25/2009	02/25/2009	Fire Safety
KS	03/29/2010	03/30/2010	Fire Safety
KS	03/29/2010	03/30/2010	Fire Safety
KS	03/29/2010	03/30/2010	Fire Safety
KS	03/29/2010	03/30/2010	Fire Safety
KS	03/29/2010	03/30/2010	Fire Safety
KS	03/29/2010	04/01/2010	Fire Safety
KS	03/29/2010	04/12/2010	Fire Safety
KS	03/29/2010	03/30/2010	Fire Safety
KS	03/29/2010	03/30/2010	Fire Safety
KS	07/22/2008	08/20/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	CENTER	
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT

sumner regional medical center

Based on VSDA2

KS	07/22/2008	08/20/2008	Fire Safety
KS	07/22/2008	08/20/2008	Fire Safety
KS	07/22/2008	08/20/2008	Fire Safety
KS	07/22/2008	08/20/2008	Fire Safety
KS	07/22/2008	08/20/2008	Fire Safety
KS	07/22/2008	08/20/2008	Fire Safety
KS	07/22/2008	08/20/2008	Fire Safety
KS	07/22/2008	08/20/2008	Fire Safety
KS	07/01/2009	07/10/2009	Fire Safety
KS	07/01/2009	07/10/2009	Fire Safety
KS	07/01/2009	07/10/2009	Fire Safety
KS	08/12/2010	08/12/2010	Fire Safety

	materials.	
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175496	PRATT REHABILITATION AND RESIDENCE CENTER	PRATT
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE

sumner regional medical center

Based on VSDA2

KS	08/12/2010	08/12/2010	Fire Safety
KS	12/05/2007	01/05/2008	Fire Safety
KS	12/05/2007	01/05/2008	Fire Safety
KS	12/05/2007	01/05/2008	Fire Safety
KS	12/05/2007	01/05/2008	Fire Safety
KS	12/05/2007	01/05/2008	Fire Safety
KS	12/05/2007	01/05/2008	Fire Safety
KS	12/05/2007	01/05/2008	Fire Safety
KS	12/05/2007	01/05/2008	Fire Safety
KS	01/14/2009	02/06/2009	Fire Safety

	would resist fire for at least one hour.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175497	RIVERVIEW ESTATES	MARQUETTE
175498	ST JOHN'S OF HAYS	HAYS

sumner regional medical center

Based on VSDA2

KS	01/14/2009	02/06/2009	Fire Safety
KS	01/14/2009	01/15/2009	Fire Safety
KS	01/14/2009	01/14/2009	Fire Safety
KS	01/14/2009	02/06/2009	Fire Safety
KS	01/14/2009	01/14/2009	Fire Safety
KS	03/26/2010	04/20/2010	Fire Safety
KS	03/26/2010	04/08/2010	Fire Safety
KS	03/26/2010	04/07/2010	Fire Safety
KS	03/26/2010	04/05/2010	Fire Safety
KS	03/26/2010	04/09/2010	Fire Safety
KS	05/06/2008	06/05/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Widespread
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175498	ST JOHN'S OF HAYS	HAYS
175498	ST JOHN'S OF HAYS	HAYS
175498	ST JOHN'S OF HAYS	HAYS
175498	ST JOHN'S OF HAYS	HAYS
175498	ST JOHN'S OF HAYS	HAYS
175498	ST JOHN'S OF HAYS	HAYS
175498	ST JOHN'S OF HAYS	HAYS
175498	ST JOHN'S OF HAYS	HAYS
175498	ST JOHN'S OF HAYS	HAYS
175498	ST JOHN'S OF HAYS	HAYS

sumner regional medical center

Based on VSDA2

KS	05/06/2008	05/07/2008	Fire Safety
KS	05/06/2008	05/09/2008	Fire Safety
KS	05/06/2008	05/09/2008	Fire Safety
KS	05/06/2008	06/05/2008	Fire Safety
KS	05/06/2008	06/05/2008	Fire Safety
KS	05/06/2008	05/06/2008	Fire Safety
KS	03/12/2009	04/09/2009	Fire Safety
KS	03/12/2009	04/09/2009	Fire Safety
KS	03/12/2009	04/09/2009	Fire Safety
KS	03/12/2009	04/09/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175498	ST JOHN'S OF HAYS	HAYS
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE

KS	03/12/2009	04/09/2009	Fire Safety
KS	03/28/2008	04/17/2008	Fire Safety
KS	03/28/2008	04/18/2008	Fire Safety
KS	03/28/2008	04/17/2008	Fire Safety
KS	03/28/2008	04/17/2008	Fire Safety
KS	03/28/2008	04/14/2008	Fire Safety
KS	03/28/2008	04/18/2008	Fire Safety
KS	03/28/2008	04/14/2008	Fire Safety
KS	03/28/2008	04/14/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175499	BRIGHTON GARDENS OF PRAIRIE VILLAGE	PRAIRIE VILLAGE
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN

KS	03/28/2008	04/18/2008	Fire Safety
KS	03/28/2008	04/11/2008	Fire Safety
KS	03/28/2008	04/25/2008	Fire Safety
KS	03/28/2008	04/25/2008	Fire Safety
KS	06/03/2009	06/03/2009	Fire Safety
KS	06/03/2009	06/03/2009	Fire Safety
KS	02/18/2008	02/23/2008	Fire Safety
KS	02/18/2008	02/19/2008	Fire Safety
KS	02/18/2008	02/19/2008	Fire Safety
KS	02/18/2008	02/19/2008	Fire Safety
KS	03/25/2009	03/25/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN
175500	HILL TOP HOUSE	BUCKLIN

sumner regional medical center

Based on VSDA2

KS	03/25/2009	04/01/2009	Fire Safety
KS	03/25/2009	03/25/2009	Fire Safety
KS	03/25/2009	04/01/2009	Fire Safety
KS	03/25/2009	04/01/2009	Fire Safety
KS	03/25/2009	03/25/2009	Fire Safety
KS	03/25/2009	03/31/2009	Fire Safety
KS	03/12/2010	03/12/2010	Fire Safety
KS	03/12/2010	03/17/2010	Fire Safety
KS	03/12/2010	03/12/2010	Fire Safety

sumner regional medical center

Based on VSDA2

	block smoke.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175500	HILL TOP HOUSE	BUCKLIN
175501	FAMILY HEALTH & REHABILITATION CENTER	WICHITA
175501	FAMILY HEALTH & REHABILITATION CENTER	WICHITA
175501	FAMILY HEALTH & REHABILITATION CENTER	WICHITA
175501	FAMILY HEALTH & REHABILITATION CENTER	WICHITA
175501	FAMILY HEALTH & REHABILITATION CENTER	WICHITA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA

sumner regional medical center

Based on VSDA2

KS	03/12/2010	03/12/2010	Fire Safety
KS	10/09/2008	10/14/2008	Fire Safety
KS	12/01/2009	01/26/2010	Fire Safety
KS	12/01/2009	12/28/2009	Fire Safety
KS	12/01/2009	02/05/2010	Fire Safety
KS	12/01/2009	12/18/2009	Fire Safety
KS	12/03/2007	12/03/2007	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA

sumner regional medical center

Based on VSDA2

KS	12/03/2007	01/02/2008	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety
KS	12/03/2007	12/07/2007	Fire Safety
KS	12/03/2007	12/05/2007	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety
KS	12/03/2007	12/03/2007	Fire Safety
KS	12/03/2007	01/02/2008	Fire Safety
KS	03/09/2009	04/08/2009	Fire Safety
KS	03/09/2009	04/08/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175502	MEDICALODGES EUDORA	EUDORA
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE

sumner regional medical center

Based on VSDA2

KS	03/09/2009	04/08/2009	Fire Safety
KS	05/14/2010	06/12/2010	Fire Safety
KS	05/14/2010	06/12/2010	Fire Safety
KS	07/29/2008	08/07/2008	Fire Safety
KS	07/29/2008	08/07/2008	Fire Safety
KS	07/29/2008	08/07/2008	Fire Safety
KS	07/29/2008	08/07/2008	Fire Safety
KS	07/29/2008	08/07/2008	Fire Safety
KS	07/29/2008	08/07/2008	Fire Safety

sumner regional medical center

Based on VSDA2

	maintenance and testing program for fire alarm systems.	
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	MARTA	
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE

sumner regional medical center

Based on VSDA2

KS	07/29/2008	08/07/2008	Fire Safety
KS	07/29/2008	08/07/2008	Fire Safety
KS	07/29/2008	08/07/2008	Fire Safety
KS	04/01/2009	04/09/2009	Fire Safety
KS	04/01/2009	04/09/2009	Fire Safety
KS	04/01/2009	04/09/2009	Fire Safety
KS	04/01/2009	04/09/2009	Fire Safety
KS	04/01/2009	04/09/2009	Fire Safety
KS	06/03/2010	07/03/2010	Fire Safety

	at least 1 1/2 hours.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175503	THE PLAZA HEALTH SERVICES AT SANTA MARTA	OLATHE
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS

sumner regional medical center

Based on VSDA2

KS	06/03/2010	07/03/2010	Fire Safety
KS	06/03/2010	07/03/2010	Fire Safety
KS	06/03/2010	07/03/2010	Fire Safety
KS	03/31/2008	04/23/2008	Fire Safety
KS	03/31/2008	04/05/2008	Fire Safety
KS	03/31/2008	04/05/2008	Fire Safety
KS	03/31/2008	03/31/2008	Fire Safety
KS	03/31/2008	04/15/2008	Fire Safety
KS	03/31/2008	04/18/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175504	SPRING VIEW MANOR	CONWAY SPRINGS
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT

sumner regional medical center

Based on VSDA2

KS	03/31/2008	04/15/2008	Fire Safety
KS	03/31/2008	04/03/2008	Fire Safety
KS	03/24/2009	04/01/2009	Fire Safety
KS	03/24/2009	03/24/2009	Fire Safety
KS	03/24/2009	03/26/2009	Fire Safety
KS	05/05/2010	05/28/2010	Fire Safety
KS	05/05/2010	05/05/2010	Fire Safety
KS	05/05/2010	05/11/2010	Fire Safety
KS	03/20/2008	04/18/2008	Fire Safety
KS	03/20/2008	04/15/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT

sumner regional medical center

Based on VSDA2

KS	03/20/2008	03/31/2008	Fire Safety
KS	03/20/2008	04/15/2008	Fire Safety
KS	03/20/2008	03/31/2008	Fire Safety
KS	03/20/2008	03/20/2008	Fire Safety
KS	03/20/2008	04/15/2008	Fire Safety
KS	03/20/2008	03/31/2008	Fire Safety
KS	06/23/2009	09/02/2009	Fire Safety
KS	06/23/2009	06/26/2009	Fire Safety
KS	06/23/2009	06/25/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175505	MITCHELL COUNTY HOSPITAL HEALTH SYSTEMS LTCU	BELOIT
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON

sumner regional medical center

Based on VSDA2

KS	05/06/2010	05/28/2010	Fire Safety
KS	05/06/2010	05/28/2010	Fire Safety
KS	05/06/2010	05/28/2010	Fire Safety
KS	05/06/2010	05/28/2010	Fire Safety
KS	01/31/2008	02/01/2008	Fire Safety
KS	01/31/2008	02/07/2008	Fire Safety
KS	01/31/2008	02/15/2008	Fire Safety
KS	01/31/2008	02/15/2008	Fire Safety
KS	01/31/2008	02/01/2008	Fire Safety
KS	01/31/2008	02/01/2008	Fire Safety
KS	01/31/2008	02/28/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON

sumner regional medical center

Based on VSDA2

KS	01/31/2008	01/31/2008	Fire Safety
KS	01/31/2008	01/31/2008	Fire Safety
KS	01/31/2008	02/01/2008	Fire Safety
KS	10/02/2008	11/01/2008	Fire Safety
KS	10/02/2008	11/01/2008	Fire Safety
KS	10/02/2008	10/06/2008	Fire Safety
KS	10/02/2008	11/01/2008	Fire Safety
KS	10/02/2008	11/01/2008	Fire Safety
KS	10/02/2008	11/01/2008	Fire Safety
KS	10/02/2008	10/24/2008	Fire Safety
KS	10/02/2008	11/01/2008	Fire Safety

	flammable curtains.	
Laboratories Deficiencies	emergency showers.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Interior Finish Deficiencies	fire-resistant interior walls.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175506	ANDBE HOME, INC	NORTON
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG

sumner regional medical center

Based on VSDA2

KS	10/08/2009	11/06/2009	Fire Safety
KS	10/08/2009	11/06/2009	Fire Safety
KS	10/08/2009	10/16/2009	Fire Safety
KS	09/10/2008	09/10/2008	Fire Safety
KS	09/10/2008	09/10/2008	Fire Safety
KS	09/10/2008	10/10/2008	Fire Safety
KS	09/10/2008	09/12/2008	Fire Safety
KS	09/10/2008	09/10/2008	Fire Safety
KS	09/10/2008	10/10/2008	Fire Safety
KS	09/10/2008	09/12/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175507	BETHANY HOME ASSOCIATION	LINDSBORG
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA

sumner regional medical center

Based on VSDA2

KS	09/10/2008	09/12/2008	Fire Safety
KS	09/10/2008	09/10/2008	Fire Safety
KS	09/10/2008	09/10/2008	Fire Safety
KS	09/10/2008	09/10/2008	Fire Safety
KS	09/10/2008	10/10/2008	Fire Safety
KS	10/08/2009	10/08/2009	Fire Safety
KS	10/08/2009	10/29/2009	Fire Safety
KS	06/11/2008	07/09/2008	Fire Safety
KS	06/11/2008	07/09/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA

sumner regional medical center

Based on VSDA2

KS	06/11/2008	07/09/2008	Fire Safety
KS	06/11/2008	07/09/2008	Fire Safety
KS	06/11/2008	07/09/2008	Fire Safety
KS	06/11/2008	07/09/2008	Fire Safety
KS	06/11/2008	07/09/2008	Fire Safety
KS	06/11/2008	06/11/2008	Fire Safety
KS	06/11/2008	07/09/2008	Fire Safety
KS	06/11/2008	07/09/2008	Fire Safety
KS	06/11/2008	07/09/2008	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Interior Finish Deficiencies	fire-resistant interior walls.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA

sumner regional medical center

Based on VSDA2

KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	10/18/2010	11/17/2010	Fire Safety
KS	10/18/2010	11/17/2010	Fire Safety
KS	10/18/2010	11/17/2010	Fire Safety
KS	10/18/2010	10/30/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175508	MAPLE HEIGHTS NURSING & REHABILITATION CENTER	HIAWATHA
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER

sumner regional medical center

Based on VSDA2

KS	10/18/2010	10/29/2010	Fire Safety
KS	10/18/2010	11/17/2010	Fire Safety
KS	10/18/2010	11/17/2010	Fire Safety
KS	12/04/2007	12/15/2007	Fire Safety
KS	12/04/2007	12/15/2007	Fire Safety
KS	12/04/2007	12/04/2007	Fire Safety
KS	01/13/2009	01/14/2009	Fire Safety
KS	01/13/2009	01/14/2009	Fire Safety
KS	01/13/2009	02/10/2009	Fire Safety
KS	01/13/2009	02/10/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER

sumner regional medical center

Based on VSDA2

KS	02/05/2010	03/04/2010	Fire Safety
KS	02/05/2010	02/26/2010	Fire Safety
KS	02/05/2010	02/06/2010	Fire Safety
KS	02/05/2010	02/09/2010	Fire Safety
KS	02/05/2010	02/26/2010	Fire Safety
KS	02/05/2010	03/04/2010	Fire Safety
KS	02/05/2010	02/15/2010	Fire Safety
KS	02/05/2010	02/15/2010	Fire Safety
KS	02/05/2010	02/15/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175509	SANDSTONE HEIGHTS	LITTLE RIVER
175511	WINDSOR PLACE OF INDEPENDENCE LLC	INDEPENDENCE
175511	WINDSOR PLACE OF INDEPENDENCE LLC	INDEPENDENCE
175511	WINDSOR PLACE OF INDEPENDENCE LLC	INDEPENDENCE
175511	WINDSOR PLACE OF INDEPENDENCE LLC	INDEPENDENCE
175511	WINDSOR PLACE OF INDEPENDENCE LLC	INDEPENDENCE
175511	WINDSOR PLACE OF INDEPENDENCE LLC	INDEPENDENCE

sumner regional medical center

Based on VSDA2

KS	02/05/2010	04/01/2010	Fire Safety
KS	02/05/2010	02/15/2010	Fire Safety
KS	02/05/2010	03/04/2010	Fire Safety
KS	02/05/2010	02/15/2010	Fire Safety
KS	09/12/2008	09/16/2008	Fire Safety
KS	09/12/2008	09/16/2008	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety
KS	09/16/2009	10/16/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Laboratories Deficiencies	proper facilities for the use and storage of combustible liquids.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

175511	WINDSOR PLACE OF INDEPENDENCE LLC	INDEPENDENCE
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON

sumner regional medical center

Based on VSDA2

KS	09/16/2009	10/16/2009	Fire Safety
KS	07/01/2008	07/02/2008	Fire Safety
KS	07/01/2008	07/03/2008	Fire Safety
KS	07/01/2008	07/03/2008	Fire Safety
KS	07/01/2008	07/15/2008	Fire Safety
KS	07/01/2008	07/15/2008	Fire Safety
KS	07/01/2008	07/01/2008	Fire Safety
KS	07/01/2008	07/08/2008	Fire Safety
KS	07/01/2008	07/03/2008	Fire Safety

	have been maintained in working order.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON

sumner regional medical center

Based on VSDA2

KS	08/21/2009	09/20/2009	Fire Safety
KS	08/21/2009	09/20/2009	Fire Safety
KS	08/21/2009	09/20/2009	Fire Safety
KS	08/21/2009	08/21/2009	Fire Safety
KS	08/21/2009	09/20/2009	Fire Safety
KS	08/21/2009	09/20/2009	Fire Safety
KS	08/21/2009	09/20/2009	Fire Safety
KS	09/22/2010	10/01/2010	Fire Safety
KS	09/22/2010	10/22/2010	Fire Safety
KS	09/22/2010	10/20/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175512	THE CENTENNIAL HOMESTEAD	WASHINGTON
175513	KANSAS SOLDIERS HOME	FORT DODGE
175513	KANSAS SOLDIERS HOME	FORT DODGE
175513	KANSAS SOLDIERS HOME	FORT DODGE

sumner regional medical center

Based on VSDA2

KS	09/22/2010	10/21/2010	Fire Safety
KS	09/22/2010	09/30/2010	Fire Safety
KS	09/22/2010	10/01/2010	Fire Safety
KS	09/22/2010	09/26/2010	Fire Safety
KS	09/22/2010	09/24/2010	Fire Safety
KS	09/22/2010	10/21/2010	Fire Safety
KS	09/22/2010	10/21/2010	Fire Safety
KS	08/17/2009	08/21/2009	Fire Safety
KS	08/17/2009	08/21/2009	Fire Safety
KS	08/17/2009	08/19/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	an externally vented heating system.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175513	KANSAS SOLDIERS HOME	FORT DODGE
175513	KANSAS SOLDIERS HOME	FORT DODGE
175513	KANSAS SOLDIERS HOME	FORT DODGE
175513	KANSAS SOLDIERS HOME	FORT DODGE
175513	KANSAS SOLDIERS HOME	FORT DODGE
175513	KANSAS SOLDIERS HOME	FORT DODGE
175515	TREGO MANOR	WAKEENEY
175515	TREGO MANOR	WAKEENEY
175515	TREGO MANOR	WAKEENEY
175516	KANSAS VETERANS HOME	WINFIELD

sumner regional medical center

Based on VSDA2

KS	08/17/2009	08/19/2009	Fire Safety
KS	06/14/2010	06/14/2010	Fire Safety
KS	06/14/2010	06/15/2010	Fire Safety
KS	06/14/2010	06/22/2010	Fire Safety
KS	06/14/2010	06/14/2010	Fire Safety
KS	06/14/2010	07/14/2010	Fire Safety
KS	03/09/2010	04/08/2010	Fire Safety
KS	03/09/2010	04/08/2010	Fire Safety
KS	03/09/2010	04/08/2010	Fire Safety
KS	03/29/2010	04/15/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175516	KANSAS VETERANS HOME	WINFIELD
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	03/29/2010	04/05/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK

sumner regional medical center

Based on VSDA2

KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175517	SWEET LIFE AT GRAND COURT	OVERLAND PARK
175518	REPUBLIC COUNTY HOSPITAL LTCU	BELLEVILLE
175518	REPUBLIC COUNTY HOSPITAL LTCU	BELLEVILLE
175518	REPUBLIC COUNTY HOSPITAL LTCU	BELLEVILLE
175518	REPUBLIC COUNTY HOSPITAL LTCU	BELLEVILLE
175518	REPUBLIC COUNTY HOSPITAL LTCU	BELLEVILLE
175518	REPUBLIC COUNTY HOSPITAL LTCU	BELLEVILLE
175519	PRESCOTT COUNTRY VIEW NURSING HOME	PRESCOTT
175519	PRESCOTT COUNTRY VIEW NURSING HOME	PRESCOTT
175519	PRESCOTT COUNTRY VIEW NURSING HOME	PRESCOTT

sumner regional medical center

Based on VSDA2

KS	06/28/2010	06/28/2010	Fire Safety
KS	06/28/2010	06/28/2010	Fire Safety
KS	05/10/2010	05/17/2010	Fire Safety
KS	05/10/2010	05/18/2010	Fire Safety
KS	05/10/2010	05/18/2010	Fire Safety
KS	05/10/2010	05/18/2010	Fire Safety
KS	05/10/2010	06/01/2010	Fire Safety
KS	05/10/2010	05/28/2010	Fire Safety
KS	05/21/2010	05/21/2010	Fire Safety
KS	05/21/2010	06/04/2010	Fire Safety
KS	05/21/2010	06/18/2010	Fire Safety

	current fire safety codes.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

175519	PRESCOTT COUNTRY VIEW NURSING HOME	PRESCOTT
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE

sumner regional medical center

Based on VSDA2

KS	05/21/2010	05/26/2010	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	03/13/2008	Fire Safety

	have been maintained in working order.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE

KS	03/03/2009	04/02/2009	Fire Safety
KS	03/03/2009	04/02/2009	Fire Safety
KS	03/03/2009	04/02/2009	Fire Safety
KS	03/03/2009	04/02/2009	Fire Safety
KS	03/03/2009	03/04/2009	Fire Safety
KS	03/03/2009	03/31/2009	Fire Safety
KS	03/03/2009	03/04/2009	Fire Safety
KS	03/03/2009	03/05/2009	Fire Safety
KS	03/03/2009	03/06/2009	Fire Safety
KS	03/03/2009	04/02/2009	Fire Safety

	testing of generators.	
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE

sumner regional medical center

Based on VSDA2

KS	03/03/2009	04/02/2009	Fire Safety
KS	03/03/2009	04/02/2009	Fire Safety
KS	03/03/2009	03/03/2009	Fire Safety
KS	03/03/2009	03/31/2009	Fire Safety
KS	03/03/2009	04/02/2009	Fire Safety
KS	03/04/2010	04/04/2010	Fire Safety
KS	03/04/2010	03/04/2010	Fire Safety
KS	03/04/2010	03/31/2010	Fire Safety

sumner regional medical center

Based on VSDA2

	permitted or did not provide ashtrays where smoking was allowed.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A001	HAMILTON COUNTY HOSPITAL LTCU	SYRACUSE
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER

sumner regional medical center

Based on VSDA2

KS	03/04/2010	03/04/2010	Fire Safety
KS	03/04/2010	04/04/2010	Fire Safety
KS	10/04/2007	10/04/2007	Fire Safety
KS	10/04/2007	10/31/2007	Fire Safety
KS	10/04/2007	10/05/2007	Fire Safety
KS	10/04/2007	10/31/2007	Fire Safety
KS	10/01/2008	10/01/2008	Fire Safety
KS	10/01/2008	10/31/2008	Fire Safety
KS	10/01/2008	10/01/2008	Fire Safety
KS	10/07/2009	10/30/2009	Fire Safety

	allowed.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A019	SMITH COUNTY MEMORIAL HOSPITAL LTCU	SMITH CENTER
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY

sumner regional medical center

Based on VSDA2

KS	10/07/2009	10/07/2009	Fire Safety
KS	10/07/2009	10/30/2009	Fire Safety
KS	10/07/2009	10/30/2009	Fire Safety
KS	04/30/2008	05/21/2008	Fire Safety
KS	04/30/2008	05/21/2008	Fire Safety
KS	04/30/2008	05/21/2008	Fire Safety
KS	04/30/2008	05/21/2008	Fire Safety
KS	04/30/2008	05/21/2008	Fire Safety
KS	04/30/2008	05/21/2008	Fire Safety
KS	04/30/2008	05/21/2008	Fire Safety

	alarm system.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A020	TREGO CO-LEMKE MEMORIAL HOSPITAL LTCU	WAKEENEY
17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION

KS	05/13/2009	05/19/2009	Fire Safety
KS	05/13/2009	05/19/2009	Fire Safety
KS	05/20/2010	05/28/2010	Fire Safety
KS	05/20/2010	05/28/2010	Fire Safety
KS	04/15/2008	05/15/2008	Fire Safety
KS	04/15/2008	05/15/2008	Fire Safety
KS	04/15/2008	05/15/2008	Fire Safety
KS	04/15/2008	05/15/2008	Fire Safety
KS	04/15/2008	05/15/2008	Fire Safety
KS	04/15/2008	04/23/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION
17A029	ST LUKE LIVING CENTER	MARION
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN

sumner regional medical center

Based on VSDA2

KS	04/15/2008	04/17/2008	Fire Safety
KS	04/15/2008	04/16/2008	Fire Safety
KS	04/15/2008	05/15/2008	Fire Safety
KS	04/15/2008	05/15/2008	Fire Safety
KS	06/03/2009	06/24/2009	Fire Safety
KS	06/01/2010	06/01/2010	Fire Safety
KS	06/26/2008	07/26/2008	Fire Safety
KS	06/26/2008	07/03/2008	Fire Safety
KS	06/26/2008	07/03/2008	Fire Safety
KS	06/26/2008	07/26/2008	Fire Safety
KS	06/26/2008	07/26/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN
17A036	DECATUR COUNTY HOSPITAL LTCU	OBERLIN

KS	06/26/2008	07/03/2008	Fire Safety
KS	06/26/2008	07/26/2008	Fire Safety
KS	06/26/2008	07/26/2008	Fire Safety
KS	06/26/2008	07/07/2008	Fire Safety
KS	08/05/2009	08/14/2009	Fire Safety
KS	08/05/2009	08/21/2009	Fire Safety
KS	08/05/2009	08/28/2009	Fire Safety
KS	08/05/2009	08/21/2009	Fire Safety
KS	08/05/2009	08/05/2009	Fire Safety
KS	08/05/2009	08/21/2009	Fire Safety
KS	08/11/2010	08/11/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Electrical Deficiencies	properly installed electrical wiring	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND

sumner regional medical center

Based on VSDA2

KS	04/14/2008	04/21/2008	Fire Safety
KS	04/14/2008	04/21/2008	Fire Safety
KS	04/14/2008	05/01/2008	Fire Safety
KS	04/14/2008	04/21/2008	Fire Safety
KS	04/08/2009	04/29/2009	Fire Safety
KS	04/08/2009	04/17/2009	Fire Safety
KS	04/08/2009	05/07/2009	Fire Safety
KS	04/08/2009	05/07/2009	Fire Safety
KS	04/08/2009	05/07/2009	Fire Safety
KS	04/08/2009	05/07/2009	Fire Safety
KS	04/08/2009	05/07/2009	Fire Safety

	and equipment.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Interior Finish Deficiencies	fire-resistant interior walls.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke	Isolated

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E002	ASHLAND HEALTH CENTER LTCU	ASHLAND
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA

KS	04/08/2009	05/07/2009	Fire Safety
KS	04/08/2009	05/07/2009	Fire Safety
KS	04/08/2009	04/08/2009	Fire Safety
KS	04/08/2009	05/07/2009	Fire Safety
KS	04/20/2010	04/26/2010	Fire Safety
KS	04/20/2010	04/30/2010	Fire Safety
KS	04/20/2010	04/30/2010	Fire Safety
KS	09/08/2008	09/08/2008	Fire Safety
KS	09/08/2008	10/07/2008	Fire Safety
KS	09/08/2008	10/07/2008	Fire Safety

	detectors.	
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA
17E003	BETHEL HOME	MONTEZUMA

sumner regional medical center

Based on VSDA2

KS	09/08/2008	10/07/2008	Fire Safety
KS	09/08/2008	10/07/2008	Fire Safety
KS	09/08/2008	10/07/2008	Fire Safety
KS	09/08/2008	09/08/2008	Fire Safety
KS	09/29/2009	10/28/2009	Fire Safety
KS	09/29/2009	10/28/2009	Fire Safety
KS	09/29/2009	10/28/2009	Fire Safety
KS	09/29/2009	10/28/2009	Fire Safety
KS	09/29/2009	10/28/2009	Fire Safety
KS	09/29/2009	10/28/2009	Fire Safety

	heard throughout the facility.	
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	weekly inspections and monthly	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E003	BETHEL HOME	MONTEZUMA
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI

sumner regional medical center

Based on VSDA2

KS	09/29/2009	10/28/2009	Fire Safety
KS	04/30/2008	05/28/2008	Fire Safety
KS	04/30/2008	05/28/2008	Fire Safety
KS	04/30/2008	05/28/2008	Fire Safety
KS	04/30/2008	05/28/2008	Fire Safety
KS	04/30/2008	05/28/2008	Fire Safety
KS	04/30/2008	05/28/2008	Fire Safety
KS	04/30/2008	05/28/2008	Fire Safety
KS	04/30/2008	05/28/2008	Fire Safety
KS	04/30/2008	05/28/2008	Fire Safety

	testing of generators.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E011	WICHITA COUNTY HEALTH CENTER LTCU	LEOTI
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM

KS	04/30/2008	05/28/2008	Fire Safety
KS	04/23/2009	04/28/2009	Fire Safety
KS	04/23/2009	04/28/2009	Fire Safety
KS	04/23/2009	05/13/2009	Fire Safety
KS	04/23/2009	04/24/2009	Fire Safety
KS	05/10/2010	05/10/2010	Fire Safety
KS	05/10/2010	06/01/2010	Fire Safety
KS	05/10/2010	05/13/2010	Fire Safety
KS	05/10/2010	05/12/2010	Fire Safety
KS	05/29/2008	06/07/2008	Fire Safety
KS	05/29/2008	06/07/2008	Fire Safety
KS	05/29/2008	06/28/2008	Fire Safety

Laboratories Deficiencies	emergency showers.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Isolated
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM

sumner regional medical center

Based on VSDA2

KS	05/29/2008	06/02/2008	Fire Safety
KS	05/29/2008	06/28/2008	Fire Safety
KS	05/29/2008	06/10/2008	Fire Safety
KS	05/29/2008	06/07/2008	Fire Safety
KS	05/29/2008	06/28/2008	Fire Safety
KS	05/29/2008	06/07/2008	Fire Safety
KS	05/29/2008	06/07/2008	Fire Safety
KS	05/29/2008	06/07/2008	Fire Safety
KS	05/29/2008	06/07/2008	Fire Safety

	would resist fire for at least one hour.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E015	GRISELL MEMORIAL HOSPITAL LTCU	RANSOM
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE	MEADE

sumner regional medical center

Based on VSDA2

KS	06/18/2009	07/14/2009	Fire Safety
KS	06/18/2009	07/14/2009	Fire Safety
KS	06/18/2009	06/19/2009	Fire Safety
KS	06/18/2009	06/19/2009	Fire Safety
KS	05/21/2010	06/04/2010	Fire Safety
KS	05/28/2008	06/25/2008	Fire Safety
KS	05/28/2008	06/18/2008	Fire Safety
KS	05/28/2008	06/28/2008	Fire Safety
KS	05/28/2008	06/26/2008	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	04/20/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	TREE RETIREMENT	
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E026	MEADE DISTRICT HOSP LTCU DBA LONE TREE RETIREMENT	MEADE
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY

KS	04/08/2009	04/13/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	04/13/2009	Fire Safety
KS	06/03/2010	06/10/2010	Fire Safety
KS	07/24/2008	07/24/2008	Fire Safety
KS	07/24/2008	08/22/2008	Fire Safety
KS	07/24/2008	08/07/2008	Fire Safety
KS	07/24/2008	08/01/2008	Fire Safety
KS	07/24/2008	08/15/2008	Fire Safety
KS	07/24/2008	08/22/2008	Fire Safety

	detectors.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit"	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E029	PARK LANE NURSING HOME	SCOTT CITY
17E034	PROTECTION VALLEY MANOR	PROTECTION

sumner regional medical center

Based on VSDA2

KS	07/24/2008	08/22/2008	Fire Safety
KS	07/24/2008	07/25/2008	Fire Safety
KS	07/24/2008	08/24/2008	Fire Safety
KS	07/24/2008	07/25/2008	Fire Safety
KS	07/24/2008	08/16/2008	Fire Safety
KS	07/16/2009	07/31/2009	Fire Safety
KS	07/16/2009	07/24/2009	Fire Safety
KS	07/16/2009	07/24/2009	Fire Safety
KS	09/23/2010	10/18/2010	Fire Safety
KS	09/23/2010	10/04/2010	Fire Safety
KS	06/11/2008	07/11/2008	Fire Safety

	signs.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION

sumner regional medical center

Based on VSDA2

KS	06/11/2008	07/11/2008	Fire Safety
KS	06/11/2008	07/11/2008	Fire Safety
KS	06/11/2008	07/11/2008	Fire Safety
KS	06/11/2008	07/11/2008	Fire Safety
KS	06/11/2008	07/11/2008	Fire Safety
KS	06/11/2008	07/11/2008	Fire Safety
KS	06/11/2008	07/11/2008	Fire Safety
KS	06/11/2008	07/11/2008	Fire Safety
KS	06/11/2008	07/11/2008	Fire Safety
KS	06/29/2009	07/31/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E034	PROTECTION VALLEY MANOR	PROTECTION
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE

sumner regional medical center

Based on VSDA2

KS	06/29/2009	07/31/2009	Fire Safety
KS	06/29/2009	07/31/2009	Fire Safety
KS	06/29/2009	07/31/2009	Fire Safety
KS	08/12/2010	08/12/2010	Fire Safety
KS	08/12/2010	08/12/2010	Fire Safety
KS	08/12/2010	08/13/2010	Fire Safety
KS	10/10/2007	11/08/2007	Fire Safety
KS	10/10/2007	11/08/2007	Fire Safety
KS	10/10/2007	11/08/2007	Fire Safety
KS	10/23/2008	11/21/2008	Fire Safety
KS	10/23/2008	11/21/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Hazardous Area Deficiencies	construction that can resist fire	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E035	RUSH COUNTY MEMORIAL HOSPITAL LTCU	LA CROSSE
17E038	LAKEWOOD REHABILITATION CTR OF	HAVILAND

sumner regional medical center

Based on VSDA2

KS	10/23/2008	11/21/2008	Fire Safety
KS	10/23/2008	11/21/2008	Fire Safety
KS	10/23/2008	11/21/2008	Fire Safety
KS	10/12/2009	11/10/2009	Fire Safety
KS	10/12/2009	11/10/2009	Fire Safety
KS	10/12/2009	11/10/2009	Fire Safety
KS	10/12/2009	11/10/2009	Fire Safety
KS	10/12/2009	11/10/2009	Fire Safety
KS	10/12/2009	11/10/2009	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety

	for one hour or an approved fire extinguishing system.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridors that are separated from	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	HAVILAND	
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND

sumner regional medical center

Based on VSDA2

KS	05/22/2008	06/21/2008	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety

	common areas by walls constructed to limit the passage of smoke.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

	HAVILAND	
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF	HAVILAND

sumner regional medical center

Based on VSDA2

KS	05/22/2008	06/21/2008	Fire Safety
KS	05/22/2008	06/21/2008	Fire Safety
KS	06/08/2009	07/06/2009	Fire Safety
KS	06/08/2009	07/06/2009	Fire Safety
KS	06/08/2009	07/06/2009	Fire Safety
KS	06/08/2009	07/06/2009	Fire Safety
KS	06/08/2009	07/06/2009	Fire Safety
KS	06/08/2009	07/06/2009	Fire Safety
KS	06/08/2009	07/06/2009	Fire Safety
KS	06/08/2009	07/06/2009	Fire Safety
KS	06/11/2010	06/11/2010	Fire Safety

	facilities.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

	HAVILAND	
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E038	LAKEWOOD REHABILITATION CTR OF HAVILAND	HAVILAND
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES

sumner regional medical center

Based on VSDA2

KS	06/11/2010	07/11/2010	Fire Safety
KS	06/11/2010	07/11/2010	Fire Safety
KS	06/11/2010	06/15/2010	Fire Safety
KS	01/29/2008	02/27/2008	Fire Safety
KS	01/29/2008	02/27/2008	Fire Safety
KS	01/29/2008	02/27/2008	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety

	resist smoke for at least 20 minutes.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES

sumner regional medical center

Based on VSDA2

KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety
KS	04/21/2009	05/20/2009	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E041	THE LEGACY AT PARK VIEW	ULYSSES
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE

KS	04/21/2009	05/20/2009	Fire Safety
KS	04/29/2010	05/05/2010	Fire Safety
KS	04/29/2010	04/29/2010	Fire Safety
KS	04/29/2010	05/28/2010	Fire Safety
KS	04/29/2010	05/28/2010	Fire Safety
KS	08/28/2007	09/28/2007	Fire Safety
KS	08/28/2007	09/28/2007	Fire Safety
KS	08/28/2007	09/08/2007	Fire Safety
KS	08/28/2007	08/31/2007	Fire Safety
KS	09/11/2008	10/15/2008	Fire Safety

	administration areas.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE

sumner regional medical center

Based on VSDA2

KS	09/11/2008	10/30/2008	Fire Safety
KS	09/11/2008	09/18/2008	Fire Safety
KS	09/11/2008	09/15/2008	Fire Safety
KS	09/11/2008	10/01/2008	Fire Safety
KS	09/11/2008	10/15/2008	Fire Safety
KS	09/11/2008	10/15/2008	Fire Safety
KS	09/11/2008	09/15/2008	Fire Safety
KS	09/11/2008	09/15/2008	Fire Safety
KS	10/15/2009	10/15/2009	Fire Safety
KS	10/15/2009	10/15/2009	Fire Safety

	materials.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E071	GREELEY COUNTY HOSPITAL LTCU	TRIBUNE
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY

sumner regional medical center

Based on VSDA2

KS	10/15/2009	10/15/2009	Fire Safety
KS	10/15/2009	10/15/2009	Fire Safety
KS	03/06/2008	03/06/2008	Fire Safety
KS	03/06/2008	03/11/2008	Fire Safety
KS	03/06/2008	03/12/2008	Fire Safety
KS	03/06/2008	03/06/2008	Fire Safety
KS	03/06/2008	03/07/2008	Fire Safety
KS	05/12/2009	06/11/2009	Fire Safety
KS	05/12/2009	05/12/2009	Fire Safety
KS	05/12/2009	06/11/2009	Fire Safety

	each shift under varying conditions.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E181	CITIZENS MEDICAL CENTER LTCU	COLBY
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER

sumner regional medical center

Based on VSDA2

KS	05/12/2009	05/14/2009	Fire Safety
KS	05/12/2009	06/11/2009	Fire Safety
KS	05/12/2009	05/26/2009	Fire Safety
KS	05/14/2010	05/17/2010	Fire Safety
KS	06/17/2008	06/30/2008	Fire Safety
KS	06/17/2008	06/30/2008	Fire Safety
KS	06/17/2008	06/30/2008	Fire Safety
KS	06/17/2008	07/11/2008	Fire Safety
KS	06/17/2008	06/27/2008	Fire Safety
KS	06/17/2008	06/19/2008	Fire Safety

	detectors.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER

KS	06/17/2008	06/30/2008	Fire Safety
KS	06/17/2008	06/30/2008	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety
KS	04/16/2009	05/08/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E183	GOVE COUNTY MEDICAL CENTER LTCU	QUINTER
17E197	ROOKS CO SENIOR SERVICES INC DBA REDBUD VILLAGE	PLAINVILLE
17E197	ROOKS CO SENIOR SERVICES INC DBA REDBUD VILLAGE	PLAINVILLE
17E197	ROOKS CO SENIOR SERVICES INC DBA REDBUD VILLAGE	PLAINVILLE
17E197	ROOKS CO SENIOR SERVICES INC DBA REDBUD VILLAGE	PLAINVILLE
17E197	ROOKS CO SENIOR SERVICES INC DBA REDBUD VILLAGE	PLAINVILLE

sumner regional medical center

Based on VSDA2

KS	04/16/2009	05/08/2009	Fire Safety
KS	04/28/2010	04/30/2010	Fire Safety
KS	04/28/2010	05/14/2010	Fire Safety
KS	04/28/2010	05/14/2010	Fire Safety
KS	04/28/2010	05/14/2010	Fire Safety
KS	05/21/2008	06/20/2008	Fire Safety
KS	05/21/2008	06/20/2008	Fire Safety
KS	05/21/2008	06/20/2008	Fire Safety
KS	05/21/2008	06/20/2008	Fire Safety
KS	05/04/2009	05/13/2009	Fire Safety

	order.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

17E197	ROOKS CO SENIOR SERVICES INC DBA REDBUD VILLAGE	PLAINVILLE
17E197	ROOKS CO SENIOR SERVICES INC DBA REDBUD VILLAGE	PLAINVILLE
17E197	ROOKS CO SENIOR SERVICES INC DBA REDBUD VILLAGE	PLAINVILLE
17E197	ROOKS CO SENIOR SERVICES INC DBA REDBUD VILLAGE	PLAINVILLE
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA

KS	05/04/2009	05/13/2009	Fire Safety
KS	05/04/2009	05/13/2009	Fire Safety
KS	06/03/2010	06/12/2010	Fire Safety
KS	06/03/2010	06/18/2010	Fire Safety
KS	10/20/2008	10/23/2008	Fire Safety
KS	10/20/2008	11/18/2008	Fire Safety
KS	10/20/2008	10/28/2008	Fire Safety
KS	10/20/2008	10/23/2008	Fire Safety
KS	10/20/2008	10/21/2008	Fire Safety
KS	10/20/2008	10/28/2008	Fire Safety

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E200	ST JOHN'S OF VICTORIA	VICTORIA

sumner regional medical center

Based on VSDA2

KS	10/20/2008	11/18/2008	Fire Safety
KS	10/20/2008	10/27/2008	Fire Safety
KS	10/20/2008	11/18/2008	Fire Safety
KS	10/20/2008	10/29/2008	Fire Safety
KS	10/20/2008	10/24/2008	Fire Safety
KS	10/20/2008	10/23/2008	Fire Safety
KS	10/20/2008	10/24/2008	Fire Safety
KS	10/06/2009	10/20/2009	Fire Safety
KS	10/06/2009	10/09/2009	Fire Safety

	smoke proof.	
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E200	ST JOHN'S OF VICTORIA	VICTORIA
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY
17E210	WESTVIEW MANOR OF PEABODY	PEABODY

sumner regional medical center

Based on VSDA2

KS	10/12/2010	10/13/2010	Fire Safety
KS	11/07/2007	12/06/2007	Fire Safety
KS	11/07/2007	12/06/2007	Fire Safety
KS	11/07/2007	12/06/2007	Fire Safety
KS	11/07/2007	12/06/2007	Fire Safety
KS	02/18/2009	03/10/2009	Fire Safety
KS	02/18/2009	03/10/2009	Fire Safety
KS	03/24/2010	03/25/2010	Fire Safety
KS	03/24/2010	03/24/2010	Fire Safety
KS	03/24/2010	04/01/2010	Fire Safety
KS	03/24/2010	03/24/2010	Fire Safety

	testing of generators.	
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	properly installed electrical wiring	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO

sumner regional medical center
Based on VSDA2

KS	02/28/2008	03/20/2008	Fire Safety
KS	02/28/2008	02/28/2008	Fire Safety
KS	02/28/2008	03/27/2008	Fire Safety
KS	02/28/2008	03/27/2008	Fire Safety
KS	02/28/2008	03/27/2008	Fire Safety
KS	02/28/2008	03/27/2008	Fire Safety
KS	02/28/2008	03/27/2008	Fire Safety
KS	02/28/2008	02/28/2008	Fire Safety
KS	02/28/2008	03/27/2008	Fire Safety

	and equipment.	
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E223	JEWELL COUNTY HOSPITAL LTCU	MANKATO
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS

sumner regional medical center

Based on VSDA2

KS	05/08/2009	05/19/2009	Fire Safety
KS	05/08/2009	05/19/2009	Fire Safety
KS	05/08/2009	05/19/2009	Fire Safety
KS	05/08/2009	05/19/2009	Fire Safety
KS	05/08/2009	05/19/2009	Fire Safety
KS	05/08/2009	05/19/2009	Fire Safety
KS	05/10/2010	05/10/2010	Fire Safety
KS	05/10/2010	05/14/2010	Fire Safety
KS	05/10/2010	05/14/2010	Fire Safety
KS	10/15/2007	10/15/2007	Fire Safety

	and equipment.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS

sumner regional medical center

Based on VSDA2

KS	10/15/2007	11/15/2007	Fire Safety
KS	10/15/2007	11/15/2007	Fire Safety
KS	10/15/2007	11/15/2007	Fire Safety
KS	10/15/2007	12/06/2007	Fire Safety
KS	12/02/2008	01/02/2009	Fire Safety
KS	12/02/2008	01/02/2009	Fire Safety
KS	12/02/2008	01/02/2009	Fire Safety
KS	12/02/2008	01/02/2009	Fire Safety
KS	12/02/2008	01/02/2009	Fire Safety
KS	12/02/2008	01/02/2009	Fire Safety

	hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E242	COMMUNITY HOSPITAL ONAGA LTCU	ST MARYS
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON

sumner regional medical center

Based on VSDA2

KS	01/19/2010	02/19/2010	Fire Safety
KS	01/19/2010	01/19/2010	Fire Safety
KS	01/19/2010	02/19/2010	Fire Safety
KS	01/19/2010	02/19/2010	Fire Safety
KS	01/19/2010	02/19/2010	Fire Safety
KS	01/19/2010	02/19/2010	Fire Safety
KS	04/14/2008	04/30/2008	Fire Safety
KS	04/14/2008	04/30/2008	Fire Safety
KS	04/14/2008	04/30/2008	Fire Safety

	detectors.	
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON

sumner regional medical center

Based on VSDA2

KS	04/14/2008	05/13/2008	Fire Safety
KS	04/14/2008	04/30/2008	Fire Safety
KS	04/14/2008	04/30/2008	Fire Safety
KS	04/14/2008	04/30/2008	Fire Safety
KS	04/14/2008	04/30/2008	Fire Safety
KS	11/18/2008	12/15/2008	Fire Safety
KS	11/18/2008	12/15/2008	Fire Safety
KS	11/18/2008	12/15/2008	Fire Safety
KS	11/18/2008	12/15/2008	Fire Safety
KS	11/18/2008	12/15/2008	Fire Safety
KS	11/18/2008	12/15/2008	Fire Safety

	hour.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E254	ATCHISON SENIOR VILLAGE	ATCHISON
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA

sumner regional medical center

Based on VSDA2

KS	11/18/2008	12/15/2008	Fire Safety
KS	02/04/2010	02/06/2010	Fire Safety
KS	02/04/2010	03/04/2010	Fire Safety
KS	02/04/2010	02/04/2010	Fire Safety
KS	02/04/2010	03/04/2010	Fire Safety
KS	02/04/2010	03/04/2010	Fire Safety
KS	02/04/2010	03/04/2010	Fire Safety
KS	02/04/2010	03/04/2010	Fire Safety
KS	07/09/2008	08/05/2008	Fire Safety
KS	07/09/2008	08/05/2008	Fire Safety

	detectors.	
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Corridor Walls and Doors Deficiencies	properly constructed windows in hallway walls or doors.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA

sumner regional medical center

Based on VSDA2

KS	07/09/2008	08/05/2008	Fire Safety
KS	07/09/2008	08/05/2008	Fire Safety
KS	07/09/2008	08/05/2008	Fire Safety
KS	10/13/2009	12/02/2009	Fire Safety
KS	10/13/2009	11/20/2009	Fire Safety
KS	10/13/2009	11/20/2009	Fire Safety
KS	10/13/2009	11/20/2009	Fire Safety
KS	10/13/2009	11/20/2009	Fire Safety
KS	10/13/2009	11/20/2009	Fire Safety
KS	10/13/2009	11/20/2009	Fire Safety
KS	01/12/2011	02/01/2011	Fire Safety

	would resist fire for at least one hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E256	BRIGHTON PLACE NORTH	TOPEKA
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER

sumner regional medical center

Based on VSDA2

KS	01/12/2011	02/01/2011	Fire Safety
KS	01/12/2011	02/01/2011	Fire Safety
KS	01/12/2011	02/01/2011	Fire Safety
KS	01/12/2011	02/01/2011	Fire Safety
KS	01/12/2011	01/12/2011	Fire Safety
KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	07/30/2008	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER

sumner regional medical center

Based on VSDA2

KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	07/31/2008	Fire Safety
KS	07/30/2008	08/07/2008	Fire Safety
KS	07/30/2008	08/07/2008	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety

	times.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage	Widespread

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER
17E294	JEFFERSON COUNTY MEM HOSPITAL LTCU	WINCHESTER

sumner regional medical center
Based on VSDA2

KS	10/20/2009	11/20/2009	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety
KS	10/20/2009	11/20/2009	Fire Safety
KS	06/07/2010	06/09/2010	Fire Safety
KS	06/07/2010	06/09/2010	Fire Safety

	of smoke.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER
17E344	FOWLER RESIDENTIAL CARE	FOWLER

sumner regional medical center

Based on VSDA2

KS	07/29/2008	08/26/2008	Fire Safety
KS	07/29/2008	08/26/2008	Fire Safety
KS	07/29/2008	08/26/2008	Fire Safety
KS	07/29/2008	08/26/2008	Fire Safety
KS	07/29/2008	08/26/2008	Fire Safety
KS	09/15/2009	10/14/2009	Fire Safety
KS	09/15/2009	10/14/2009	Fire Safety
KS	09/15/2009	10/14/2009	Fire Safety
KS	09/15/2009	10/14/2009	Fire Safety
KS	08/16/2010	08/26/2010	Fire Safety

	at least 1 1/2 hours.	
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA

sumner regional medical center

Based on VSDA2

KS	07/31/2008	08/30/2008	Fire Safety
KS	07/31/2008	08/30/2008	Fire Safety
KS	07/31/2008	08/30/2008	Fire Safety
KS	07/31/2008	08/30/2008	Fire Safety
KS	07/31/2008	08/30/2008	Fire Safety
KS	07/31/2008	08/30/2008	Fire Safety
KS	07/31/2008	08/30/2008	Fire Safety
KS	07/31/2008	08/30/2008	Fire Safety
KS	07/31/2008	08/30/2008	Fire Safety
KS	07/31/2008	08/30/2008	Fire Safety

	conditions.	
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA

sumner regional medical center

Based on VSDA2

KS	07/22/2009	08/21/2009	Fire Safety
KS	07/22/2009	08/21/2009	Fire Safety
KS	07/22/2009	08/21/2009	Fire Safety
KS	07/22/2009	08/21/2009	Fire Safety
KS	07/22/2009	08/21/2009	Fire Safety
KS	07/22/2009	08/21/2009	Fire Safety
KS	07/22/2009	08/01/2009	Fire Safety
KS	04/20/2010	05/14/2010	Fire Safety
KS	04/20/2010	05/05/2010	Fire Safety

	and equipment.	
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E356	SATANTA DISTRICT HOSPITAL LTCU	SATANTA
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON

sumner regional medical center

Based on VSDA2

KS	04/20/2010	05/15/2010	Fire Safety
KS	04/20/2010	05/19/2010	Fire Safety
KS	04/20/2010	05/05/2010	Fire Safety
KS	04/20/2010	04/27/2010	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/08/2008	Fire Safety
KS	02/08/2008	02/08/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON

sumner regional medical center

Based on VSDA2

KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	02/08/2008	Fire Safety
KS	02/08/2008	02/08/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety

	extinguishing system.	
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON

sumner regional medical center

Based on VSDA2

KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	02/08/2008	03/09/2008	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety

	administration areas.	
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Hazardous Area Deficiencies	properly installed hallway dispensers for alcohol-based hand rub.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON

KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	04/08/2009	05/08/2009	Fire Safety
KS	06/09/2010	07/07/2010	Fire Safety
KS	06/09/2010	07/07/2010	Fire Safety
KS	06/09/2010	07/07/2010	Fire Safety
KS	06/09/2010	07/07/2010	Fire Safety
KS	06/09/2010	07/07/2010	Fire Safety
KS	06/09/2010	07/07/2010	Fire Safety

	conditions.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Building Service Equipment Deficiencies	heating and ventilation systems	Isolated

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E358	TRI-COUNTY MANOR LIVING CENTER INC	HORTON
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS

sumner regional medical center

Based on VSDA2

KS	06/09/2010	07/07/2010	Fire Safety
KS	06/09/2010	07/07/2010	Fire Safety
KS	05/28/2008	06/26/2008	Fire Safety
KS	05/28/2008	06/02/2008	Fire Safety
KS	05/28/2008	06/25/2008	Fire Safety
KS	05/28/2008	06/25/2008	Fire Safety
KS	05/28/2008	06/25/2008	Fire Safety
KS	05/28/2008	06/02/2008	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	08/20/2009	Fire Safety

	that have been properly installed according to the manufacturer's instructions.	
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E384	OTTAWA COUNTY HEALTH CENTER LTCU	MINNEAPOLIS
17E422	LANE COUNTY HOSPITAL LTCU	DIGHTON
17E422	LANE COUNTY HOSPITAL LTCU	DIGHTON

sumner regional medical center

Based on VSDA2

KS	07/22/2009	08/20/2009	Fire Safety
KS	07/22/2009	07/23/2009	Fire Safety
KS	09/15/2010	10/15/2010	Fire Safety
KS	09/15/2010	10/15/2010	Fire Safety
KS	09/15/2010	09/15/2010	Fire Safety
KS	09/15/2010	10/15/2010	Fire Safety
KS	09/15/2010	10/15/2010	Fire Safety
KS	09/15/2010	10/15/2010	Fire Safety
KS	09/15/2010	09/15/2010	Fire Safety
KS	09/16/2008	10/16/2008	Fire Safety
KS	09/16/2008	10/16/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Interior Finish Deficiencies	fire-resistant interior walls.	Isolated
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E422	LANE COUNTY HOSPITAL LTCU	DIGHTON
17E422	LANE COUNTY HOSPITAL LTCU	DIGHTON
17E422	LANE COUNTY HOSPITAL LTCU	DIGHTON
17E422	LANE COUNTY HOSPITAL LTCU	DIGHTON
17E422	LANE COUNTY HOSPITAL LTCU	DIGHTON
17E422	LANE COUNTY HOSPITAL LTCU	DIGHTON
17E422	LANE COUNTY HOSPITAL LTCU	DIGHTON
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE

sumner regional medical center

Based on VSDA2

KS	09/16/2008	10/16/2008	Fire Safety
KS	09/16/2008	10/16/2008	Fire Safety
KS	09/16/2008	10/16/2008	Fire Safety
KS	10/07/2009	10/30/2009	Fire Safety
KS	10/07/2009	10/28/2009	Fire Safety
KS	10/07/2009	10/30/2009	Fire Safety
KS	10/07/2009	10/30/2009	Fire Safety
KS	05/29/2008	06/06/2008	Fire Safety
KS	05/29/2008	06/06/2008	Fire Safety
KS	05/29/2008	06/20/2008	Fire Safety

	at least 1 1/2 hours.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE

sumner regional medical center

Based on VSDA2

KS	05/29/2008	06/20/2008	Fire Safety
KS	05/29/2008	06/06/2008	Fire Safety
KS	05/29/2008	06/26/2008	Fire Safety
KS	05/29/2008	06/26/2008	Fire Safety
KS	05/29/2008	06/06/2008	Fire Safety
KS	04/15/2009	05/10/2009	Fire Safety
KS	04/15/2009	05/10/2009	Fire Safety
KS	04/15/2009	05/10/2009	Fire Safety
KS	04/15/2009	05/10/2009	Fire Safety
KS	04/15/2009	05/10/2009	Fire Safety

	would resist fire for at least one hour.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Exits and Egress Deficiencies	corridors or aisles that are unobstructed and are at least 8 feet in width.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E424	SHERIDAN COUNTY HOSPITAL LTCU	HOXIE
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG

sumner regional medical center

Based on VSDA2

KS	04/15/2009	05/10/2009	Fire Safety
KS	04/15/2009	05/10/2009	Fire Safety
KS	04/15/2009	05/10/2009	Fire Safety
KS	04/26/2010	04/28/2010	Fire Safety
KS	04/26/2010	04/26/2010	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Pattern
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG

sumner regional medical center

Based on VSDA2

KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety

	extinguishing system.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Exits and Egress Deficiencies	two separate exits in rooms of more than 1000 square feet.	Widespread
Automatic Sprinkler Systems Deficiencies	properly working alarms on sprinkler valves.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Smoke Compartmentation and Control Deficiencies	proper construction of ducts through walls designed to prevent smoke passage.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E432	PHILLIPS COUNTY RETIREMENT CENTER	PHILLIPSBURG
17E445	STANTON COUNTY HEALTH CARE FACILITY LTCU	JOHNSON
17E445	STANTON COUNTY HEALTH CARE FACILITY LTCU	JOHNSON
17E445	STANTON COUNTY HEALTH CARE FACILITY LTCU	JOHNSON
17E445	STANTON COUNTY HEALTH CARE FACILITY LTCU	JOHNSON

sumner regional medical center

Based on VSDA2

KS	07/16/2008	08/13/2008	Fire Safety
KS	07/16/2008	08/13/2008	Fire Safety
KS	07/29/2009	08/31/2009	Fire Safety
KS	07/29/2009	08/25/2009	Fire Safety
KS	07/29/2009	08/08/2009	Fire Safety
KS	07/29/2009	08/05/2009	Fire Safety
KS	07/07/2010	07/08/2010	Fire Safety
KS	04/28/2009	05/04/2009	Fire Safety
KS	04/28/2009	04/30/2009	Fire Safety
KS	04/28/2009	04/29/2009	Fire Safety
KS	04/28/2009	04/29/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Laboratories Deficiencies	emergency showers.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E445	STANTON COUNTY HEALTH CARE FACILITY LTCU	JOHNSON
17E445	STANTON COUNTY HEALTH CARE FACILITY LTCU	JOHNSON
17E445	STANTON COUNTY HEALTH CARE FACILITY LTCU	JOHNSON
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY

KS	06/03/2010	06/25/2010	Fire Safety
KS	06/03/2010	06/25/2010	Fire Safety
KS	06/03/2010	06/25/2010	Fire Safety
KS	01/30/2008	02/25/2008	Fire Safety
KS	01/30/2008	02/25/2008	Fire Safety
KS	01/30/2008	02/25/2008	Fire Safety
KS	01/30/2008	02/25/2008	Fire Safety
KS	01/30/2008	02/25/2008	Fire Safety
KS	01/30/2008	02/25/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Widespread
Interior Finish Deficiencies	fire-resistant interior walls.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY

KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	12/03/2008	12/30/2008	Fire Safety
KS	11/30/2009	12/21/2009	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Exits and Egress Deficiencies	corridors or aisles that are unobstructed and are at least 8 feet in width.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Isolated

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E451	DAWSON PLACE	HILL CITY
17E451	DAWSON PLACE	HILL CITY
17E458	MOUNDRIDGE MANOR	MOUNDRIDGE
17E458	MOUNDRIDGE MANOR	MOUNDRIDGE
17E458	MOUNDRIDGE MANOR	MOUNDRIDGE
17E458	MOUNDRIDGE MANOR	MOUNDRIDGE
17E458	MOUNDRIDGE MANOR	MOUNDRIDGE
17E458	MOUNDRIDGE MANOR	MOUNDRIDGE
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON

sumner regional medical center

Based on VSDA2

KS	11/30/2009	12/21/2009	Fire Safety
KS	11/30/2009	12/21/2009	Fire Safety
KS	09/03/2008	09/08/2008	Fire Safety
KS	09/03/2008	09/08/2008	Fire Safety
KS	09/03/2008	09/08/2008	Fire Safety
KS	09/03/2008	09/05/2008	Fire Safety
KS	09/03/2008	09/09/2008	Fire Safety
KS	11/23/2010	11/26/2010	Fire Safety
KS	03/04/2008	04/03/2008	Fire Safety
KS	03/04/2008	04/03/2008	Fire Safety

	at least 1 1/2 hours.	
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON

sumner regional medical center

Based on VSDA2

KS	03/04/2008	04/03/2008	Fire Safety
KS	03/04/2008	04/03/2008	Fire Safety
KS	03/04/2008	04/03/2008	Fire Safety
KS	03/04/2008	04/03/2008	Fire Safety
KS	03/04/2008	04/03/2008	Fire Safety
KS	03/16/2009	04/16/2009	Fire Safety
KS	03/16/2009	03/20/2009	Fire Safety
KS	03/16/2009	04/16/2009	Fire Safety
KS	03/16/2009	03/20/2009	Fire Safety
KS	03/16/2009	03/20/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Pattern

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON

KS	03/16/2009	03/16/2009	Fire Safety
KS	03/16/2009	03/20/2009	Fire Safety
KS	03/16/2009	03/20/2009	Fire Safety
KS	03/16/2009	04/16/2009	Fire Safety
KS	03/16/2009	03/17/2009	Fire Safety
KS	03/15/2010	04/14/2010	Fire Safety
KS	03/15/2010	03/15/2010	Fire Safety
KS	03/15/2010	03/15/2010	Fire Safety

	each shift under varying conditions.	
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Vertical Openings Deficiencies	exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E465	COMMUNITY CARE INC	CLIFTON
17E465	COMMUNITY CARE INC	CLIFTON
17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA
17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA
17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA
17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA
17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA
17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA
17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA
17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA
17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA

sumner regional medical center

Based on VSDA2

KS	03/15/2010	04/14/2010	Fire Safety
KS	03/15/2010	03/24/2010	Fire Safety
KS	11/20/2007	12/20/2007	Fire Safety
KS	11/20/2007	11/28/2007	Fire Safety
KS	11/20/2007	11/28/2007	Fire Safety
KS	01/22/2009	01/29/2009	Fire Safety
KS	01/22/2009	01/29/2009	Fire Safety
KS	01/11/2010	02/12/2010	Fire Safety
KS	01/11/2010	02/08/2010	Fire Safety
KS	01/11/2010	01/14/2010	Fire Safety
KS	01/11/2010	02/12/2010	Fire Safety

	extinguishing system.	
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	did not have a written emergency evacuation plan.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

17E470	MINNEOLA DISTRICT HOSPITAL LTCU	MINNEOLA
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY

sumner regional medical center

Based on VSDA2

KS	01/11/2010	01/11/2010	Fire Safety
KS	10/09/2007	10/10/2007	Fire Safety
KS	10/09/2007	10/09/2007	Fire Safety
KS	10/09/2007	11/11/2007	Fire Safety
KS	10/09/2007	10/15/2007	Fire Safety
KS	10/09/2007	10/15/2007	Fire Safety
KS	10/09/2007	10/15/2007	Fire Safety
KS	11/05/2008	11/11/2008	Fire Safety
KS	11/05/2008	11/19/2008	Fire Safety
KS	11/05/2008	11/17/2008	Fire Safety

	have been maintained in working order.	
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E473	COFFEY COUNTY HOSPITAL LTCU	WAVERLY
17E488	THE SHEPHERD'S CENTER	CIMARRON
17E488	THE SHEPHERD'S CENTER	CIMARRON
17E488	THE SHEPHERD'S CENTER	CIMARRON
17E488	THE SHEPHERD'S CENTER	CIMARRON
17E488	THE SHEPHERD'S CENTER	CIMARRON
17E488	THE SHEPHERD'S CENTER	CIMARRON
17E488	THE SHEPHERD'S CENTER	CIMARRON
17E488	THE SHEPHERD'S CENTER	CIMARRON
17E488	THE SHEPHERD'S CENTER	CIMARRON

sumner regional medical center

Based on VSDA2

KS	11/05/2008	11/05/2008	Fire Safety
KS	11/18/2009	12/10/2009	Fire Safety
KS	03/11/2008	04/10/2008	Fire Safety
KS	03/11/2008	04/10/2008	Fire Safety
KS	03/11/2008	04/10/2008	Fire Safety
KS	03/11/2008	04/10/2008	Fire Safety
KS	03/11/2008	04/10/2008	Fire Safety
KS	06/08/2010	07/08/2010	Fire Safety
KS	06/08/2010	07/07/2010	Fire Safety
KS	06/08/2010	06/23/2010	Fire Safety
KS	06/08/2010	07/08/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E488	THE SHEPHERD'S CENTER	CIMARRON
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND

sumner regional medical center

Based on VSDA2

KS	06/08/2010	07/08/2010	Fire Safety
KS	12/11/2008	12/18/2008	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety

	obstructions and can be used at all times.	
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND

sumner regional medical center

Based on VSDA2

KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/16/2009	01/14/2010	Fire Safety
KS	12/16/2009	01/14/2010	Fire Safety
KS	12/16/2009	01/14/2010	Fire Safety
KS	12/16/2009	01/14/2010	Fire Safety
KS	12/16/2009	01/14/2010	Fire Safety
KS	12/16/2009	01/14/2010	Fire Safety
KS	01/24/2011	01/24/2011	Fire Safety

	conditions.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E499	CHERRY VILLAGE	GREAT BEND
17E499	CHERRY VILLAGE	GREAT BEND
17E507	DEXTER CARE CENTER	DEXTER
17E507	DEXTER CARE CENTER	DEXTER
17E507	DEXTER CARE CENTER	DEXTER
17E507	DEXTER CARE CENTER	DEXTER
17E507	DEXTER CARE CENTER	DEXTER
17E507	DEXTER CARE CENTER	DEXTER
17E507	DEXTER CARE CENTER	DEXTER
17E507	DEXTER CARE CENTER	DEXTER

sumner regional medical center

Based on VSDA2

KS	01/24/2011	01/24/2011	Fire Safety
KS	01/24/2011	01/31/2011	Fire Safety
KS	10/03/2008	10/06/2008	Fire Safety
KS	10/03/2008	10/25/2008	Fire Safety
KS	10/03/2008	10/06/2008	Fire Safety
KS	10/03/2008	10/03/2008	Fire Safety
KS	10/03/2008	10/06/2008	Fire Safety
KS	10/03/2008	10/03/2008	Fire Safety
KS	12/03/2009	01/02/2010	Fire Safety

	at least 1 1/2 hours.	
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E507	DEXTER CARE CENTER	DEXTER
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART

sumner regional medical center

Based on VSDA2

KS	12/21/2010	01/19/2011	Fire Safety
KS	01/30/2008	02/28/2008	Fire Safety
KS	01/30/2008	02/28/2008	Fire Safety
KS	01/30/2008	01/30/2008	Fire Safety
KS	01/30/2008	01/31/2008	Fire Safety
KS	12/10/2008	12/15/2008	Fire Safety
KS	12/10/2008	12/15/2008	Fire Safety
KS	12/10/2008	01/09/2009	Fire Safety

	have been maintained in working order.	
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E522	MORTON COUNTY HOSPITAL LTCU	ELKHART
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA

KS	12/10/2008	12/10/2008	Fire Safety
KS	01/25/2010	01/25/2010	Fire Safety
KS	01/25/2010	01/25/2010	Fire Safety
KS	01/25/2010	01/25/2010	Fire Safety
KS	01/25/2010	01/25/2010	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	06/30/2008	Fire Safety
KS	04/23/2008	06/28/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Widespread
Interior Finish Deficiencies	fire-resistant interior walls.	Widespread
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA

KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety

	block smoke.	
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/23/2008	05/23/2008	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Building Service Equipment Deficiencies	restrictions on the use of portable space heaters.	Isolated
Furnishings and Decorations Deficiencies	restrictions on the use of highly flammable materials.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Widespread
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Widespread
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA

sumner regional medical center

Based on VSDA2

KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	04/03/2009	05/03/2009	Fire Safety
KS	07/20/2010	08/19/2010	Fire Safety
KS	07/20/2010	08/19/2010	Fire Safety
KS	07/20/2010	08/19/2010	Fire Safety
KS	07/20/2010	08/19/2010	Fire Safety
KS	07/20/2010	08/19/2010	Fire Safety
KS	07/20/2010	08/19/2010	Fire Safety
KS	07/20/2010	08/19/2010	Fire Safety

	conditions.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E528	COUNTRYSIDE HEALTH CENTER	TOPEKA
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN

sumner regional medical center

Based on VSDA2

KS	07/20/2010	08/19/2010	Fire Safety
KS	05/14/2008	06/10/2008	Fire Safety
KS	05/14/2008	05/20/2008	Fire Safety
KS	05/14/2008	06/10/2008	Fire Safety
KS	05/14/2008	06/01/2008	Fire Safety
KS	05/14/2008	06/10/2008	Fire Safety
KS	05/14/2008	05/30/2008	Fire Safety
KS	05/14/2008	06/03/2008	Fire Safety
KS	04/22/2009	05/21/2009	Fire Safety
KS	04/22/2009	05/08/2009	Fire Safety
KS	04/22/2009	05/04/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E531	KEARNY COUNTY HOSPITAL LTCU	LAKIN
17E534	ATTICA LONG TERM CARE FACILITY	ATTICA
17E534	ATTICA LONG TERM CARE FACILITY	ATTICA
17E534	ATTICA LONG TERM CARE FACILITY	ATTICA
17E534	ATTICA LONG TERM CARE FACILITY	ATTICA

sumner regional medical center

Based on VSDA2

KS	04/22/2009	04/24/2009	Fire Safety
KS	04/22/2009	04/29/2009	Fire Safety
KS	04/22/2009	04/22/2009	Fire Safety
KS	05/03/2010	05/28/2010	Fire Safety
KS	05/03/2010	05/03/2010	Fire Safety
KS	07/03/2008	07/11/2008	Fire Safety
KS	07/03/2008	07/03/2008	Fire Safety
KS	07/03/2008	07/08/2008	Fire Safety
KS	07/03/2008	07/07/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E534	ATTICA LONG TERM CARE FACILITY	ATTICA
17E534	ATTICA LONG TERM CARE FACILITY	ATTICA
17E534	ATTICA LONG TERM CARE FACILITY	ATTICA
17E534	ATTICA LONG TERM CARE FACILITY	ATTICA
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON

sumner regional medical center

Based on VSDA2

KS	07/03/2008	07/17/2008	Fire Safety
KS	07/03/2008	07/09/2008	Fire Safety
KS	06/30/2009	07/06/2009	Fire Safety
KS	07/15/2010	08/11/2010	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety

	maintenance and testing program for fire alarm systems.	
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON

sumner regional medical center

Based on VSDA2

KS	04/30/2008	05/30/2008	Fire Safety
KS	04/30/2008	05/30/2008	Fire Safety
KS	01/05/2009	01/05/2009	Fire Safety
KS	01/05/2009	01/12/2009	Fire Safety
KS	01/05/2009	01/12/2009	Fire Safety
KS	01/05/2009	02/04/2009	Fire Safety
KS	01/05/2009	02/04/2009	Fire Safety
KS	01/05/2009	02/04/2009	Fire Safety
KS	02/15/2010	03/17/2010	Fire Safety
KS	02/15/2010	03/17/2010	Fire Safety

	areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at	Pattern

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E546	STEVENS COUNTY HOSPITAL LTCU	HUGOTON
17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN
17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN
17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN
17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN
17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN
17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN
17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN
17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN

sumner regional medical center

Based on VSDA2

KS	02/15/2010	03/17/2010	Fire Safety
KS	02/15/2010	03/17/2010	Fire Safety
KS	02/15/2010	03/17/2010	Fire Safety
KS	10/10/2007	11/09/2007	Fire Safety
KS	10/10/2007	11/09/2007	Fire Safety
KS	10/10/2007	11/09/2007	Fire Safety
KS	10/10/2007	11/09/2007	Fire Safety
KS	12/10/2008	12/10/2008	Fire Safety
KS	12/10/2008	12/10/2008	Fire Safety
KS	12/10/2008	12/16/2008	Fire Safety

	all times.	
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN
17E555	THE WHEATLANDS HEALTH CARE CENTER	KINGMAN
17E577	ANDERSON COUNTY HOSPITAL LTCU	GARNETT
17E577	ANDERSON COUNTY HOSPITAL LTCU	GARNETT
17E577	ANDERSON COUNTY HOSPITAL LTCU	GARNETT
17E577	ANDERSON COUNTY HOSPITAL LTCU	GARNETT
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER

sumner regional medical center

Based on VSDA2

KS	12/10/2008	12/10/2008	Fire Safety
KS	12/10/2008	12/10/2008	Fire Safety
KS	09/17/2008	09/22/2008	Fire Safety
KS	10/07/2009	10/27/2009	Fire Safety
KS	10/07/2009	10/27/2009	Fire Safety
KS	10/07/2009	10/27/2009	Fire Safety
KS	06/12/2008	06/20/2008	Fire Safety
KS	06/12/2008	06/20/2008	Fire Safety
KS	06/12/2008	07/11/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Laboratories Deficiencies	emergency showers.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Widespread
Corridor Walls and Doors Deficiencies	corridors that are separated from common areas by walls constructed to limit the passage of smoke.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER

KS	06/12/2008	06/22/2008	Fire Safety
KS	06/12/2008	06/20/2008	Fire Safety
KS	06/12/2008	07/11/2008	Fire Safety
KS	06/12/2008	07/11/2008	Fire Safety
KS	06/12/2008	07/11/2008	Fire Safety
KS	06/12/2008	07/11/2008	Fire Safety
KS	08/25/2009	09/02/2009	Fire Safety
KS	08/25/2009	09/25/2009	Fire Safety
KS	08/25/2009	09/02/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Building Service Equipment Deficiencies	properly constructed linen or trash chutes.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Service Equipment Deficiencies	heating and ventilation systems that have been properly installed according to the manufacturer's	Isolated

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E580	PIONEER LODGE	COLDWATER
17E581	LEISURE HOMESTEAD AT STAFFORD	STAFFORD
17E581	LEISURE HOMESTEAD AT STAFFORD	STAFFORD
17E581	LEISURE HOMESTEAD AT STAFFORD	STAFFORD
17E581	LEISURE HOMESTEAD AT STAFFORD	STAFFORD
17E581	LEISURE HOMESTEAD AT STAFFORD	STAFFORD

sumner regional medical center

Based on VSDA2

KS	08/25/2009	09/25/2009	Fire Safety
KS	08/12/2010	09/11/2010	Fire Safety
KS	08/12/2010	09/11/2010	Fire Safety
KS	10/22/2008	10/25/2008	Fire Safety
KS	10/22/2008	10/31/2008	Fire Safety
KS	10/13/2009	10/13/2009	Fire Safety
KS	10/13/2009	11/10/2009	Fire Safety
KS	10/13/2009	10/14/2009	Fire Safety

	according to the manufacturer's instructions.	
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E581	LEISURE HOMESTEAD AT STAFFORD	STAFFORD
17E581	LEISURE HOMESTEAD AT STAFFORD	STAFFORD
17E581	LEISURE HOMESTEAD AT STAFFORD	STAFFORD
17E581	LEISURE HOMESTEAD AT STAFFORD	STAFFORD
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON

sumner regional medical center

Based on VSDA2

KS	10/13/2009	11/10/2009	Fire Safety
KS	10/13/2009	10/14/2009	Fire Safety
KS	10/18/2010	10/18/2010	Fire Safety
KS	10/18/2010	11/12/2010	Fire Safety
KS	02/12/2008	02/13/2008	Fire Safety
KS	02/12/2008	02/19/2008	Fire Safety
KS	02/12/2008	02/13/2008	Fire Safety
KS	02/12/2008	02/22/2008	Fire Safety
KS	02/12/2008	02/15/2008	Fire Safety
KS	02/12/2008	02/13/2008	Fire Safety
KS	04/09/2009	04/09/2009	Fire Safety

Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Pattern
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E585	DOOLEY CENTER	ATCHISON
17E589	CUMBERNAULD VILLAGE	WINFIELD

sumner regional medical center

Based on VSDA2

KS	04/09/2009	04/09/2009	Fire Safety
KS	04/09/2009	04/09/2009	Fire Safety
KS	04/09/2009	04/17/2009	Fire Safety
KS	04/09/2009	04/10/2009	Fire Safety
KS	05/11/2010	06/10/2010	Fire Safety
KS	05/11/2010	05/11/2010	Fire Safety
KS	05/11/2010	06/10/2010	Fire Safety
KS	05/11/2010	06/10/2010	Fire Safety
KS	02/20/2008	02/25/2008	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Widespread
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E589	CUMBERNAULD VILLAGE	WINFIELD
17E589	CUMBERNAULD VILLAGE	WINFIELD
17E589	CUMBERNAULD VILLAGE	WINFIELD
17E589	CUMBERNAULD VILLAGE	WINFIELD
17E589	CUMBERNAULD VILLAGE	WINFIELD
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS

sumner regional medical center

Based on VSDA2

KS	02/20/2008	02/25/2008	Fire Safety
KS	02/20/2008	02/25/2008	Fire Safety
KS	02/03/2009	02/14/2009	Fire Safety
KS	02/03/2009	02/04/2009	Fire Safety
KS	02/03/2009	02/04/2009	Fire Safety
KS	06/12/2008	06/12/2008	Fire Safety
KS	06/12/2008	06/12/2008	Fire Safety
KS	06/12/2008	06/17/2008	Fire Safety
KS	06/12/2008	06/17/2008	Fire Safety
KS	06/12/2008	06/17/2008	Fire Safety

Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS

sumner regional medical center

Based on VSDA2

KS	06/12/2008	06/17/2008	Fire Safety
KS	06/12/2008	07/12/2008	Fire Safety
KS	06/12/2008	06/17/2008	Fire Safety
KS	06/12/2008	06/12/2008	Fire Safety
KS	06/12/2008	06/12/2008	Fire Safety
KS	09/22/2009	10/05/2009	Fire Safety
KS	09/22/2009	10/05/2009	Fire Safety
KS	09/22/2009	10/05/2009	Fire Safety
KS	09/22/2009	10/05/2009	Fire Safety
KS	09/22/2009	10/05/2009	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Automatic Sprinkler Systems Deficiencies	back-up procedures in place for a faulty automatic sprinkler system.	Pattern
Fire Alarm Systems Deficiencies	an approved back-up procedure for a faulty fire alarm system.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E591	VALLEY HEALTH CARE CENTER	VALLEY FALLS
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA

sumner regional medical center

Based on VSDA2

KS	10/18/2010	11/12/2010	Fire Safety
KS	10/18/2010	11/12/2010	Fire Safety
KS	10/18/2010	11/15/2010	Fire Safety
KS	10/18/2010	11/10/2010	Fire Safety
KS	10/18/2010	11/10/2010	Fire Safety
KS	10/18/2010	11/10/2010	Fire Safety
KS	10/18/2010	11/10/2010	Fire Safety
KS	01/10/2008	02/09/2008	Fire Safety
KS	01/10/2008	01/10/2008	Fire Safety
KS	01/10/2008	02/09/2008	Fire Safety
KS	01/10/2008	01/10/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Laboratories Deficiencies	emergency showers.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA

sumner regional medical center

Based on VSDA2

KS	01/10/2008	02/09/2008	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Interior Finish Deficiencies	fire-resistant room wall surfaces.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E596	BRIGHTON PLACE WEST	TOPEKA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA

sumner regional medical center

Based on VSDA2

KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	07/09/2010	08/08/2010	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA

sumner regional medical center

Based on VSDA2

KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	11/28/2007	12/27/2007	Fire Safety
KS	12/09/2008	12/22/2008	Fire Safety
KS	12/09/2008	12/22/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Interior Finish Deficiencies	fire-resistant interior walls.	Pattern

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E597	KIOWA HOSPITAL DISTRICT MANOR	KIOWA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	12/09/2008	12/22/2008	Fire Safety
KS	12/09/2008	12/22/2008	Fire Safety
KS	12/09/2008	12/22/2008	Fire Safety
KS	12/09/2008	12/22/2008	Fire Safety
KS	12/09/2008	12/22/2008	Fire Safety
KS	12/01/2009	12/10/2009	Fire Safety
KS	12/01/2009	12/10/2009	Fire Safety
KS	12/01/2009	12/10/2009	Fire Safety
KS	12/01/2009	12/10/2009	Fire Safety
KS	04/04/2008	05/01/2008	Fire Safety
KS	04/04/2008	05/01/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Building Construction Deficiencies	approved construction type or materials.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	04/04/2008	05/01/2008	Fire Safety
KS	04/04/2008	05/01/2008	Fire Safety
KS	04/04/2008	05/01/2008	Fire Safety
KS	04/04/2008	05/01/2008	Fire Safety
KS	04/04/2008	05/01/2008	Fire Safety
KS	04/04/2008	05/01/2008	Fire Safety
KS	04/04/2008	05/01/2008	Fire Safety
KS	04/04/2008	05/01/2008	Fire Safety
KS	05/11/2009	06/09/2009	Fire Safety
KS	05/11/2009	06/09/2009	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Furnishings and Decorations Deficiencies	properly sized and located linen or trash receptacles.	Isolated
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Widespread

sumner regional medical center

Based on VSDA2

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	05/11/2009	06/09/2009	Fire Safety
KS	05/11/2009	06/09/2009	Fire Safety
KS	05/11/2009	06/09/2009	Fire Safety
KS	05/11/2009	06/09/2009	Fire Safety
KS	05/13/2010	06/01/2010	Fire Safety
KS	05/13/2010	05/21/2010	Fire Safety
KS	05/13/2010	05/17/2010	Fire Safety
KS	05/13/2010	05/17/2010	Fire Safety
KS	05/13/2010	05/17/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Corridor Walls and Doors Deficiencies	signs that state that exit doors are to be kept closed.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Widespread

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E599	WICHITA NURSING CENTER	WICHITA
17E607	LEISURE HOMESTEAD AT ST JOHN	ST JOHN
17E607	LEISURE HOMESTEAD AT ST JOHN	ST JOHN
17E607	LEISURE HOMESTEAD AT ST JOHN	ST JOHN
17E607	LEISURE HOMESTEAD AT ST JOHN	ST JOHN
17E607	LEISURE HOMESTEAD AT ST JOHN	ST JOHN
17E607	LEISURE HOMESTEAD AT ST JOHN	ST JOHN
17E607	LEISURE HOMESTEAD AT ST JOHN	ST JOHN

sumner regional medical center

Based on VSDA2

KS	05/13/2010	06/13/2010	Fire Safety
KS	05/13/2010	05/19/2010	Fire Safety
KS	05/13/2010	05/13/2010	Fire Safety
KS	03/18/2009	03/25/2009	Fire Safety
KS	03/18/2009	03/25/2009	Fire Safety
KS	03/18/2009	03/25/2009	Fire Safety
KS	03/18/2009	03/18/2009	Fire Safety
KS	03/18/2009	03/18/2009	Fire Safety
KS	02/11/2010	02/11/2010	Fire Safety
KS	03/14/2011	03/16/2011	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

17E607	LEISURE HOMESTEAD AT ST JOHN	ST JOHN
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY

sumner regional medical center

Based on VSDA2

KS	03/14/2011	04/01/2011	Fire Safety
KS	03/12/2008	03/17/2008	Fire Safety
KS	03/12/2008	03/14/2008	Fire Safety
KS	03/12/2008	03/17/2008	Fire Safety
KS	03/12/2008	03/14/2008	Fire Safety
KS	03/12/2008	03/13/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety

	hour.	
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Isolated

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY

sumner regional medical center

Based on VSDA2

KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	04/10/2008	Fire Safety
KS	03/12/2008	03/14/2008	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety

	alarm system.	
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Isolated
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Widespread
Building Service Equipment Deficiencies	properly protected cooking facilities.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY
17E611	CANEY NURSING CENTER	CANEY

sumner regional medical center

Based on VSDA2

KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	01/20/2009	02/18/2009	Fire Safety
KS	03/08/2010	03/11/2010	Fire Safety
KS	03/08/2010	03/08/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY

KS	10/02/2007	10/02/2007	Fire Safety
KS	10/02/2007	10/02/2007	Fire Safety
KS	10/02/2007	11/02/2007	Fire Safety
KS	10/02/2007	11/02/2007	Fire Safety
KS	10/02/2007	10/02/2007	Fire Safety
KS	10/02/2007	10/02/2007	Fire Safety
KS	10/09/2008	10/09/2008	Fire Safety
KS	10/09/2008	10/10/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Building Construction Deficiencies	approved construction type or materials.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Pattern
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Isolated
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY

sumner regional medical center

Based on VSDA2

KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	11/07/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Pattern
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Widespread
Automatic Sprinkler Systems Deficiencies	an approved automatic sprinkler system connected to the fire alarm system.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Building Service Equipment Deficiencies	properly protected cooking facilities.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Furnishings and Decorations Deficiencies	restrictions on the use of flammable curtains.	Widespread

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E613	LOGAN COUNTY MANOR - LTCU	OAKLEY
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL

sumner regional medical center

Based on VSDA2

KS	10/09/2008	11/07/2008	Fire Safety
KS	10/09/2008	10/09/2008	Fire Safety
KS	10/09/2008	10/15/2008	Fire Safety
KS	12/03/2009	12/03/2009	Fire Safety
KS	12/01/2008	01/01/2009	Fire Safety
KS	12/01/2008	01/01/2009	Fire Safety
KS	12/01/2008	01/01/2009	Fire Safety
KS	12/01/2008	01/01/2009	Fire Safety
KS	12/01/2008	01/01/2009	Fire Safety
KS	12/01/2008	12/01/2008	Fire Safety
KS	12/01/2008	12/04/2008	Fire Safety

	flammable curtains.	
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Miscellaneous Deficiencies	fire safety features required by current fire safety codes.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Isolated
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	a fire alarm system that can be heard throughout the facility.	Widespread

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E619	RUSSELL REGIONAL HOSPITAL LTCU	RUSSELL
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR	NESS CITY

KS	12/01/2008	01/01/2009	Fire Safety
KS	12/01/2008	12/02/2008	Fire Safety
KS	12/01/2008	12/04/2008	Fire Safety
KS	12/01/2008	01/01/2009	Fire Safety
KS	11/03/2009	12/03/2009	Fire Safety
KS	11/03/2009	12/03/2009	Fire Safety
KS	11/03/2009	11/13/2009	Fire Safety
KS	11/03/2009	12/03/2009	Fire Safety
KS	11/18/2010	11/27/2010	Fire Safety
KS	11/18/2010	12/15/2010	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Vertical Openings Deficiencies	proper stairway enclosures and vertical shafts.	Isolated
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Isolated
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Corridor Walls and Doors Deficiencies	corridor and hallway doors that	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

	VILLAGE	
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E625	NESS COUNTY HOSPITAL LTCU DBA CEDAR VILLAGE	NESS CITY
17E627	HODGEMAN COUNTY HEALTH CENTER LTCU	JETMORE

sumner regional medical center

Based on VSDA2

KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	07/17/2008	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	08/15/2008	Fire Safety
KS	07/17/2008	07/21/2008	Fire Safety
KS	07/15/2009	07/16/2009	Fire Safety
KS	07/15/2009	07/16/2009	Fire Safety
KS	07/12/2010	07/15/2010	Fire Safety
KS	11/10/2008	11/11/2008	Fire Safety

	block smoke.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Pattern
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Electrical Deficiencies	properly installed electrical wiring and equipment.	Pattern
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated

harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E627	HODGEMAN COUNTY HEALTH CENTER LTCU	JETMORE
17E627	HODGEMAN COUNTY HEALTH CENTER LTCU	JETMORE
17E627	HODGEMAN COUNTY HEALTH CENTER LTCU	JETMORE
17E627	HODGEMAN COUNTY HEALTH CENTER LTCU	JETMORE
17E627	HODGEMAN COUNTY HEALTH CENTER LTCU	JETMORE
17E627	HODGEMAN COUNTY HEALTH CENTER LTCU	JETMORE
17E627	HODGEMAN COUNTY HEALTH CENTER LTCU	JETMORE
17E627	HODGEMAN COUNTY HEALTH CENTER LTCU	JETMORE
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	11/10/2008	11/11/2008	Fire Safety
KS	11/10/2008	11/11/2008	Fire Safety
KS	11/10/2008	12/11/2008	Fire Safety
KS	10/06/2009	10/09/2009	Fire Safety
KS	10/06/2009	10/31/2009	Fire Safety
KS	10/06/2009	10/31/2009	Fire Safety
KS	10/20/2010	10/20/2010	Fire Safety
KS	10/20/2010	10/20/2010	Fire Safety
KS	12/18/2007	01/11/2008	Fire Safety

sumner regional medical center

Based on VSDA2

Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Fire Alarm Systems Deficiencies	an approved installation, maintenance and testing program for fire alarm systems.	Pattern
Furnishings and Decorations Deficiencies	exits that are free from obstructions and can be used at all times.	Isolated
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Widespread
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated
Exits and Egress Deficiencies	exit stairways and towers that are smoke proof.	Pattern

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA
17E629	VIA CHRISTI HOPE HEALTH CENTER	WICHITA

sumner regional medical center

Based on VSDA2

KS	12/18/2007	01/16/2008	Fire Safety
KS	12/18/2007	01/16/2008	Fire Safety
KS	12/18/2007	01/16/2008	Fire Safety
KS	12/18/2007	12/31/2007	Fire Safety
KS	12/18/2007	01/04/2008	Fire Safety
KS	12/18/2007	01/11/2008	Fire Safety
KS	12/18/2007	01/04/2008	Fire Safety
KS	12/11/2008	12/12/2008	Fire Safety
KS	12/11/2008	12/12/2008	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	12/11/2008	01/09/2009	Fire Safety
KS	02/11/2010	03/01/2010	Fire Safety

sumner regional medical center

Based on VSDA2

Illumination and Emergency Power Deficiencies	proper backup exit lighting.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Laboratories Deficiencies	emergency showers.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Exits and Egress Deficiencies	exits that are accessible at all times.	Widespread
Medical Gases and Anesthetizing Areas Deficiencies	proper medical gas storage and administration areas.	Isolated
Electrical Deficiencies	weekly inspections and monthly testing of generators.	Isolated
Electrical Deficiencies	properly installed electrical wiring and equipment.	Isolated
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire	Isolated

sumner regional medical center

Based on VSDA2

Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm
Minimal harm or potential for actual harm

sumner regional medical center

Based on VSDA2

17E630	ANTHONY COMMUNITY CARE CENTER	ANTHONY
17E630	ANTHONY COMMUNITY CARE CENTER	ANTHONY
17E630	ANTHONY COMMUNITY CARE CENTER	ANTHONY
17E630	ANTHONY COMMUNITY CARE CENTER	ANTHONY
17E630	ANTHONY COMMUNITY CARE CENTER	ANTHONY
17E630	ANTHONY COMMUNITY CARE CENTER	ANTHONY
17E630	ANTHONY COMMUNITY CARE CENTER	ANTHONY
17E630	ANTHONY COMMUNITY CARE CENTER	ANTHONY
17E634	IOLA NURSING CENTER	IOLA
17E634	IOLA NURSING CENTER	IOLA
17E634	IOLA NURSING CENTER	IOLA
17E634	IOLA NURSING CENTER	IOLA

sumner regional medical center

Based on VSDA2

KS	08/05/2008	08/21/2008	Fire Safety
KS	09/18/2009	09/18/2009	Fire Safety
KS	09/18/2009	09/18/2009	Fire Safety
KS	09/18/2009	09/18/2009	Fire Safety
KS	09/18/2009	09/18/2009	Fire Safety
KS	09/09/2010	09/09/2010	Fire Safety
KS	09/09/2010	09/09/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety

	extinguishing system.	
Hazardous Area Deficiencies	construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Isolated
Illumination and Emergency Power Deficiencies	properly located and lighted "Exit" signs.	Isolated
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Isolated
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Widespread
Automatic Sprinkler Systems Deficiencies	portable fire extinguishers.	Widespread
Building Construction Deficiencies	a two-hour-resistant firewall in common walls.	Pattern
Building Construction Deficiencies	approved construction type or materials.	Pattern
Corridor Walls and Doors Deficiencies	corridor and hallway doors that block smoke.	Pattern
Smoke Compartmentation and Control Deficiencies	walls or barriers that prevent	Pattern

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual

sumner regional medical center

Based on VSDA2

17E634	IOLA NURSING CENTER	IOLA
17E634	IOLA NURSING CENTER	IOLA
17E634	IOLA NURSING CENTER	IOLA
17E634	IOLA NURSING CENTER	IOLA
17E634	IOLA NURSING CENTER	IOLA
17E634	IOLA NURSING CENTER	IOLA

sumner regional medical center

Based on VSDA2

KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	02/05/2010	Fire Safety
KS	01/22/2010	01/22/2010	Fire Safety
KS	01/22/2010	01/25/2010	Fire Safety

	smoke from passing through and would resist fire for at least one hour.	
Exits and Egress Deficiencies	exits that are accessible at all times.	Pattern
Illumination and Emergency Power Deficiencies	emergency lighting that can last at least 1 1/2 hours.	Pattern
Emergency Plans and Fire Drills Deficiencies	record of quarterly fire drills for each shift under varying conditions.	Widespread
Fire Alarm Systems Deficiencies	properly maintained smoke detectors.	Widespread
Automatic Sprinkler Systems Deficiencies	automatic sprinkler systems that have been maintained in working order.	Pattern
Smoking Regulations Deficiencies	posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern

harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm

Minimal harm or potential for actual harm